

New Jersey Police Crash Investigation Report												Case Number 2017-00070801			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Both vehicles were waiting to merge in traffic onto Route 70 West from the Eastbound Route 88 off ramp. The front end of Vehicle #1 collided with the rear end of Vehicle #2, causing moderate damage to both vehicles.

Driver #1 advised that Vehicle #2 was at the end of the ramp and appeared as if he were about to merge in traffic so he began to accelerate while looking back to his left at the oncoming traffic. Driver #1 further advised that he did not realize that Vehicle #2 was stopped until the collision happened because he was looking to the rear at the oncoming traffic. Driver #2 advised that he initially began to accelerate but another vehicle suddenly crossed over the intersection coming from the other side of Route 70 in the lane that he was attempting to merge into. Driver #2 further advised that he reapplied his brakes to yield to that vehicle when he was suddenly struck in the rear by Vehicle #1.

Based upon my observations, and statements made by both drivers, I find Driver #1 at fault for failing to yield to oncoming traffic.

146. Officer's Signature Michael V Bennett II	147. Badge # 279	148. Reviewer Joseph Forrester	Badge # 202	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police

Code: 01

Station:


Case No: 2017-00070801

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



NOT TO SCALE



Michael V Bennett II

Officer's Signature

279

Badge Number