

New Jersey Police Crash Investigation Report

Police Dept: _____ Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **Brick Police** Case No: **2015-00074465**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
ALL INVOLVED	83	84	85	86	87	88	89	90	91	92	93	94	95	
	A													
	B													
	C													
	D													
E														

135 Crash Description

Vehicle #1 was traveling south through the construction coned right lane on Jack Martin Blvd. Vehicle #2 was also traveling south on Jack Martin Blvd but in the left coned lane. Soon after the two coned lanes merged into one, Vehicle #1 attempted a left U Turn in front of Vehicle #2, causing crash.

The driver of Vehicle #1 stated she did not see Vehicle #2 (Brick School Bus) was behind her and she tried to make a U turn around the construction cones to head north on Jack Martin Blvd. She added she unknowingly turned in front of Vehicle #2 and caused the crash. She was issued a summons for making an improper U turn.

The driver of vehicle #2 stated she had slowed for Vehicle #1 to get in front of her vehicle and that soon after Vehicle #1 made the improper U turn in front of her. The driver of Vehicle #2 stated she was unable to avoid the crash.

The insurance information for the school bus is as follows: Policy # P223AG

Company # SBJIF003

There were no injuries reported on scene.

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: _____ Code: **01-Municipal Police**

Station: **Brick Police**

Case No: **2015-00074465**

Jack Martin Blvd

