

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2020-00007884			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle #2 was traveling eastbound on Route 88. Vehicle #1 was traveling directly behind vehicle #2. Vehicle #1's front bumper collided with the rear bumper of vehicle #2.

Driver of vehicle #2 stated he was traveling eastbound on Route 88. He started to slow down due to the traffic ahead. At that time, vehicle #1's front bumper collided with his rear bumper.

Driver of vehicle #1 stated he was traveling eastbound on Route 88, behind vehicle #2. He noticed vehicle #2 coming to a quick stop. He stepped on the brake pedal, while down shifting gears to try and slow down. Due to the rain fall and the ground being wet, he could not stop in time. At that time, his front bumper collided with vehicle #2's rear bumper.

Driver of vehicle #2 had a complaint of head pain and refused any medical attention. Based off my observations and both drivers' statements, I find vehicle #1 at fault for following too closely.

146. Officer's Signature John P Stephenson	147. Badge # 291	148. Reviewer Joseph T Pacitti	Badge # 238	149. Case Status ☐ Pending ☒ Complete
---	---------------------	-----------------------------------	----------------	---


New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2020-00007884

144 Crash Diagram (NOT TO SCALE)

 Indicate North

Route 88



Hoffman Street

John P Stephenson

Officer's Signature

291

Badge Number