

New Jersey Police Crash Investigation Report												Case Number 2019-00004315			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 2 was stopped at a yield sign on the ramp from RT 88 to RT 70 eb. Vehicle 1 was stopped behind Vehicle 2.

Vehicle 2 started forward but was forced to stop again due to oncoming traffic. Vehicle 1 started forward with

Vehicle 2 but failed to stop again, causing a rear end collision.

Driver 1 stated she thought Vehicle 2 was going to continue it's merge onto RT 70 when it initially started forward. After looking back to her left and observing traffic was clear, she started forward, not realizing vehicle 2 had stopped again. Driver 1 stated she was unable to stop again to avoid the collision.

No injuries were reported on scene by either party. Vehicle 2 was driven from the scene and Vehicle 1 remained on scene in a valid parking space, disabled with leaking fluid from the engine. No motor vehicle summonses were issued.

146. Officer's Signature Daniel P Testa	147. Badge # 265	148. Reviewer —	Badge # —	149. Case Status ☐ Pending ☒ Complete
--	---------------------	--------------------	--------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police

Code: 01

Station:

Case No: 2019-00004315


144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



RT 70

ROUTE 88



RT 70

Daniel P Testa

Officer's Signature

265

Badge Number