

New Jersey Police Crash Investigation Report												Case Number 2018-00074948			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle #1 was traveling East on Route 88. Vehicle #2 was stopped in traffic waiting to make a left turn onto Hoover Street. The front driver side of Vehicle #1 struck the rear passenger side of Vehicle #2.

Driver #1 first advised that he was struck by a vehicle traveling in the opposite direction on Route 88. When advised that he actually struck a vehicle that was waiting to make a left turn, Driver #1 stated he did not see it as that. Driver #1 further stated that he never observed any vehicles waiting to make a left turn.

Driver #2 stated she was completely stopped in traffic for some time waiting to make the left turn when she was suddenly struck in the rear passenger side by Vehicle #1. Driver #2 further advised that Vehicle #1 continued up the roadway shortly before pulling over and stopping on the shoulder. The damage to both vehicles was consistent with that of Driver #2's account.

Based upon my observations, and statements made by both parties, I find driver #1 at fault for colliding with Vehicle #2.

146. Officer's Signature Michael V Bennett II	147. Badge # 279	148. Reviewer Michael N Drew	Badge # 169	149. Case Status ☐ Pending ☒ Complete
--	---------------------	---------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram


Police Dept: Brick Police

Code: 01

Station:

Case No: 2018-00074948

144 Crash Diagram (NOT TO SCALE)



Michael V Bennett II

Officer's Signature

279

Badge Number