



Kingston Volunteer Fire Company #1

South Brunswick Fire District #3

6-8 Heathcote Road, Kingston, New Jersey 08528

INCIDENT

Incident Number 24-300118	Incident Date 05/13/2024	NFIRS Number 0000138	Incident Type (745) - Alarm system activation, no fire - unintentional
FDID 12321	Station Kingston 24	Shift M-F Evening Time/Weekends	District South Brunswick Dist #3
Initial Dispatch Code 			
Alarms 	Working Fire? 	COVID-19 was a factor 	Critical Incident Team
Temporary Resident Involvement 			
Hazardous Materials Released 			
Action Taken 1 (81) - Incident command			
Action Taken 2 (86) - Investigate			

AID

Aid Given/Received

(N) - None

LOCATION

Location Type

(1) - Street address

Address

30 Tanner Dr, Princeton, New Jersey, 08540

Cross Street, USNG, or Directions

Latitude

Longitude

Census Tract

Detector Alerted Occupant

Property Use

(419) - 1 or 2 family dwelling

Mixed Use

TIMES

PSAP Received

Dispatch Notified Time

Alarm Time

21:04:00, 05/13/2024

Arrival Time

21:12:00, 05/13/2024

Water on Fire Time

At Patient Time

 TIMES

Loss Stop Time

Controlled Time

Last Unit Cleared Time

21:32:00, 05/13/2024

Total On Scene Time

0 hrs 20 mins 0 sec

Total Incident Time

0 hrs 28 mins 0 sec

 COUNTS

Counts Include Aid Received?

No

Suppression:

Apparatus

1

Personnel

2

EMS:

Apparatus

0

Personnel

0

Other:

Apparatus

2

Personnel

2

 PERSON/OWNER AUTHORIZATION

Report Writer:

Name

Luck, John

Employee Number

34

Assignment

Authorization Date

05/13/2024

Officer in Charge:

Name

Luck, John

Employee Number

34

Assignment

Authorization Date

05/13/2024

Quality Control:

Name

Coniglio, Thomas

Authorization Date

07/01/2024

 INCIDENT NARRATIVE

Dispatched for an activated fire alarm . upon arrival of C240 the homeowner reported the alarm was activated due to careless cooking.the homeowner had opened all the windows and doors to ventilate the houseand there was no smoke present. the house was checked with no sign of smoke or fire found. the upstairs detector was found to be faulty. the homeownerwas advised to replace the detectoras they were mfg. in 1999. the homeownerhad battery operated detectors and another one was left. all units cleared and command terminated.

W Walker for J Luck

Created By: Walker, Bill

 Unit Reports

ENGINE 3

Use

(1) - Suppression

Responding From

Priority

Response Delays

Dispatch Time

21:04:00, 05/13/2024

Enroute Time

21:04:00, 05/13/2024

Arrival Time

21:12:00, 05/13/2024

At Patient Time

Clear Time

21:32:00, 05/13/2024

In District Time

ENGINE 3

Actions Taken:

Investigate

Personnel

George Luck, Hector Arroyo

CHIEF CAR

Use

(0) - Other

Responding From

Priority

Response Delays

Dispatch Time

21:04:00, 05/13/2024

Enroute Time

21:04:00, 05/13/2024

Arrival Time

21:12:00, 05/13/2024

At Patient Time

Clear Time

21:32:00, 05/13/2024

In District Time

Actions Taken:

Incident command

Personnel

John Luck

DEPUTY CHIEF CAR

Use

(0) - Other

Responding From

Priority

Response Delays

Dispatch Time

21:04:00, 05/13/2024

Enroute Time

21:04:00, 05/13/2024

Arrival Time

21:12:00, 05/13/2024

At Patient Time

Clear Time

21:32:00, 05/13/2024

In District Time

Actions Taken:

Investigate

Personnel

Rob Weissman