

New Jersey Police												Case Number			Page <u>2</u> of <u>4</u>		
Crash Investigation Report												2022-00053837					
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death			

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

A motor vehicle collision occurred in the intersection of Jack Martin Boulevard and Green Grove Road. Vehicle 01 was traveling straight ahead on Jack Martin Boulevard headed north bound. Vehicle 02 was traveling on Green Grove Road towards the intersection with Jack Martin Boulevard before coming to a stop at the stop sign. Vehicle 02 entered the intersection while vehicle 01 was about to pass causing the front driver side corner of vehicle 01 to strike the rear driver side corner of vehicle 02.

While on scene, there were no reported injuries and all parties declined medical attention.

Driver 01 stated he was traveling on Jack Martin Boulevard going straight ahead towards Burrsville Road. Driver 01 explained another uninvolved motor vehicle made a right turn ahead of him to enter onto Green Grove Road. Driver 01 said he was about to travel through the intersection when vehicle 02 suddenly entered the roadway directly ahead of him. Driver 01 went on to state he attempted to avoid the collision but was unable to do so in time.

Driver 02 stated she was traveling on Green Grove Road and came to a stop at the stop sign to wait to make a left

146. Officer's Signature Brennan James Lanni	147. Badge # 307	148. Reviewer Marc C Alexander	Badge # 216	149. Case Status ☐ Pending ☒ Complete
---	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash DescriptionPolice Dept: Brick Police Code: 01
Station: Case No: 2022-00053837

145 Crash Description

turn onto Jack Martin Boulevard. Driver 02 explained she observed an uninvolved motor vehicle make a right turn off of Jack Martin Boulevard onto Green Grove Road. Driver 02 said she did not observe anyone behind this motor vehicle so she proceeded to enter the roadway believing it to be clear. Driver 02 stated vehicle 01 struck vehicle 02 as she began to make her turn in the intersection.

Through my investigation, I find driver 02 at fault for failure to yield right-of-way and obstructed view.


Brennan James Lanni

307

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2022-00053837

144 Crash Diagram (NOT TO SCALE)



Brennan James Lanni

307