

New Jersey Police Crash Investigation Report Motor Vehicle Crash Description	Police Dept: _____ Code: _____
	Station: _____ Case No: _____

145. Crash Description

Ptl. Gale was flagged down to the above accident scene while on patrol in the area of Main Street and Park Place Avenue. Upon arrival, officers discovered V1 facing East on the sidewalk and against a utility pole on the South Bound side of Main Street. V2 was discovered parked facing North in the South Bound Lane of Main Street, several feet North of the accident. Officers made contact with Driver 2 who was seated on the street and was alert and conscious. Officers then discovered Driver 1 who was still seated and trapped in V1, and was unconscious, unresponsive and not breathing. Officers attempted to remove Driver 1 from vehicle, but were unsuccessful due to damage on front and rear driver side door. Officers then made entry into the vehicle from the passenger side and began to administer first aid and resuscitative efforts. Officers advised HQ to dispatch First Aid and Medic Units, as well as the Fire Dept. and Asbury Park FD Extrication Team. Medics arrived on scene and medical treatment of Driver 1 was turned over to their care. Asbury Park FD and Extrication Team arrived shortly after, in which Driver 1 was extricated from V1 and subsequently transported by Asbury Park EMS and Medics to JSUMC. Driver 2 was also assessed and transported by Bradley Beach EMS to JSUMC for a possible head injury. This agency was later notified by JSUMC staff the Driver 1 had passed away while at the hospital.

Subsequent investigation through interview from Driver 2 and CCTV camera footage revealed the following. V2 was traveling North on Main Street approaching the intersection at Park Place Avenue. Driver 2 stated that as she was approaching the intersection at Main Street and Park Place Avenue, V1 had suddenly entered the intersection in front of her while turning left onto Main Street. . Driver 2 stated that V1 was traveling West on Park Place Avenue and stopped at the intersection of Main Street, prior to entering the intersection in front of her. CCTV footage viewed by officers on scene, confirmed the same sequence of events as explained by Driver 2. Officers viewed the footage and were able to confirm that V1 was traveling West on Park Place Avenue and had stopped at the intersection at Main Street. V1 is then observed entering the intersection in front of V2 which was traveling North on Main Street, causing the collision.

*** See Attached Diagram and Field Measurements***