

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report											Case Number 20000461				Page <u>2</u> of <u>3</u>	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE NJTR-1B

145. Crash Description/Narrative

Vehicle 1 (V1) was in the right lane and Vehicle 2 (V2) was in the middle lane on Rt 130 south. Driver of V1 stated when she noticed that her lane was turning into a exit ramp (for community park) she tried to change lanes, to the left, but struck V2 who was travelling straight ahead. Driver of V2 stated he was travelling straight ahead when V1 merged into him. Visible damage to the driver side mirror on V1 and no visible damage on V2. No injuries were reported on scene. V2 was towing trailer ME REG:20TLR51903 with no visible damage found. Based on driver statements and evidence at the scene, crash investigation revealed the driver of V1 at fault for an unsafe lane change. Driver of V1 was issued summon 1215E20000108 for 39:4-97.

Box 55 No three digit code. Insurance #24015.

146. Officer's Signature TSUI L	147. Badge # 162	148. Reviewer MCCORMICK M	Badge # 100	149. Case Status ☐ Pending ☒ Complete
---	----------------------------	-------------------------------------	-----------------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: NORTH BRUNSWICK Code: 01

Station: - Case No: 20000461

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



TSUI L

Officer's Signature

162

Badge Number