



NJTR - 1 (Rev. 01/17)

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Address of Occupants If Deceased, Date & Time of
E	--	--	--	--	--	--	--	--	--	--	--	--	--	-- --
F	--	--	--	--	--	--	--	--	--	--	--	--	--	-- --
G	--	--	--	--	--	--	--	--	--	--	--	--	--	-- --
H	--	--	--	--	--	--	--	--	--	--	--	--	--	-- --
I	--	--	--	--	--	--	--	--	--	--	--	--	--	-- --
J	--	--	--	--	--	--	--	--	--	--	--	--	--	-- --

144 Crash Diagram



145 Crash Description

D1 STATED IN EFFECT THAT V1 WAS ENTERING ROUTE 27 NORTH FROM THE SHOULDER. D1 FURTHER STATED THAT V2 THEN STRUCK THE REAR BUMPER OF V1 AFTER V1 ENTERED ROUTE 27 NORTH.

D2 STATED IN EFFECT THAT V1 WENT OVER THE DOUBLE YELLOW TRAFFIC LINE AND PASSED V2. D2 FURTHER STATED THAT V1 ATTEMPTED TO ENTER ROUTE 27 NORTH AND CUT OFF V2, WHICH CAUSED V2 TO HIT THE REAR BUMPER OF V1.