

Fire Incident # 2025-75 was located at 300 Cold Soil Road, an automatic fire alarm and the response time was 9:38 (minutes/seconds) to the station and 12:54 (minutes/seconds) to the scene. The cause of the activation was a malfunctioning smoke alarm. This call was listed on the run data sheets provided but inadvertently left off of the memorandum.