



Morristown Fire Department

Station: **0**
Shifts Or Platoon: **Tour 3**

Location: 20 Hillairy AVE Morristown NJ 07960	Incident Type: 111 - Building fire
Lat/Long: N 40° 48' 22.45" W 74° 28' 31.21"	FDID: 14240 Incident #: 2023-00087 Exposure ID: 71195949 Exposure #: 0 Incident Date: 01/19/2023 Dispatch Run #: F230190051
Location Type: 1 - Street address	

Report Completed by:	McDonough , Sean S	ID: 1180	Date: 01/20/2023
Report Reviewed by:	Prizzi , Dominic	ID: 1122	Date: 02/13/2023
Report Printed by:	Doyle, Lindsay	ID: S-1	Date: 9/28/2023 Time: 11:52

Structure Type: Enclosed building	Property Use: 419 - 1 or 2 family dwelling
Automatic Extinguishment System Present: ☐	Detectors Present: ☒ Cause of Ignition: Unintentional
Aid Given or Received: None	Primary action taken: 86 - Investigate
Additional actions: 81 - Incident command , 11 - Extinguishment by fire service personnel	
Losses	Pre-Incident Values
Property:	Property:
Contents:	Contents:
Total:	Total:
Civilian Injuries: 0	Fire Service Injuries: 0
Civilian Fatalities: 0	Fire Service Fatalities: 0
Total Casualties: 0	Total Fire Service Casualties: 0
Total # of apparatus on call: 5	Total # of personnel on call: 7

NARRATIVE (2)

Narrative Title: n/a

Narrative Author: McDonough, Sean

Narrative Date: 01/20/2023 00:52:17

Narrative Apparatus ID: F24CA

Narrative:

While enroute dispatch advised that the caller said the fire had been extinguished.

On arrival found a 2 family 2 story wood frame with nothing showing. Capt 1 made entry calling for the tenant who was still inside, when asked what was going on he said "the fire is out; its upstairs". Eng 4 B, & L1-B went to investigate Div 2.

Fire was located in a bedroom on the BC corner Div2. FF Rickershauser made entry and found a dog which he was able to remove from the fire room. 2 PWs were used to extinguish a fire involving a couch and clothes. Fire was confined to the one room.

There were multiple candles, smoking devices, a space heater, and a power strip all within the location of the fire.

The tenants daughter whose room it was stated she had a candle going and an article of clothing has fallen on it. She then said she tried to get the dog out of the room but was pushed back by the smoke.

Multiple extension cords were noticed through out the home as well as temporary lights being used to light various rooms. The tenant stated they have problems with the electec in the home.

Power was secured to the effected area of the home.

Overhaul was completed, all burned and charred debris removed, checked for extension with Thermal imaging cameras.

Deputy Chief Prizzi took the bldg owners contact info to follow up with.

Command terminated.

APPARATUS			
Unit	F24CA	Unit	F24E1
Type:	Chief officer car	Type:	Engine
Use:	Suppression	Use:	Suppression
Response Mode:	Lights and Sirens	Response Mode:	Lights and Sirens
# of People	1	# of People	1
Alarm	01 /19/2023 22:39:39	Alarm	01 /19/2023 22:39:39
Dispatched	01 /19/2023 22:40:38	Dispatched	01 /19/2023 22:40:38
Enroute	01 /19/2023 22:42:46	Enroute	01 /19/2023 22:42:46
Arrived	01 /19/2023 22:44:21	Arrived	01 /19/2023 22:44:54
Cancelled	-- / -- / -- -- : -- : --	Cancelled	-- / -- / -- -- : -- : --
Cleared Scene	01 /19/2023 23:34:25	Cleared Scene	01 /19/2023 23:34:25
In Quarters	-- / -- / -- -- : -- : --	In Quarters	-- / -- / -- -- : -- : --
In Service	01 /19/2023 23:34:25	In Service	01 /19/2023 23:34:25
Unit	F24E4	Unit	F24L1
Type:	Engine	Type:	Truck or aerial
Use:	Suppression	Use:	Suppression
Response Mode:	Lights and Sirens	Response Mode:	Lights and Sirens
# of People	2	# of People	2
Alarm	01 /19/2023 22:39:39	Alarm	01 /19/2023 22:39:39
Dispatched	01 /19/2023 22:40:38	Dispatched	01 /19/2023 22:40:38
Enroute	01 /19/2023 22:42:46	Enroute	01 /19/2023 22:42:46
Arrived	01 /19/2023 22:44:42	Arrived	01 /19/2023 22:44:48
Cancelled	-- / -- / -- -- : -- : --	Cancelled	-- / -- / -- -- : -- : --
Cleared Scene	01 /19/2023 23:34:25	Cleared Scene	01 /19/2023 23:34:25
In Quarters	-- / -- / -- -- : -- : --	In Quarters	-- / -- / -- -- : -- : --
In Service	01 /19/2023 23:34:25	In Service	01 /19/2023 23:34:25
Unit	F24C2		
Type:	Chief officer car		
Use:	Suppression		
Response Mode:	Lights and Sirens		
# of People	1		
Alarm	01 /19/2023 22:39:39		
Dispatched	01 /19/2023 22:47:48		
Enroute	01 /19/2023 22:47:48		
Arrived	01 /19/2023 23:11:34		
Cancelled	-- / -- / -- -- : -- : --		
Cleared Scene	01 /19/2023 23:34:25		
In Quarters	-- / -- / -- -- : -- : --		
In Service	01 /19/2023 23:34:25		
Number Of People not on apparatus: 0			

FIRE			
Acres Burned	None or Less Than One	Acres Burn From Wildland Form	False
Area Of Fire Origin	Bedroom - < 5 persons; included are jail or prison	Heat Source	Candle
Item First Ignited	Upholstered sofa, chair, vehicle seats	Fire Is Confined To Object Of Origin	
Type Of Material	Fabric, fiber, cotton, blends, rayon, wool	Cause Of Ignition	Unintentional
Factor Contributing To Ignition	Heat source too close to combustibles.		
Human Factors Contributing	Possibly impaired by alcohol or drugs, Unattended or unsupervised person,		

STRUCTURE FIRE

Structure Type	Enclosed building	Building Status	In normal use
# Of Stories At Above Grade	2	# Of Stories Below Grade	1
Square Feet		Length	30
Width	50	Floor Of Origin	2
Fire Spread	Confined to room of origin		
Minor Damage	0	Significant Damage	0
Heavy Damage	0	Extreme Damage	0
Presence Of Detectors	Present	Type Of Detection System	Smoke
Detector Power Supply	Battery only	Detector Operation	Detector operated
Detector Effectiveness	Detector alerted occupants, occupants responded	Detector Failure Reason	

PEOPLE -- PERSON 1

Is Owner	True	Business Name	973-675-9345
Name	Welling Walker	Date of Birth	
Address			

PEOPLE -- PERSON 2

Is Owner	False	Business Name	
Telephone Number		Involvement	Tenant
Name	MR Lee I Bradford JR	Date of Birth	11/5/1964
Address	20 Hillairy AVE Morristown, NJ 07960-		

INCIDENT IMAGES

Member Making Report (Captain/EMT Sean S McDonough): _____

Incident Reviewer (Provisional Deputy Chief Dominic Prizzi): _____



Morristown Fire Department

Station: **0**
Shifts Or Platoon: **Tour 1**

Location: 98 Elm ST Morristown NJ 07960	Incident Type: 111 - Building fire
Lat/Long: N 40° 47' 47.08" W 74° 28' 27.86"	FDID: 14240 Incident #: 2023-00275 Exposure ID: 72122390 Exposure #: 0 Incident Date: 03/11/2023 Dispatch Run #: F230700002
Location Type: 1 - Street address	

Report Completed by:	Barter , Philip	ID: 1164	Date: 03/11/2023
Report Reviewed by:	Prizzi , Dominic	ID: 1122	Date: 03/13/2023
Report Printed by:	Doyle, Lindsay	ID: S-1	Date: 9/28/2023 Time: 11:52

Structure Type: Enclosed building	Property Use: 161 - Restaurant or cafeteria		
Automatic Extinguishment System Present: ☐	Detectors Present: ☒	Cause of Ignition: Unintentional	
Aid Given or Received: None	Primary action taken: 11 - Extinguishment by fire service personnel		
Additional actions: 12 - Salvage & overhaul , 51 - Ventilate			
Losses	Pre-Incident Values		
Property:	Property:	Civilian Injuries: 0	Fire Service Injuries: 0
Contents:	Contents:	Civilian Fatalities: 0	Fire Service Fatalities: 0
Total:	Total:	Total Casualties: 0	Total Fire Service Casualties: 0
Total # of apparatus on call: 4		Total # of personnel on call: 5	

NARRATIVE (2)

Narrative Title: n/a

Narrative Author: Barter, Philip

Narrative Date: 03/11/2023 04:06:27

Narrative Apparatus ID: F24CA

Narrative:

Capt. 1 arrived, reported an awning on fire attached to the front of the building. Capt. 1 requested the remainder of the 1st alarm assignment be dispatched and established command. E-3 pulled past the building to leave room for the ladder truck. E-3 began knocking the fire using PW cans. Ladder-1 and E-1 arrived and began checking for extension in the building. No extension but a smoke condition on division 2 with 2 apartments present. Alarm system failed to operate(Fire Marshal notified). FD began ventilating 1st and 2nd floors. Once the fire was extinguished, no extension was determined and the building was ventilated, FD conducted investigation and determined the fire was caused by led lighting attached to the awning. FD secured the power to the lighting. Resident on 2nd floor was going to notify the building owner. FD cleared and returned to service.

APPARATUS			
Unit	F24CA	Unit	F24E1
Type:	Chief officer car	Type:	Engine
Use:	Suppression	Use:	Suppression
Response Mode:	Lights and Sirens	Response Mode:	Lights and Sirens
# of People	1	# of People	1
Alarm	03 /11/2023 03:05:37	Alarm	03 /11/2023 03:05:37
Dispatched	03 /11/2023 03:06:36	Dispatched	03 /11/2023 03:06:36
Enroute	03 /11/2023 03:10:12	Enroute	03 /11/2023 03:16:58
Arrived	03 /11/2023 03:11:15	Arrived	03 /11/2023 03:17:01
Cancelled	-- /--/-- --:--:--	Cancelled	-- /--/-- --:--:--
Cleared Scene	03 /11/2023 03:40:00	Cleared Scene	03 /11/2023 03:40:00
In Quarters	-- /--/-- --:--:--	In Quarters	-- /--/-- --:--:--
In Service	03 /11/2023 03:40:00	In Service	03 /11/2023 03:40:00
Unit	F24E3	Unit	F24L1
Type:	Engine	Type:	Truck or aerial
Use:	Suppression	Use:	Suppression
Response Mode:	Lights and Sirens	Response Mode:	Lights and Sirens
# of People	1	# of People	2
Alarm	03 /11/2023 03:05:37	Alarm	03 /11/2023 03:05:37
Dispatched	03 /11/2023 03:10:17	Dispatched	03 /11/2023 03:11:54
Enroute	03 /11/2023 03:10:17	Enroute	03 /11/2023 03:14:03
Arrived	03 /11/2023 03:11:59	Arrived	03 /11/2023 03:16:04
Cancelled	-- /--/-- --:--:--	Cancelled	-- /--/-- --:--:--
Cleared Scene	03 /11/2023 03:40:34	Cleared Scene	03 /11/2023 03:40:34
In Quarters	-- /--/-- --:--:--	In Quarters	-- /--/-- --:--:--
In Service	03 /11/2023 03:40:34	In Service	03 /11/2023 03:40:34
Number Of People not on apparatus: 0			

FIRE			
Acres Burned	None or Less Than One	Acres Burn From Wildland Form	False
Area Of Fire Origin	Entranceway, lobby	Heat Source	Electrical arcing
Item First Ignited	Awning, canopy	Fire Is Confined To Object Of Origin	TRUE
Type Of Material	Plastic	Cause Of Ignition	Unintentional
Factor Contributing To Ignition	Electrical failure, malfunction, other		
Human Factors Contributing	None		
Equipment Involved In Ignition Flag	True	Equipment Involved	Decorative or landscape lighting, low voltage
Equipment Power Source	Batteries and low voltage (< 50 volts)	Equipment Portability	Stationary

STRUCTURE FIRE			
Structure Type	Enclosed building	Building Status	In normal use
# Of Stories At Above Grade	2	# Of Stories Below Grade	1
Square Feet		Length	75
Width	75	Floor Of Origin	1
Fire Spread	Confined to object of origin		
Minor Damage	0	Significant Damage	0
Heavy Damage	0	Extreme Damage	0
Presence Of Detectors	Present	Type Of Detection System	Smoke
Detector Power Supply	Hardwire with battery backup	Detector Operation	Detector failed to operate
Detector Effectiveness		Detector Failure Reason	Undetermined

Member Making Report (Captain/EMT Philip Barter): _____

Incident Reviewer (Provisional Deputy Chief Dominic Prizzi): _____



Morristown Fire Department

Station: **0**
Shifts Or Platoon: **Tour 4**

Location: 22 Catherine LN Morristown NJ 07960	Incident Type: 111 - Building fire
Lat/Long: N 40° 47' 24.27" W 74° 28' 39.33"	FDID: 14240 Incident #: 2023-00475 Exposure ID: 72916752 Exposure #: 0 Incident Date: 04/23/2023 Dispatch Run #: F231130003
Location Type: 1 - Street address	

Report Completed by:	Prizzi , Dominic	ID: 1122	Date: 04/26/2023
Report Reviewed by:	Prizzi , Dominic	ID: 1122	Date: 05/05/2023
Report Printed by:	Doyle, Lindsay	ID: S-1	Date: 9/28/2023 Time: 11:52

Structure Type: Enclosed building	Property Use: 419 - 1 or 2 family dwelling		
Automatic Extinguishment System Present: ☐	Detectors Present: ☐	Cause of Ignition: Cause under investigation	
Aid Given or Received: Mutual aid received	Primary action taken: 11 - Extinguishment by fire service personnel		
Additional actions: 21 - Search , 12 - Salvage & overhaul			
Losses	Pre-Incident Values		
Property:	Property:	Civilian Injuries: 0	Fire Service Injuries: 1
Contents:	Contents:	Civilian Fatalities: 0	Fire Service Fatalities: 0
Total:	Total:	Total Casualties: 0	Total Fire Service Casualties: 1
Total # of apparatus on call: 11		Total # of personnel on call: 19	

Neighboring Agencies
Agency Name: Madison Fire Agency ID: 14170 Agency Type: Fire
Agency Name: Morris Plains Fire Agency ID: 14230 Agency Type: Fire
Agency Name: Morris Township Fire Agency ID: 14220 Agency Type: Fire

NARRATIVE (2)**Narrative Title:** IR**Narrative Author:** Blekicki, Greg**Narrative Date:** 04/24/2023 19:36:37**Narrative Apparatus ID:** F24CA**Narrative:**

Arrived on scene and found heavy fire on A side, 1st and 2nd floors of a single family 2 1/2 story wood frame (possibly balloon frame construction). A vehicle 5 feet from front of house also on fire. Captain Blekicki established command on A side and started accountability. Captain Blekicki immediately called to upgrade to a 2nd alarm. Accountability was transferred to FF Prachthausen. PD reported that it was confirmed that all residents were out of the structure. E4 and L1 pulled past front of structure and E3 assisted E4 with establishing water supply from MacCulloch Ave. FF Sanfelice and FF Koller stretched the first 1 3/4 inch attack line to the front door. Majority of exterior fire knocked down and line was advanced inside. A second attack line was put into service by FF Loyek and FF Hoferer backing up the primary line after extinguishing vehicle fire. Fire was knocked down on first floor and primary line advanced to 2nd floor. FF Sanfelice reporting hoarding conditions inside. Madison RIC and EMS arrived.

Volunteer members arrived and placed ground ladders on the alpha, bravo and delta sides of the structure. Assistant Fire Chief Paul Miller injured himself while descending the ladder on the delta side. Approximately 6 feet off the ground he slipped and fell to the ground also hitting Volunteer FF Tim Byrnes. Assistant chief Paul Miller was checked out by EMS and brought to Morristown Medical center for further treatment.

FF Sanfelice, working off the line did a primary search with negative results. R5 and Platform 2 arrived with off duty members. A third attack line was placed in service and advanced inside to the attic/division 3. Fire was attacked on all 3 divisions but unable to extinguish. Due to this, the fire load, fire in the walls and limited access, Captain Blekicki ordered an evacuation of the building and a change to defensive operations. PAR was taken and all members accounted for.

Deputy Chief Prizzi arrived and a face to face transfer of command was given by Captain Blekicki who was now assigned as operations. Deputy Chief Prizzi upgraded to a 3rd alarm. Ladder 1 and platform 2 were setup, a 2 1/2 inch line was brought to the rear and four 1 3/4 hand lines were used to fully extinguish the fire. JCPL representative reported that power was de-energized to the entire street. Gas company was unable shut off gas to the structure until conditions improved. Morris Plains members arrived with county air truck. Some of those members were assigned to suppression tasks.

Chief Flanagan arrived and command was transferred from Deputy Chief Prizzi. Defensive operations continued with overhaul being conducted from aerial on Ladder 1. Fire was completely extinguished and the Investigation phase started.

Fire Official Matt Laughlin was notified and advised Chief Flanagan to have CID respond and the Madison fire Official to investigate and document the fire. All suppression units broke down all lines and cleared scene with the exception of Engine 3 with FF Rickershauser and Gathings. They would remain for fire watch. Command was terminated

APPARATUS			
Unit	F24CA	Unit	F24E3
Type:	Chief officer car	Type:	Engine
Use:	Suppression	Use:	Suppression
Response Mode:	Lights and Sirens	Response Mode:	Lights and Sirens
# of People	1	# of People	1
Alarm	04 /23/2023 03:42:52	Alarm	04 /23/2023 03:42:52
Dispatched	04 /23/2023 03:44:23	Dispatched	04 /23/2023 03:44:23
Enroute	04 /23/2023 03:47:02	Enroute	04 /23/2023 03:47:37
Arrived	04 /23/2023 03:48:45	Arrived	04 /23/2023 03:50:03
Cancelled	-- / -- / -- -- : -- : --	Cancelled	-- / -- / -- -- : -- : --
Cleared Scene	04 /23/2023 08:32:01	Cleared Scene	04 /23/2023 10:04:12
In Quarters	-- / -- / -- -- : -- : --	In Quarters	-- / -- / -- -- : -- : --
In Service	04 /23/2023 08:32:01	In Service	04 /23/2023 10:04:12
Unit	F24E4	Unit	F24L1
Type:	Engine	Type:	Truck or aerial
Use:	Suppression	Use:	Suppression
Response Mode:	Lights and Sirens	Response Mode:	Lights and Sirens
# of People	1	# of People	2
Alarm	04 /23/2023 03:42:52	Alarm	04 /23/2023 03:42:52
Dispatched	04 /23/2023 03:44:23	Dispatched	04 /23/2023 03:44:23
Enroute	04 /23/2023 03:47:42	Enroute	04 /23/2023 03:47:30
Arrived	04 /23/2023 03:50:03	Arrived	04 /23/2023 03:50:06
Cancelled	-- / -- / -- -- : -- : --	Cancelled	-- / -- / -- -- : -- : --
Cleared Scene	04 /23/2023 08:18:10	Cleared Scene	04 /23/2023 08:40:44
In Quarters	-- / -- / -- -- : -- : --	In Quarters	-- / -- / -- -- : -- : --
In Service	04 /23/2023 08:18:10	In Service	04 /23/2023 08:40:44
Unit	F24C2	Unit	F24R5
Type:	Chief officer car	Type:	Rescue unit
Use:	Suppression	Use:	Suppression
Response Mode:	Lights and Sirens	Response Mode:	Lights and Sirens
# of People	1	# of People	2
Alarm	04 /23/2023 03:42:52	Alarm	04 /23/2023 03:42:52
Dispatched	04 /23/2023 03:53:58	Dispatched	04 /23/2023 03:55:16
Enroute	04 /23/2023 03:53:58	Enroute	04 /23/2023 03:55:16
Arrived	04 /23/2023 04:01:54	Arrived	04 /23/2023 04:01:53
Cancelled	-- / -- / -- -- : -- : --	Cancelled	-- / -- / -- -- : -- : --
Cleared Scene	04 /23/2023 08:40:41	Cleared Scene	04 /23/2023 08:40:38
In Quarters	-- / -- / -- -- : -- : --	In Quarters	-- / -- / -- -- : -- : --
In Service	04 /23/2023 08:40:41	In Service	04 /23/2023 08:40:38
Unit	F24P2	Unit	F24E7
Type:	Truck or aerial	Type:	BLS unit
Use:	Suppression	Use:	EMS
Response Mode:	Lights and Sirens	Response Mode:	Lights and Sirens
# of People	2	# of People	2
Alarm	04 /23/2023 03:42:52	Alarm	04 /23/2023 03:42:52
Dispatched	04 /23/2023 04:02:28	Dispatched	04 /23/2023 04:21:28
Enroute	04 /23/2023 04:02:28	Enroute	04 /23/2023 04:21:28
Arrived	04 /23/2023 04:21:40	Arrived	04 /23/2023 04:21:37
Cancelled	-- / -- / -- -- : -- : --	Cancelled	-- / -- / -- -- : -- : --
Cleared Scene	04 /23/2023 08:40:37	Cleared Scene	04 /23/2023 08:40:35
In Quarters	-- / -- / -- -- : -- : --	In Quarters	-- / -- / -- -- : -- : --
In Service	04 /23/2023 08:40:37	In Service	04 /23/2023 08:40:35
Unit	F24C1	Unit	P O V
Type:	Chief officer car	Type:	Privately owned vehicle
Use:	Suppression	Use:	Suppression
Response Mode:	Lights and Sirens	Response Mode:	()
# of People	1	# of People	5
Alarm	04 /23/2023 03:42:52	Alarm	04 /23/2023 03:42:52
Dispatched	04 /23/2023 04:59:28	Dispatched	04 /23/2023 03:55:28
Enroute	-- / -- / -- -- : -- : --	Enroute	-- / -- / -- -- : -- : --
Arrived	04 /23/2023 04:59:28	Arrived	04 /23/2023 03:55:28
Cancelled	-- / -- / -- -- : -- : --	Cancelled	-- / -- / -- -- : -- : --
Cleared Scene	04 /23/2023 08:40:31	Cleared Scene	04 /23/2023 08:40:31
In Quarters	-- / -- / -- -- : -- : --	In Quarters	-- / -- / -- -- : -- : --
In Service	04 /23/2023 08:40:31	In Service	04 /23/2023 08:40:31
Unit	F24FM		
Type:	Chief officer car		

Use:	Suppression
Response Mode:	()
# of People	1
Alarm	04 /23/2023 03:42:52
Dispatched	04 /23/2023 03:55:28
Enroute	-- / -- / -- -- : -- : --
Arrived	04 /23/2023 06:00:28
Cancelled	-- / -- / -- -- : -- : --
Cleared Scene	04 /23/2023 08:40:31
In Quarters	-- / -- / -- -- : -- : --
In Service	04 /23/2023 08:40:31
Number Of People not on apparatus: 0	

VEHICLES	
Vehicle	
Make	Hyundai
Type	
Model	Veloster
Color	White
Vin Number	
Year	
License Plate Number	Z91MLS
Owner	
Name	
Phone Number	
Address	
Driver	
Name	
Phone Number	
Address	
License Number	***
Driver Is Owner	No
Driver Is Resident	Undetermined
Insurance	
Company Name	
Company Policy Number	
Company Coverage Level	
Agent Name	
Agent Phone Number	
Involvement	
Law Enforcement Officer	
Police Report Or File Number	
Number Of Occupants	
Number Of Injured Occupants	
Number Of Fatalities	
Disposable Equipment Used	
Narrative Text	Vehicle was parked 5 feet from front of house. Vehicle caught fire after auto exposure

FIRE			
Acres Burned	None or Less Than One	Acres Burn From Wildland Form	False
Area Of Fire Origin	Function areas, other	Heat Source	Undetermined
Item First Ignited	Undetermined	Fire Is Confined To Object Of Origin	
Type Of Material	Undetermined	Cause Of Ignition	Cause under investigation
Factor Contributing To Ignition	Undetermined		
Human Factors Contributing	Asleep,		

STRUCTURE FIRE

Structure Type	Enclosed building	Building Status	In normal use
# Of Stories At Above Grade	3	# Of Stories Below Grade	1
Square Feet		Length	60
Width	20	Floor Of Origin	1
Fire Spread	Confined to building of origin		
Minor Damage	0	Significant Damage	0
Heavy Damage	0	Extreme Damage	0

ARSON**FIRE SERVICE CASUALTIES**

Identification Number		Number Of Responses During Past 24 Hours	
Name	Paul Miller	Gender	Male
Age	44	Date Of Birth	***
Date Of Injury	04 /23/2023	Time Of Injury	04 :10:
Career/Volunteer	Volunteer	Usual Assignment	
Physical Condition Just Prior To Injury		Severity	Treated by physician, not a lost-time injury
Taken To		Activity At Time Of Injury	Climbing ladder
Primary Apparent Symptom	Pain only	Primary Injured Body Part	Spine
Cause Of Firefighter Injury	Fall	Contributing Factor	Slippery or uneven surfaces, other
Object Involved In Injury	Ladder: ground	Where Injury Occured	At scene, outside structure
Injury Relation To Structure	Outside of structure	Stories Or Floor Where Injury Occured	
Specific Location	On ground ladder	Vehicle Type	
Did Protective Equipment Fail And Or Contribue To The Injury			

Member Making Report (Deputy Chief Dominic Prizzi): _____

Incident Reviewer (Deputy Chief Dominic Prizzi): _____



Morristown Fire Department

Station: 0
Shifts Or Platoon: Tour 1

Location: 30 Lafayette AVE Morristown NJ 07960	Incident Type: 111 - Building fire
Lat/Long: N 40° 47' 55.09" W 74° 28' 24.54"	FDID: 14240 Incident #: 2023-00954 Exposure ID: 74652061 Exposure #: 0 Incident Date: 07/25/2023 Dispatch Run #: F232060007
Location Type: 1 - Street address	

Report Completed by:	Babington , Marshall	ID: 1182	Date: 07/25/2023
Report Reviewed by:	Prizzi , Dominic	ID: 1122	Date: 08/01/2023
Report Printed by:	Doyle, Lindsay	ID: S-1	Date: 9/28/2023 Time: 11:53

Structure Type: Enclosed building	Property Use: 161 - Restaurant or cafeteria		
Automatic Extinguishment System Present: ☒	Detectors Present: ☐	Cause of Ignition: Failure of equipment or heat source	
Aid Given or Received: None	Primary action taken: 64 - Shut down system		
Losses	Pre-Incident Values		
Property:	Property:	Civilian Injuries: 0	Fire Service Injuries: 0
Contents:	Contents:	Civilian Fatalities: 0	Fire Service Fatalities: 0
Total:	Total:	Total Casualties: 0	Total Fire Service Casualties: 0
Total # of apparatus on call: 4		Total # of personnel on call: 4	

NARRATIVE (2)

Narrative Title: n/a

Narrative Author: Babington, Marshall

Narrative Date: 07/25/2023 08:40:57

Narrative Apparatus ID: F24CA

Narrative:

FD responded to 30 Lafayette St for report of fire in restaurant. All FD units arrived on scene simultaneously. Upon arrival building was occupied and no alarm was sounding. PD then notified Capt 1 that employee stated there was a fire in the back kitchen area of the restaurant. Cap1 and L1 crew proceeded to the rear of the restaurant. There was a minor smoke condition in the restaurant as we made our way to the rear of the restaurant. Once in the back there was no visible fire and a different employee said that he saw flames shooting from a condenser unit on top of the walk in freezer and he then shut the breakers off to the condenser and fire went out. Area was checked with TIC and it was found that the hottest area was a booster motor for hood exhaust system. That motor was deenergized by FD and restaurant was ventilated. None of the restaurants hood systems were activated or the sprinkler system. Also did not seem to set off the buildings fire alarm system. FD then monitored the motor with TIC and temperatures started to drop to normal ranges. Fire Official was notified and Health Department also. Restaurant manager arrived on scene and was told to shut down the restaurant until health department arrived and conducted an inspection of the restaurant and hood system. Capt 1 cleared E4,E1, and L1 from the scene, Cap1 remained on scene until the Fire Official arrived. Fire Official arrived on scene and informed manager of restaurant that health department was coming out soon and they had to remain closed. FD then cleared from 30 Lafayette ST.

APPARATUS			
Unit	F24CA	Unit	F24E1
Type:	Chief officer car	Type:	Engine
Use:	Suppression	Use:	Suppression
Response Mode:	Lights and Sirens	Response Mode:	Lights and Sirens
# of People	1	# of People	1
Alarm	07 /25/2023 06:23:07	Alarm	07 /25/2023 06:23:07
Dispatched	07 /25/2023 06:24:39	Dispatched	07 /25/2023 06:24:39
Enroute	07 /25/2023 06:27:25	Enroute	-- / -- / -- -- : -- : --
Arrived	07 /25/2023 06:29:11	Arrived	07 /25/2023 06:29:55
Cancelled	-- / -- / -- -- : -- : --	Cancelled	-- / -- / -- -- : -- : --
Cleared Scene	07 /25/2023 08:02:06	Cleared Scene	07 /25/2023 07:01:32
In Quarters	-- / -- / -- -- : -- : --	In Quarters	-- / -- / -- -- : -- : --
In Service	07 /25/2023 08:02:06	In Service	07 /25/2023 07:01:32
Unit	F24E4	Unit	F24L1
Type:	Engine	Type:	Truck or aerial
Use:	Suppression	Use:	Suppression
Response Mode:	Lights and Sirens	Response Mode:	Lights and Sirens
# of People	1	# of People	1
Alarm	07 /25/2023 06:23:07	Alarm	07 /25/2023 06:23:07
Dispatched	07 /25/2023 06:24:39	Dispatched	07 /25/2023 06:24:39
Enroute	07 /25/2023 06:27:34	Enroute	07 /25/2023 06:27:21
Arrived	07 /25/2023 06:34:16	Arrived	07 /25/2023 06:29:59
Cancelled	-- / -- / -- -- : -- : --	Cancelled	-- / -- / -- -- : -- : --
Cleared Scene	07 /25/2023 07:01:32	Cleared Scene	07 /25/2023 07:01:32
In Quarters	-- / -- / -- -- : -- : --	In Quarters	-- / -- / -- -- : -- : --
In Service	07 /25/2023 07:01:32	In Service	07 /25/2023 07:01:32
Number Of People not on apparatus: 0			

FIRE			
Acres Burned	None or Less Than One	Acres Burn From Wildland Form	False
Area Of Fire Origin	Duct: hvac, cable, exhaust, heating, or AC	Heat Source	Electrical arcing
Item First Ignited	Electrical wire, cable insulation	Fire Is Confined To Object Of Origin	TRUE
Type Of Material	Undetermined	Cause Of Ignition	Failure of equipment or heat source
Factor Contributing To Ignition	Mechanical failure, malfunction, other		
Human Factors Contributing	None		
Equipment Involved In Ignition Flag	True	Equipment Involved	Heating, ventilation and air conditioning, other
Equipment Power Source	Electrical line voltage (>= 50 volts)	Equipment Portability	Stationary

STRUCTURE FIRE			
Structure Type	Enclosed building	Building Status	In normal use
# Of Stories At Above Grade	2	# Of Stories Below Grade	1
Square Feet	1500	Length	
Width		Floor Of Origin	1
Fire Spread	Confined to object of origin		
Minor Damage	0	Significant Damage	0
Heavy Damage	0	Extreme Damage	0
Presence OF AES	Present	Type Of AES	Wet-pipe sprinkler system
Operation Of Automatic Extinguishing System	Fire too small to activate system	Number Of Sprinkler Heads Operating	
Reason For AES Failure	Fire not in area protected by the system		

Member Making Report (FF/EMT Marshall Babington): _____



Morristown Fire Department

Station: **0**
Shifts Or Platoon: **Tour 4**

Location: 56 Ridgedale AVE # 56 B Morristown NJ 07960	Incident Type: 111 - Building fire
Lat/Long: N 40° 47' 56.65" W 74° 28' 9.37"	FDID: 14240 Incident #: 2023-02232 Exposure ID: 75174380 Exposure #: 0 Incident Date: 08/20/2023 Dispatch Run #: F232320024
Location Type: 1 - Street address	

Report Completed by:	Loyek , Scott	ID: 1125	Date: 08/26/2023
Report Reviewed by:	Not Reviewed		
Report Printed by:	Doyle, Lindsay	ID: S-1	Date: 9/28/2023 Time: 11:53

Structure Type: Enclosed building	Property Use: 429 - Multifamily dwelling		
Automatic Extinguishment System Present: ☐	Detectors Present: ☐	Cause of Ignition: Unintentional	
Aid Given or Received: Automatic aid received	Primary action taken: 10 - Fire control or extinguishment, other		
Additional actions: 21 - Search , 51 - Ventilate			
Losses	Pre-Incident Values		
Property:	Property:	Civilian Injuries: 0	Fire Service Injuries: 0
Contents:	Contents:	Civilian Fatalities: 0	Fire Service Fatalities: 0
Total:	Total:	Total Casualties: 0	Total Fire Service Casualties: 0
Total # of apparatus on call: 8		Total # of personnel on call: 16	

Neighboring Agencies
Agency Name: Madison Fire Agency ID: 14170 Agency Type: Fire
Agency Name: Morris Plains Fire Agency ID: 14230 Agency Type: Fire
Agency Name: Morris Township Fire Agency ID: 14220 Agency Type: Fire

NARRATIVE (2)**Narrative Title:** n/a**Narrative Author:** Loyek, Scott**Narrative Date:** 08/25/2023 13:01:00**Narrative Apparatus ID:** F24CA**Narrative:**

Captain 1, Engine 4, Ladder 1, Engine 1 dispatched to 56 Ridgedale Ave #56B commercial structure fire. Captain 1 arrived on with command and requested 2nd alarm due to heavy smoke. Gave size-up of fire on the second floor coming out windows. Due to size of building, fire conditions, and high life hazard Captain 1 requested 3rd alarm. Tenants' self-evacuated building and stated everyone was out of their units and no one was injured.

Advised Engine 4 to secure water supply from hydrant on corner of Abbett Ave and Ridgedale Ave. Ladder 1 crew deployed 1 3/4 in attack line to the front door. Engine 1 assisted Ladder crew with hose line. Crews knocked down main body of fire on second floor and hydraulic vented bedroom. L-1 crew conducted a primary search of unit and results were negative. E-4 operator put a ground ladder on D side of building for firefighter egress. During ladder deployment FF Mussner injured hand. Morris Township Fire was assigned to overhaul of fire room. Interior fire crew coordinated with ladder operation to vent roof to improve visibility and remove excess heat. D/C Prizzi arrived on scene and command was transferred. Captain 1 was assigned to operations.

DC arrived and assumed command approx. 20 minutes after first arriving units. Utilities were requested on scene and arrived shutting down gas and electrical to fire Apt. Captain 1 established water supply, attack crews, primary search, and was in the process of overhaul and ventilation. Accountability, RIC, safety, staging and rehab was established. MPD, EMS, Madison FD, Morris Twp FD, County Coordinators and County air truck was on scene. Fire investigator from Madison FD was requested along with Sheriffs Dept photographer. Tenants of fire apt were on the side of the building in safe area being attended to by EMS on scene. I introduced myself to the tenants and asked if they were ok in which they stated yes. I asked if there were any details, they could give me about fire origin and what they experienced inside at the incipient stage of the fire progression. No clear details were given as only they could remember a lot of smoke and decided to exit building. Red Cross was requested due to damage of fire apt and welfare of tenants. Tenants would not be able to reoccupy and live there in the condition it was after fire and smoke damage. Tenants were informed of Red Cross request. Representative was approx. 20 minutes out. After ventilation and light overhaul in fire Apt, secondary search was conducted. Captain Loyek, Captain Nunn from Madison FD, Sheriffs Dept Photographer and MPD Detective went in to investigate. Outside crews were then directed to help tenants from the rest of the building. All Apts in building were checked for any gas readings on meters and ventilated as necessary before any tenants were allowed to reoccupy. The 2 Apts that were not to be reoccupied were fire apt and immediate apt on the Bravo 1 exposure. PD was made aware of the 2 Apts and were going to secure property when finished with operations and investigation. Red Cross representative arrived on scene and was introduced to both tenants. EMS was monitoring tenants constantly checking on medical condition. Both tenants were outside sitting on wall alert and with 2 other people who were friends and or family. Red Cross Rep started taking information and was coordinating welfare and lodging for tenants. Fire Apt was overhauled and rechecked with TIC along with all 6 sides of fire room. It was noted by me and Chief Nunn that fire spread would have been catastrophic if fire had impeded and breached attic common cockloft area. Because of the open area and lightweight construction, fire spread in this area would have destroyed and collapsed roof for possibly the entire building making it uninhabitable. After adjoining Apts were checked with meters and ventilated all tenants were allowed to reoccupy their Apts. All crews were ordered to clean up and recheck area. TIC was again utilized to check for any extension. FD Investigator Nunn along with MPD detective and Sherriff photographer stayed on scene to continue investigation and secure property. Engine crew stayed behind with AC Cirelli to assist with investigation and check and extinguish hot spots in Apt. DC cleared all other fire units on scene and returned to service. EMS and PD remained on scene along with Red Cross. At approximately 0430 Engine 4 crew were complete with overhaul and assisting investigation. Engine 4 cleaned up and went back into service. PD and EMS was still on scene and Red Cross was assisting tenants. PD secured fire Apt.

NARRATIVE (3)**Narrative Title:** n/a**Narrative Author:** Loughlin, Matthew**Narrative Date:** 08/25/2023 13:07:16**Narrative Apparatus ID:** n/a**Narrative:**

At approximately 1000hrs on 8/24/23 the Fire Marshal was made aware that one of the tenants went to receive medical treatment on 8/21/23 and was still currently in the hospital receiving treatment 72 hour later. All appropriate agencies were notified

APPARATUS			
Fire Controlled Date / Time:		8/20/2023 11:55:00 PM	
Unit	F24CA	Unit	F24E1
Type:	Chief officer car	Type:	Engine
Use:	Suppression	Use:	Suppression
Response Mode:	Lights and Sirens	Response Mode:	Lights and Sirens
# of People	1	# of People	1
Alarm	08 /20/2023 23:20:31	Alarm	08 /20/2023 23:20:31
Dispatched	08 /20/2023 23:21:25	Dispatched	08 /20/2023 23:21:25
Enroute	08 /20/2023 23:23:03	Enroute	08 /20/2023 23:23:41
Arrived	08 /20/2023 23:26:10	Arrived	08 /20/2023 23:32:34
Cancelled	-- / -- / -- -- : -- : --	Cancelled	-- / -- / -- -- : -- : --
Cleared Scene	08 /21/2023 02:25:32	Cleared Scene	08 /21/2023 02:29:38
In Quarters	-- / -- / -- -- : -- : --	In Quarters	-- / -- / -- -- : -- : --
In Service	08 /21/2023 02:25:32	In Service	08 /21/2023 02:29:38
Unit	F24E4	Unit	F24L1
Type:	Engine	Type:	Truck or aerial
Use:	Suppression	Use:	Suppression
Response Mode:	Lights and Sirens	Response Mode:	Lights and Sirens
# of People	1	# of People	2
Alarm	08 /20/2023 23:20:31	Alarm	08 /20/2023 23:20:31
Dispatched	08 /20/2023 23:21:25	Dispatched	08 /20/2023 23:21:25
Enroute	08 /20/2023 23:23:47	Enroute	08 /20/2023 23:26:31
Arrived	08 /20/2023 23:32:33	Arrived	08 /20/2023 23:32:37
Cancelled	-- / -- / -- -- : -- : --	Cancelled	-- / -- / -- -- : -- : --
Cleared Scene	08 /21/2023 04:28:40	Cleared Scene	08 /21/2023 02:29:32
In Quarters	-- / -- / -- -- : -- : --	In Quarters	-- / -- / -- -- : -- : --
In Service	08 /21/2023 04:28:40	In Service	08 /21/2023 02:29:32
Unit	F24C2	Unit	F24R5
Type:	Chief officer car	Type:	Rescue unit
Use:	Suppression	Use:	Suppression
Response Mode:	Lights and Sirens	Response Mode:	Lights and Sirens
# of People	1	# of People	1
Alarm	08 /20/2023 23:20:31	Alarm	08 /20/2023 23:20:31
Dispatched	08 /20/2023 23:27:34	Dispatched	08 /20/2023 23:34:40
Enroute	08 /20/2023 23:27:34	Enroute	08 /20/2023 23:34:40
Arrived	08 /20/2023 23:46:44	Arrived	08 /20/2023 23:36:35
Cancelled	-- / -- / -- -- : -- : --	Cancelled	-- / -- / -- -- : -- : --
Cleared Scene	08 /21/2023 02:35:33	Cleared Scene	08 /21/2023 02:29:46
In Quarters	-- / -- / -- -- : -- : --	In Quarters	-- / -- / -- -- : -- : --
In Service	08 /21/2023 02:35:33	In Service	08 /21/2023 02:29:46
Unit	F24P2	Unit	F24E7
Type:	Truck or aerial	Type:	BLS unit
Use:	Suppression	Use:	EMS
Response Mode:	Lights and Sirens	Response Mode:	Lights and Sirens
# of People	2	# of People	1
Alarm	08 /20/2023 23:20:31	Alarm	08 /20/2023 23:20:31
Dispatched	08 /20/2023 23:35:49	Dispatched	08 /20/2023 23:40:09
Enroute	08 /20/2023 23:35:49	Enroute	08 /20/2023 23:40:09
Arrived	08 /21/2023 00:12:47	Arrived	08 /20/2023 23:41:14
Cancelled	-- / -- / -- -- : -- : --	Cancelled	-- / -- / -- -- : -- : --
Cleared Scene	08 /21/2023 02:25:46	Cleared Scene	08 /21/2023 04:28:40
In Quarters	-- / -- / -- -- : -- : --	In Quarters	-- / -- / -- -- : -- : --
In Service	08 /21/2023 02:25:46	In Service	08 /21/2023 04:28:40
Number Of People not on apparatus: 6			

FIRE			
Acres Burned	None or Less Than One	Acres Burn From Wildland Form	False
Area Of Fire Origin	Bedroom - 5+ persons; including barrack/dormitory	Heat Source	Heat from powered equipment, other
Item First Ignited	Cabinetry (including built-in)	Fire Is Confined To Object Of Origin	
Type Of Material	Fiberboard, particleboard, and hardboard	Cause Of Ignition	Unintentional
Factor Contributing To Ignition	Unspecified short-circuit arc		
Human Factors Contributing	None		
Equipment Involved In Ignition Flag	True	Equipment Involved	Ground-fault interrupter (GFI), portable, plug-in
Equipment Power Source	Electrical line voltage (≥ 50 volts)	Equipment Portability	Portable

STRUCTURE FIRE			
Structure Type	Enclosed building	Building Status	In normal use
# Of Stories At Above Grade	2	# Of Stories Below Grade	1
Square Feet	1200	Length	
Width		Floor Of Origin	2
Fire Spread	Confined to room of origin		
Minor Damage	0	Significant Damage	0
Heavy Damage	0	Extreme Damage	0