

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2018-00041794			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicles 1 and 2 were traveling eastbound on State Highway 88 in the left lane, approaching the intersection of Post Road. Vehicle 1 was behind Vehicle 2.

As the vehicles were approaching the traffic signal at the intersection, the light was changing to red. Vehicle 2 stopped for the red light when it was struck from behind by Vehicle 1.

Investigation at the scene revealed that the driver of Vehicle 1 was an inexperienced new driver with a probationary license. She stated that as she was slowing for the light, she believed she was pressing the brake pedal hard enough to stop, but apparently was not applying enough force to stop in time. As a result, Vehicle 1 collided into the rear of Vehicle 2. Vehicle 1 was determined to be at fault for the collision.

No injuries were reported at the scene. No motor vehicle summonses were issued. The father of the driver for Vehicle 1 was also on scene. Both vehicles sustained moderate damage, but still remained operable.

146. Officer's Signature Christopher Geskey	147. Badge # 184	148. Reviewer Joshua A Jenssen	Badge # 225	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2018-00041794

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Christopher Geskey

Officer's Signature

184

Badge Number