

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2018-00042435			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 1 was traveling west bound on Rt. 88 when it crossed over the center line, into the east bound lane, continue onto the east bound shoulder, strike the curb on the east bound side of the road and into a utility pole, #JC279. After striking the pole, vehicle 1 spun 180 degrees and came to rest on the lawn of 2195 Rt. 88, causing damage to the landscaping. Driver 1 stated that while traveling west on Rt. 88, he was attempting to find his cell phone which he had dropped between the seat and center console. While trying to get the phone, he took his attention off the road and did not notice that his vehicle had veered into the east bound lane until the time of impact with the utility pole. Driver 1 was found to be at fault for the crash as he had failed to keep his attention on the roadway and for failing to maintain his lane. Driver 1 was issued the following summons: #T156660 for Careless Driving 39:4-97, #T157241 for Failure to Maintain Lane 39:4-88b and #T157242 for Failure to exhibit a valid Insurance card 39:3-29c. Later investigation found that the force of the impact dislodged the under ground power lines running from the utility pole to 2195 Rt. 88, causing the electric meter to be damaged and disconnected from the building further causing a total power loss to the Foot and Ankle Associates Office.


146. Officer's Signature Raymond F LaPoint	147. Badge # 222	148. Reviewer Sandra Naiduk	Badge # 195	149. Case Status ☐ Pending ☒ Complete
---	---------------------	--------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2018-00042435

144 Crash Diagram (NOT TO SCALE)

○ Indicate North



Raymond F LaPoint

222