

New Jersey Police Crash Investigation Report												Case Number 2018-00035181			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 2 was stopped at a yield sign on the ramp from RT 70 e/b to Jack Martin Blvd. waiting for traffic to clear. Vehicle 1 was stopped behind Vehicle 2. Vehicle 2 started forward but was forced to stop again for oncoming traffic. Vehicle 1 started forward along with Vehicle 2 but failed to stop again, and crashed into the rear of Vehicle 2.

Driver 1 stated he was stopped behind Vehicle 2 and observed Vehicle 2 start forward from the ramp onto Jack Martin Blvd. Driver 1 advised traffic appeared to be clear and he thought Vehicle 2 would continue forward, so he too started forward. Driver 1 stated Vehicle 2 then suddenly stopped in front of him and he was unable to stop in time to avoid the collision.

Driver 2 stated she started forward to merge onto Jack Martin Blvd when some of the oncoming traffic in the left and center lanes began to shift into the right lane in front of her, forcing her to stop again.

No injuries were reported by either party and both vehicles were driven from the scene.

146. Officer's Signature Daniel P Testa	147. Badge # 0265	148. Reviewer Joshua A Jenssen	Badge # 225	149. Case Status ☐ Pending ☒ Complete
--	----------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2018-00035181

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Daniel P Testa

Officer's Signature

0265

Badge Number