

New Jersey Police Crash Investigation Report												Case Number 2018-00032646			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 2 was traveling west through the parking lot of 425 Jack Martin Blvd. when it was struck by vehicle 1 who

was attempting to make a left hand turn. Driver 1 stated that after stopping at the stop sign and seeing no

approaching traffic, she proceeded to make the turn and struck vehicle 2 who she did not initially see

approaching from the east. She further stated that she is familiar with the parking lot and knows that east bound

vehicles often travel at higher than normal speeds around a curve and she was partially distracted while checking

for eastbound traffic prior to making the left turn. Driver 2 stated that she was traveling west and was suddenly

struck by vehicle 1. Driver 1 was found to be at fault for the crash as she failed to observe and stop for

oncoming traffic before entering the roadway.


146. Officer's Signature Raymond F LaPoint	147. Badge # 222	148. Reviewer Jason M Matthews	Badge # 210	149. Case Status ☐ Pending ☒ Complete
---	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2018-00032646

144 Crash Diagram (NOT TO SCALE)

○ Indicate North



Raymond F LaPoint

222