

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2018-00035422			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 2 stopped at the stop sign, Burrsville Road southbound at Route 88. Vehicle 1 stopped directly behind Vehicle 2.

Driver 2 stated she was stopped, waiting for traffic to clear when she was struck from behind by Vehicle 1.

Driver 1 stated she was stopped directly behind Vehicle 2, waiting for Vehicle 2 to pull onto Route 88.

Driver 1 stated her foot slipped off the brake pedal and began to roll forward. Before she could reapply the brake, Vehicle 1 struck the passenger side rear of Vehicle 2. Driver 1 advised Vehicle 1 was a loaner car from Lakewood Motors LLC and that there was preexisting damage to the front of the vehicle when it was given to her.

She could not see any new damage to the vehicle.

146. Officer's Signature John C Boronkas	147. Badge # 165	148. Reviewer Robert A Hine	Badge # 158	149. Case Status ☐ Pending ☒ Complete
---	---------------------	--------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2018-00035422

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



John C Boronkas

Officer's Signature

165

Badge Number