

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report											Case Number 2018-00002850				Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Investigation at the scene revealed: The driver of vehicle 1 traveled North on Burrsville Road and was approximately 200 feet South from the intersection of Jack Martin Blvd. / Burrsville Rd. The accident occurred when the driver of vehicle 1 drove into a hole in the middle of the roadway on Burrsville Rd. The front and rear right tires of vehicle 1 had damage which caused the tire to become flat. There were no injuries reported while at the scene, and the vehicle was moved prior to police arrival.

I spoke to driver 1 on scene and she stated the following:

Driver 1 traveled north on Burrsville Road near the intersection with Jack Martin Boulevard. A hole in the roadway suddenly appeared and the driver was unable to avoid it. The front and rear passenger side tire drove into the hole which caused the tires to become flat.

*County was notified of the unsafe road conditions on 01/13/2018.

146. Officer's Signature Kevin A Docherty	147. Badge # 275	148. Reviewer Robert A Hine	Badge # 158	149. Case Status ☐ Pending ☒ Complete
--	---------------------	--------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2018-00002850

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Kevin A Docherty

Officer's Signature

275

Badge Number