

New Jersey Police Crash Investigation Report												Case Number 2018-00003729			Page 2 of 4	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 1 was traveling on Route 88 east attempting to make a left onto Olden Street. Vehicle 2 was traveling on Route 88 west going straight through the intersection at Olden Street. Vehicle 1 turned in front of vehicle 2 and both vehicles subsequently collided within the intersection.

Driver 1 stated she was traveling on Route 88 east attempting to make a left turn onto Olden Street. She observed vehicle 2 traveling towards her on Route 88 west and believed she had enough time to turn in front of vehicle 2.

Driver 1 stated that while she was making her turn she was struck by vehicle 2.

Driver 2 stated she was traveling on Route 88 west approaching the intersection at Olden Street. Driver 2 stated she observed vehicle 1 start to turn in front of her and she attempted to avoid a collision by swerving towards the right but was unable to avoid it. Driver 2 stated vehicle 1 struck her vehicle as she was traveling straight through the intersection.

I spoke to a witness on scene who confirmed what driver 2 stated and a witness statement form was completed.

146. Officer's Signature Michael A DeFluri	147. Badge # 270	148. Reviewer James J Kelly	Badge # 233	149. Case Status ☐ Pending ☒ Complete
---	---------------------	--------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Description

Police Dept: Brick Police Code: 01
Station: Case No: 2018-00003729

145 Crash Description

Investigation revealed that the cause of the crash was driver 1 making an improper left turn and failing to yield to vehicle 2 which was driving straight through the intersection.

Brick Police EMS responded to the scene due to airbag deployment in vehicle 2 to check driver 2. Driver 2 refused treatment with first aid.

Michael A DeFluri


270

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2018-00003729

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Michael A DeFluri

Officer's Signature

270

Badge Number