

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2017-00084067			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

On scene investigation revealed that vehicle 1 and vehicle 2 were traveling north on Jack Martin Blvd in the area of 515 Jack Martin Blvd. Vehicle 2 began slowing down when vehicle 1 was unable to stop in enough time resulting in the collision between both vehicles. The collision occurred approximately 500 feet south of Green Grove Rd.

Driver 1 stated he was traveling west on Jack Martin Blvd when vehicle 2 had suddenly slowed down in an effort to make a left turn and due to the road surface condition was unable to stop. Prior to the collision it had rained a majority of the morning and caused the roads to become wet. Driver 1 did not report any injuries on scene and vehicle 1 had minor front end damage consisting of dents and scratches.

Driver 2 stated she was approaching the lot to Ocean Monmouth Care but had missed the entrance. She proceeded to the next lot and began slowing down to make a left turn but was struck by vehicle 1. Driver 2 did not report any injuries on scene and vehicle 2 had minor rear end damage consisting of dents and scratches.

See diagram for further detail.

146. Officer's Signature Glen Pacyna	147. Badge # 0287	148. Reviewer Joshua A Jenssen	Badge # 225	149. Case Status ☐ Pending ☒ Complete
---	----------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2017-00084067

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Glen Pacyna

0287