

NJTR-1 (Rev. 01/17)

New Jersey Police												Case Number			Page <u>2</u> of <u>4</u>		
Crash Investigation Report												2021-00071927					
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death			
E F G H I J																	

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 1 was parked facing west in the parking lot of Speedway Gas, at the gas pump. Vehicle 2 was backing up in front of Vehicle 1 traveling east. Vehicle 1 did not stop in time and backed into Vehicle 2.

In speaking with the driver of Vehicle 1, he stated he was pulling into the gas station to get gas. Vehicle 2 was already parked getting gas. Vehicle 1 pulled up in front of Vehicle 2 and started to back up so that they could also get gas. Driver 1 stated he put the vehicle in reverse and without using any gas let the vehicle start to slowly back up. As he was backing up he stated he was at the most going as fast as you would be walking, when he struck Vehicle 2's bumper with the rear of his vehicle.

In speaking with the driver of Vehicle 2, he stated he was parked in the parking lot with his vehicle off and sitting in the driver seat of vehicle. Driver 2 stated he saw Vehicle 1 backing up and according to him, Vehicle 1 "floored it" and rammed into the front of his vehicle. Driver 1 stated he was able to brace for the vehicle and when his vehicle was struck, the person who was filling up his vehicle stated his vehicle was pushed back two feet. Driver 2 also stated he was able to brace for the impact and when the vehicle was struck, his left shoulder got pushed back and he was feeling a complaint of pain. Driver 2 also stated his windshield was also cracked due

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Erik Ryan Talty	303	Charles P Kelly	241	☐ Pending ☒ Complete

New Jersey Police Crash Investigation Report
Motor Vehicle Crash DescriptionPolice Dept: Brick Police Code: 01Station: — Case No: 2021-00071927

145 Crash Description

to the force of being struck. Driver 2 was checked out by EMS but refused further medical attention.

Vehicle 1 had no damage to the rear of the vehicle and Vehicle 2 had a minor bend in the license plate and license plate holder. There were no skid marks where Vehicle 2 was parked. One of the employee's stated Vehicle 1 was slowly backing up and struck Vehicle 2. The windshield also appeared to be previously hit by a small rock.

Based on the statements made and the facts of my investigation, Vehicle 1 is at fault for the crash.

Erik Ryan Talty

303

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01

Station: Case No: 2021-00071927


144 Crash Diagram (NOT TO SCALE)

○ Indicate
North

Speedway Store
(1672 Route 88)



Not To Scale



Route 88

Erik Ryan Talty

Officer's Signature

303

Badge Number