

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2017-00078311			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 2 was stopped in traffic. Route 70 e/b approximately 500 feet west of the intersection with Van Zile Road.

Vehicle 2 was traveling in the middle lane at the time. Vehicle 1 was traveling behind Vehicle 2. Vehicle 1 failed to stop and struck Vehicle 1, causing damage. No injuries were reported on scene. Both vehicles were moved from the point of impact to the shoulder of the road prior to Police arrival.

Driver 1 stated that prior to this crash, she was blinded by sun glare, and did not notice that Vehicle 2 was stopped in front of her vehicle until it was too late.

Driver 2 stated that prior to this crash, she was unaware that Vehicle 1 was traveling behind her vehicle.

Investigation on scene revealed that the pre-crash actions of Vehicle 1/Driver 1 caused this crash to occur.


146. Officer's Signature John E Turrin	147. Badge # 199	148. Reviewer Jason M Matthews	Badge # 210	149. Case Status ☐ Pending ☒ Complete
---	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2017-00078311

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



John E Turrin

Officer's Signature

199

Badge Number