

118a	09
118b	20
119a	25
119b	—
120a	01
120b	—
121a	01
121b	—
122	01
123	03
124	00
125	04
126a	26
126b	—
126c	—
126d	—
126e	26
127a	28
127b	—
127c	—
127d	—
127e	28
128	36
129	12
130	12
131	06
132	06
133	04
134	03

[illegible]

New Jersey Police
Crash Investigation Report

Case Number

6186-17

Page 2 of 2

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death
E														
F														
G														
H														
I														
J														

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

- RT. 88 -

V-2

V-1

LAUREL HEIGHTS PLAZA

1929 RT. 88

145. Crash Description/Narrative

VEHICLE 2 WAS TRAVELING WEST ON RT. 88. VEHICLE 1 WAS TRAVELING WEST ON RT. 88. BEHIND VEHICLE 2. THE DRIVER OF VEHICLE 2 STATE SHE STOPPED TO MAKE A LEFT TURN INTO THE LAUREL HEIGHTS PLAZA, 1929 RT 88, AND WAS REARENDED BY VEHICLE 1 WHILE WAITING TO MAKE THE LEFT TURN. THE DRIVER OF VEHICLE 1 STATED THAT WHILE TRAVELING WEST ON RT. 88 HE LOOKED DOWN TO ADJUST HIS CAR SEAT AND WHEN HE LOOKED UP VEHICLE 2 WAS STOPPED TO TURN AND HE STRUCK VEHICLE 2. UPON COMPLETION OF MY INVESTIGATION I FOUND VEHICLE 1 TO BE AT FAULT. THERE WEREN'T ANY REPORTED INJURIES FROM EITHER DRIVER ON SCENE.

146. Officer's Signature

[Signature]

147. Badge #

236

148. Reviewer

[Signature]

Badge #

229

149. Case Status

☐ Pending ☒ Complete