

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2022-00023844			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle #2 was traveling west on Rt. 88 approaching the intersection of Clay Ave. Vehicle #1 was attempting to

turn left from Clay Ave onto Rt. 88 eastbound. Vehicle #1 pulled into the intersection in front of Vehicle #2.

Driver #2 stated that he was traveling west on Rt. 88 when Vehicle #1 pulled out in front of him. He stated that

he was unable to stop in such a short distance and struck the side of Vehicle #1.

Driver #1 stated that he was stopped at the stop for Clay Ave and Rt. 88. He stated he looked before attempting

to make a left turn and believed that the road was clear. After pulling out onto the roadway he felt Vehicle #2

strike the side of his UPS truck.

After my investigation I have determined that Driver #1 is at fault for the incident.


146. Officer's Signature Mark Hentges	147. Badge # 288	148. Reviewer Marc C Alexander	Badge # 216	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2022-00023844

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Mark Hentges

Officer's Signature

288

Badge Number