

New Jersey Police Crash Investigation Report

Police Dept: _____ Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: _____ Case No: **2016-00031349**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
A	83	84	85	86	87	88	89	90	91	92	93	94	95	
L														
I														
N														
V														
O														
L														
V														
E														

135 Crash Description

Vehicle #1 was negotiating the curve on Rt 88 Eastbound approximately 200 feet East of Laurel Brook Dr. The driver of vehicle #1 lost control of the vehicle, and she attempted to correct her course. She overcompensated, causing vehicle #1 to leave the roadway to the right, travel over the curb, and collide into Verizon utility pole #BT 184BK with the driver's side of the vehicle. The utility pole intruded approximately 1.5 feet into the passenger compartment of the vehicle on the driver side, entrapping Driver #1.

Brick Township Fire responded to assist in extricating Driver #1. Driver #1 was removed from the vehicle prior to the arrival of Brick Township Fire, and was transported to Ocean Medical Center by Lakewood EMS.


Driver #1 was issued the following motor-vehicle Summonses: E16-3199 Failure to Use Car Seat for Child Under 8 years 39:3-76.2a, and E16-3200 Careless Driving 39:4-97.

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: _____ Code: 01-Municipal Police

Station: _____ Case No: 2016-00031349



08724