

New Jersey Police Crash Investigation Report												Case Number 2022-00039790			Page 2 of 4	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 1 (V1) and Vehicle 2 (V2) were traveling eastbound on Route 88 just past Post Road when they made contact

in a same direction side-swipe. V1 was traveling in the right lane and V2 was traveling in the left lane. No

injuries reported on scene.

The driver of V1 stated she was in the right lane when she attempted to move into the left lane due to the merge

ahead and crashed into the back right side of V2. Driver of V1 stated she did not see V2 while attempting to make

a lane change.

The driver of V2 stated she was traveling eastbound on Route 88 in the left lane when V1 started to merge into her

lane making contact with her vehicle.

V1 and V2 sustained minor damage and were driven off the scene.

Due to my observations, V1 was listed at fault for this crash for improper lane change and driver inattention.

146. Officer's Signature Trevor Jacob Sherman	147. Badge # 327	148. Reviewer Joshua A Jenssen	Badge # 225	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Description

Police Dept: Brick Police Code: 01

Station: Case No: 2022-00039790

145 Crash Description

BWC footage available.

Trevor Jacob Sherman

327

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police

Code: 01

Station: —

Case No: 2022-00039790

144 Crash Diagram (NOT TO SCALE)




State
Highway
88



NOT TO SCALE



Post Road



Trevor Jacob Sherman

327