

New Jersey Police Crash Investigation Report

Police Dept: _____ Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **Brick Police**Case No: **2016-00019875**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
A	83	84	85	86	87	88	89	90	91	92	93	94	95	
B														
C														
D														
E														

135 Crash Description

Vehicle #1 was traveling West on Rt 88 West approaching Jack Martin Blvd, behind Vehicle #2. Vehicle #2 stopped for a traffic signal that was changing to red at the intersection and Vehicle #1 crashed into Vehicle #2's rear bumper.

The driver of Vehicle #1 stated, as he was traveling west behind Vehicle #2, on Rt 88 that Vehicle #2 stopped abruptly at a green traffic signal causing him to skid on the wet pavement and crash into Vehicle #2's rear. Driver #1 and his passengers all refused medical attention.

The driver of Vehicle #2 stated, she was traveling west on Rt 88 West and noticed the traffic signal at the intersection with Jack Martin Blvd had turned amber and she began to brake. In doing so, Vehicle #1 crashed into her rear bumper. The driver of Vehicle #2 complained of neck pain and was transported to Ocean Medical Center.

The driver of Vehicle #1 showed signs of being impaired. Field sobriety tests were given by Ptl Farnkopf #230 and Ptl Scott #266. The driver of Vehicle #1 was subsequently arrested for DUI (See Ptl Farnkopf's #230 and Ptl Scott's #266 report with this same case number).

An additional summons of following to closely (39:4-89) was also issued (T 152578).
Vehicle #1 was towed by Legacy towing as it was disabled.

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: _____ Code: **01-Municipal Police**

Station: **Brick Police**

Case No: **2016-00019875**

