

New Jersey Police Crash Investigation Report

Police Dept: _____ Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **Brick Police**Case No: **2016-00016957**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
A	83	84	85	86	87	88	89	90	91	92	93	94	95	
L														
I														
N														
V														
O														
L														
V														
E														

135 Crash Description

A motor vehicle crash occurred on Route 88 at the intersection of Burrsville Road.

Driver of Vehicle #1 advised he was attempting to turn left onto Route 88 from Burrsville Road. Driver #1 advised he did not observe Vehicle #2 travel west on Route 88.

Driver of Vehicle #2 stated she was traveling west on Route 88. Driver #2 advised Vehicle #1 pulled out from Burrsville Road. Driver #2 stated the vehicles collided at the intersection of Route 88 and Burrsville Road.

Driver of Vehicle #3 advised he observed the collision between Vehicle #1 and Vehicle #2. Driver #3 stated he braked and came to a full stop when Vehicle #2 struck him on the front driver side bumper.

Both the driver and passenger of Vehicle #1 had complaint of pain. Driver #1 advised he had pain all over his body and the passenger stated she was having problems breathing and her chest hurt. Both the driver and passenger were transported to Ocean Medical Center via Brick Township Police EMS. Driver #2 had complaint of pain in her knee and neck and was also transported to Ocean Medical Center by Brick Township Police EMS.

There were multiple air bag deployments in both Vehicle #1 and Vehicle #2. Vehicle #1 was towed by Frank's Towing. Vehicle #2 was towed by D and L Towing.

Vehicle #1 failed to observe Vehicle #2 traveling west on Route 88 prior to turning onto Route 88 from Burrsville Road, causing a collision. Vehicle #1 and #2 collided and Vehicle #2 traveled west on Route 88 striking Vehicle #3 on the front driver side front bumper.

Driver #1 is the at fault driver for driver inattention and failure to yield right of way. Driver #1 was issued the following summons: 1506 T 152152 for 39:4-97, Careless driving.

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: _____ Code: 01-Municipal Police

Station: Brick Police

Case No: 2016-00016957

