

New Jersey Police Crash Investigation Report Motor Vehicle Crash Description	Police Dept: Brick PD Code: 01-Municipal Police Station: --- Case No: 2012-00025390
---	--

(Refer to vehicle by number)

G														
	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	
ALL INVOLVED	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants - If Deceased, Date & Time of Death

135 Crash Description

Vehicle #1 was traveling east on Rt. 88 and vehicle #2 was traveling west on Rt. 88. As both vehicles approached a curve in the roadway, vehicle #1 continued straight and crossed into the on coming traffic lane. Vehicle #1 collided into the left rear side of vehicle #2 causing vehicle #2 to leave the roadway striking a concrete retaining wall. After colliding into the concrete wall, vehicle #2 became airborne, spinning through the air and landing in the parking lot entrance of The Tuscany Restaurant upside down. Vehicle #1 spun an unknown amount of times and collided into the same concrete retaining wall at The Tuscany Restaurant.

Driver #1 complained of minor injuries to her finger and mouth. Driver #2 was stuck in his vehicle which was laying on the driver side roof. Fire and EMS Personal had to cut him from the vehicle. Driver #2 was transported to Jersey Shore Medical Center where he was treated for cuts to his head and other unknown injuries.

While at the scene, driver #1 was upset and concerned about driver #2. She admitted that she had been drinking at the Miracle Bar in Toms River, NJ during the morning hours of the day. She said that she had consumed 4 vodka and cokes prior to driving as well as a Percocet, a Celexa and a Soma, all which have been prescribed by her doctor and taken daily. She was transported to Brick Hospital where she was taken into custody for DWI and voluntarily provided blood and urine samples. After being issued summonses for 39:4-50, DWI-T124685; 39:4-96, Reckless Driving-T-124686; 39:4-97, Careless Driving-T-124687; and 39:4-88B, Failure to Maintain Lane-T-124688, she was released in accordance with John's Law (see arrest report for further details).

The debris from both vehicles were in the westbound lane, north side shoulder and on the front property of the Tuscany Restaurant. There was little to no debris in the east bound lane. Driver #1 stated that she thought vehicle #2 had pulled out in front of her vehicle and that the collision occurred in her lane of travel.

Driver #2 stated that he observed the vehicle in front of him, also traveling west, swerve as vehicle #1 started to cross over the double yellow center lane marker into his lane. Driver #2 attempted to move to the right but was struck by vehicle #1. Numerous witnesses had the same account of the collision as driver #2 (see witness statement forms).

GeorgeWilliams180

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: Brick PD

Code: 01-Municipal Police

Station: ---



Case No: 2012-00025390

134 Crash Diagram (NOT TO SCALE)

○ Indicate North

Landscape Retaining Wall/Concrete

Tuscany Restaurant
1490 Rt.88



George

Williams

180