

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2020-00059897			Page 2 of 4	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
	02	01	01	—	51	M	—	—	—	11	04	—	—	MOHAMMED M ISLAM 336 SAWMILL RD BRICK TOWNSHIP NJ 08724		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Prior to arrival both vehicles were moved from Route 70 west bound approximately 100 feet east of the intersection with Olden Ave to a near by parking lot.

Driver #2 stated he was stopped in the left lane of travel of Route 70 westbound waiting for the traffic signal to turn green. He said while he was stopped, vehicle #1 collided into the rear bumper of vehicle #2 causing damage to the entire rear bumper.

Driver #1 said she was traveling directly behind vehicle #2 and was also stopped waiting for the traffic signal to change from red to green. She said when the traffic signal turned green she took her foot off the brake and started to roll forward anticipating vehicle #2 to proceed forward as well. Driver #1 said when vehicle #2 did not move, the front bumper of vehicle #1 tapped into the rear bumper of vehicle #2.

On scene investigation determined the following:

The two screws securing vehicle #1's front license plate left two screw impressions on the rear bumper of vehicle

146. Officer's Signature Richard J Zimmerer	147. Badge # 272	148. Reviewer Anthony S DeMaio	Badge # 194	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash DescriptionPolice Dept: Brick Police Code: 01Station: — Case No: 2020-00059897

145 Crash Description

#2. Driver #2 insisted that the damage to the rear left upper bumper area and right rear upper bumper area was also caused from this crash. Since the damage driver #2 was claiming was not consistent with the crash, I asked driver #2 if this vehicle was involved in any other accidents and if this could possibly be pre existing damage.

Driver #2 said yes it was pre existing damage, but then he pointed to another crack in the left rear upper bumper area directly above it and said he never saw this damage before. I was able to locate an accident that occurred in this jurisdiction on 10/24/2015 involving the same Honda civic bearing NJ registration. C68emx, but was unable to access any other details pertaining to the details of that crash.

The only damage that was consistent with this crash was the two license plate screw impressions. Vehicle #1 did not have any damage.

Richard J Zimmerer

Officer's Signature

272

Badge Number

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram


Police Dept: Brick Police Code: 01
Station: Case No: 2020-00059897

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North

Olden Street

NOT TO SCALE



Highway 70

Richard J Zimmerer

Officer's Signature

272

Badge Number