

New Jersey Police Crash Investigation Report												Case Number 2021-00036801			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle #1 was stopped on the shoulder of Jack Martin Blvd (N/B), approximately 200 feet north of Quadara Blvd. Vehicle #2 was traveling north on Jack Martin Blvd when Vehicle #1 attempted to merge back into traffic, sideswiping Vehicle #2.

The driver of Vehicle #1 stated that she pulled onto the shoulder of Jack Martin Blvd as she believed she was lost. She added that when she decided to merge back into the north bound lane again, she saw Vehicle #2 coming. The driver of Vehicle #1 explained that she thought Vehicle #2 was slowing to allow her back into the lane. When she started back into traffic, she stated she crashed into the side of Vehicle #2.

The driver of vehicle #2 stated that she was traveling north on Jack Martin Blvd and was about to pass Vehicle #1. She added that as she passed, Vehicle #1 started into her lane and crashed into her vehicle.

No injuries were reported on scene.

146. Officer's Signature Robert F Scelfo	147. Badge # 189	148. Reviewer Charles P Kelly	Badge # 241	149. Case Status ☐ Pending ☒ Complete
---	---------------------	----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram



Police Dept: Brick Police Code: 01

Station: Case No: 2021-00036801

144 Crash Diagram (NOT TO SCALE)

 Indicate North

Jack Martin Blvd



Robert F Scelfo

Officer's Signature

189

Badge Number