

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2019-00077526			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Upon arrival, both vehicles were out of the roadway and parked on Younger St.

Driver #1 stated he was traveling west on Route 88 directly behind vehicle #2. Driver #1 stated vehicle #2 stopped short and when driver #1 applied his brakes, vehicle #1 started to skid and subsequently the front of vehicle #1 collided into the rear bumper/ fender of vehicle #2.

Driver #2 stated she was stopped on Route 88 westbound for a school bus that had its warning lights on picking up kids in the area of Younger St. Driver #1 said there were several other cars stopped in front of her vehicle for the school bus as well. Driver #2 felt the impact of the collision but did not observe it.

On Scene investigation determined Driver #1 to be at fault for following too closely and also failed to operate a vehicle safely in the inclement weather conditions.

Driver #2 complained of neck pain but refused medical at this time.

146. Officer's Signature Richard J Zimmerer	147. Badge # 272	148. Reviewer Joshua A Jenssen	Badge # 225	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram



Police Dept: Brick Police Code: 01
Station: Case No: 2019-00077526

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North

RT 88

YOUNGER ST



Richard J Zimmerer

Officer's Signature

272

Badge Number