

NJTR-1 (Rev. 01/17)

New Jersey Police												Case Number			Page <u>2</u> of <u>4</u>		
Crash Investigation Report												2020-00041980					
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death			

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

A motor vehicle collision occurred on July 7th, 2020, at the location of Jack Martin Boulevard in front of the parking lot of The Chelsea at Brick (458 Jack Martin Blvd).

The Driver of Vehicle 1 stated he made a right turn out of the parking lot located at Complete Care (475 Jack Martin Blvd) onto Jack Martin Blvd south. Driver 1 said he looked left and right before making his turn. Driver 1 made the right turn onto the street but failed to observe Vehicle 2 making a left turn. Vehicle 1 struck Vehicle 2 in the rear.

The Driver of Vehicle 2 stated he was traveling southbound on Jack Martin Blvd when he stopped to make his left turn into the parking lot of The Chelsea at Brick. Driver 2 turned his blinker on, approached the turn location, and waited for opposing traffic to pass before making the turn. Driver 2 said he then felt his vehicle get struck from behind.

Vehicle 1 had damage to the front driver-side corner. The bumper had significant damage. The steering wheel airbag was activated and deployed.

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Brennan James Lanni	0307	Joseph L Rossi	240	☒ Pending ☐ Complete

New Jersey Police Crash Investigation Report
Motor Vehicle Crash DescriptionPolice Dept: Brick Police Code: 01Station: — Case No: 2020-00041980

145 Crash Description

Vehicle 2 had damage to the rear passenger-side corner. The bumper, trunk, and right brake light had significant damage.

While on scene, there were no reported injuries and both parties refused medical treatment.

Through my investigations, I determined Driver 1 to be the at fault driver. Driver 1 was inattentive and failed to observe Vehicle 2 attempt to make a left turn ahead of him. Vehicle 1 then collided with Vehicle 2, resulting in a rear end.

Driver 1 and Driver 2 requested assistance with acquiring a tow. Both vehicles were towed by D&L Towing.

It should be noted that both vehicles were removed from the roadway prior to my arrival. A debris field was observed at the reported collision site that is consistent with what was reported.

Body-worn Cameras were activated and were recording during this incident.

Brennan James Lanni

0307

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2020-00041980

144 Crash Diagram (NOT TO SCALE)




Diagram Not
To Scale

The Chelsea at Brick Parking Lot

Jack Martin BLVD

Complete Care Parking Lot



Brennan James Lanni

0307