

New Jersey Police Crash Investigation Report												Case Number 2018-00068497			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Crash investigation reveals a two vehicle, right angle crash. Vehicle 1 was stopped at for a marked stop sign on Washington Drive awaiting to turn left onto Route 88 W. Vehicle 2 was traveling west on Route 88.

The driver of vehicle 1 stated as he began turning left onto Route 88 W from Washington Drive, his vehicle crashed into the left middle side of vehicle 2. The driver of vehicle 1 stated he thought the roadway was clear as he was making the turn onto Route 88 W and stated he didn't see vehicle 2 until he started making his turn. The driver of vehicle 2 stated he was traveling west on Route 88 when he observed vehicle 1 turn left onto Route 88 W and crash into his vehicle.

No injuries were reported and both vehicles sustained moderate damage. Vehicle 1 was driven from the scene. Vehicle 2 was towed from the scene by Brick Performance Towing Company. No injuries were reported. The driver of vehicle 1 is at fault for the crash and was issued summonses for 39:3-10 (1506-T-159700) and 39:4-97 (1506-T-159681). The registered owner of vehicle 1 will be issued a summons for 39:3-37.1B (1506-T-159682).


146. Officer's Signature Thomas P Caulfield	147. Badge # 235	148. Reviewer Austin E Kenny	Badge # 224	149. Case Status ☐ Pending ☒ Complete
--	---------------------	---------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2018-00068497

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Thomas P Caulfield

Officer's Signature

235

Badge Number