

New Jersey Police Crash Investigation Report												Case Number 2018-00063422			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle two was stopped at the intersection of Burrsville Road and Rt 88, facing South, waiting for traffic.

Vehicle one was stopped directly behind vehicle two on Burrsville Road. Vehicle one rolled into vehicle two, striking the rear passenger side bumper with the front driver's side bumper of vehicle one. Driver two advised that vehicle one failed to stop and struck vehicle two. Driver one advised that he rolled into vehicle two when he thought driver two was going to accelerate. I observed a minor dent on the passenger side rear bumper and the bumper was pushed slightly out of place on vehicle two. Additionally vehicle two may have sustained a small crack in the paint by the passenger side tail light as a result of the accident. Vehicle one showed no signs of damage. Driver one confirmed there is no new damage to vehicle one. Both drivers advised they are not injured. Driver one was issued summons T-160545 for careless driving. Both vehicles were driven from the scene.

146. Officer's Signature John M Gannaio	147. Badge # 234	148. Reviewer Michael N Drew	Badge # 169	149. Case Status ☐ Pending ☒ Complete
--	---------------------	---------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2018-00063422

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



John M Gannaio

Officer's Signature

234

Badge Number