

New Jersey Police Crash Investigation Report												Case Number 2018-00057363			Page 2 of 4	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle #2 was stopped in traffic, south on Burrsville Rd. approximately 40 feet north of the intersection of Rt. 88.

Vehicle #1 was starting in traffic, south on Burrsville Rd., directly behind vehicle #2.

Driver #1 believed vehicles in front of him were starting to move forward, and he began accelerating prior to vehicle #2 moving, causing the front bumper of his vehicle to collide with the rear bumper of vehicle #2. Minor cracks and holes were visible on the rear bumper of vehicle #2, and no damage was observed on the front bumper of vehicle #1. It appeared that the two bolts which secure the front license plate to vehicle #1 were what caused the damage to vehicle #2.

Vehicles were moved from the roadway prior to my arrival.

Driver#1 was issued motor-vehicle Summons# T-160334 for Careless Driving 39:4-97.

146. Officer's Signature Joseph L Rossi	147. Badge # 240	148. Reviewer Jason M Matthews	Badge # 210	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Description

Police Dept: Brick Police Code: 01
Station: Case No: 2018-00057363

145 Crash Description

***Vehicle #1 is insured, out-of-state, by Geico (Code#100) 1 Geico Plaza, Washington D.C. 20076 (1-800-841-3000).

Joseph L Rossi

Officer's Signature

240

Badge Number

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2018-00057363

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Joseph L Rossi

Officer's Signature

240

Badge Number