



Kingston Volunteer Fire Company #1

South Brunswick Fire District #3
6-8 Heathcote Road, Kingston, New Jersey 08528

INCIDENT

Incident Number 24-300119	Incident Date 05/14/2024	NFIRS Number 0000139	Incident Type (735) - Alarm system sounded due to malfunction
FDID 12321	Station Kingston 24	Shift M-F Evening Time/Weekends	District South Brunswick Dist #3
Initial Dispatch Code 			
Alarms 	Working Fire? 	COVID-19 was a factor 	Critical Incident Team
Temporary Resident Involvement 			
Hazardous Materials Released 			
Action Taken 1 (81) - Incident command			
Action Taken 2 (86) - Investigate			

AID

Aid Given/Received
(N) - None

LOCATION

Location Type
(1) - Street address

Address
4385 Rt 1 North, Princeton, New Jersey, 08540

Cross Street, USNG, or Directions 	Latitude 	Longitude 	Census Tract
---	------------------	-------------------	----------------------

Detector Alerted Occupant

Property Use
(449) - Hotel/motel, commercial

Mixed Use

TIMES

PSAP Received 	Dispatch Notified Time 	Alarm Time 00:50:00, 05/14/2024
Arrival Time 00:57:00, 05/14/2024	Water on Fire Time 	At Patient Time

 TIMES

Loss Stop Time	Controlled Time	Last Unit Cleared Time
		01:26:00, 05/14/2024
Total On Scene Time	Total Incident Time	
0 hrs 29 mins 0 sec	0 hrs 36 mins 0 sec	

 COUNTS

Counts Include Aid Received?

No

Suppression:		EMS:		Other:	
Apparatus	Personnel	Apparatus	Personnel	Apparatus	Personnel
2	6	0	0	2	2

 PERSON/OWNER

 AUTHORIZATION

Report Writer:			
Name	Employee Number	Assignment	Authorization Date
Weissman, Rob	151		05/14/2024
Officer in Charge:			
Name	Employee Number	Assignment	Authorization Date
Weissman, Rob	151		05/14/2024
Quality Control:			
Name	Authorization Date		
Coniglio, Thomas	07/01/2024		

 INCIDENT NARRATIVE

Dispatched for a fire alarm. enroute was advised alarm was coming from room 335E243 crew investigated no cause for the alarm found. alarm was not able to be reset.SBBFP contacted, SBDFM Kamen advised of situation. occupant in room 355 was relocated to another room. Hampton inn front desk advise to have alarm company respond to make repairs . a fire watch is to be maintained until repairs are made

W Walker for Rr Weissman

Created By: Walker, Bill

 Unit Reports

CHIEF CAR

Use	Responding From	Priority
(0) - Other		
Response Delays		
Dispatch Time	Enroute Time	Arrival Time
00:50:00, 05/14/2024	00:50:00, 05/14/2024	00:57:00, 05/14/2024
At Patient Time	Clear Time	In District Time
	01:26:00, 05/14/2024	

CHIEF CAR

Actions Taken:

Standby

Personnel

John Luck

DEPUTY CHIEF CAR

Use

(0) - Other

Responding From

Priority

Response Delays

Dispatch Time

00:50:00, 05/14/2024

Enroute Time

00:50:00, 05/14/2024

Arrival Time

00:57:00, 05/14/2024

At Patient Time

Clear Time

01:26:00, 05/14/2024

In District Time

Actions Taken:

Incident command

Personnel

Rob Weissman

ENGINE 3

Use

(1) - Suppression

Responding From

Priority

Response Delays

Dispatch Time

00:50:00, 05/14/2024

Enroute Time

00:50:00, 05/14/2024

Arrival Time

00:57:00, 05/14/2024

At Patient Time

Clear Time

01:26:00, 05/14/2024

In District Time

Actions Taken:

Investigate

Person 1: Clark, Timothy

Person 2: Lee, Cheng-Yu

Person 3: Luck, George

Action Taken 1

(58) - Operate apparatus or vehicle

Person 4: Steinfeld, Tyler

ENGINE 5

Use

(1) - Suppression

Responding From

Priority

Response Delays

ENGINE 5

Dispatch Time	Enroute Time	Arrival Time
00:50:00, 05/14/2024	00:50:00, 05/14/2024	00:57:00, 05/14/2024

At Patient Time	Clear Time	In District Time
	01:26:00, 05/14/2024	

Actions Taken:

Standby

Personnel

Hector Arroyo, Austin Brock