



Kingston Volunteer Fire Company #1

South Brunswick Fire District #3

6-8 Heathcote Road, Kingston, New Jersey 08528

INCIDENT

Incident Number 24-3000111	Incident Date 05/05/2024	NFIRS Number 0000129	Incident Type (745) - Alarm system activation, no fire - unintentional
FDID 12321	Station Kingston 24	Shift M-F Evening Time/Weekends	District South Brunswick Dist #3
Initial Dispatch Code 			
Alarms 	Working Fire? 	COVID-19 was a factor 	Critical Incident Team
Temporary Resident Involvement 			
Hazardous Materials Released 			
Action Taken 1 (81) - Incident command			
Action Taken 2 (86) - Investigate			

AID

Aid Given/Received

(N) - None

LOCATION

Location Type

(1) - Street address

Address

4331 Us Rt 1, Monmouth Junction, New Jersey, 08852

Cross Street, USNG, or Directions

Latitude

Longitude

Census Tract

Detector Alerted Occupant

Property Use

(311) - 24-hour care Nursing homes, 4 or more persons

Mixed Use

TIMES

PSAP Received

Dispatch Notified Time

Alarm Time

16:44:00, 05/05/2024

Arrival Time

17:00:00, 05/05/2024

Water on Fire Time

At Patient Time

 TIMES

Loss Stop Time	Controlled Time	Last Unit Cleared Time
		17:34:00, 05/05/2024
Total On Scene Time	Total Incident Time	
0 hrs 34 mins 0 sec	0 hrs 50 mins 0 sec	

 COUNTS

Counts Include Aid Received?

No

Suppression:		EMS:		Other:	
Apparatus	Personnel	Apparatus	Personnel	Apparatus	Personnel
1	4	0	0	1	1

 PERSON/OWNER

 AUTHORIZATION

Report Writer:			
Name	Employee Number	Assignment	Authorization Date
Luck, John	34		05/05/2024
Officer in Charge:			
Name	Employee Number	Assignment	Authorization Date
Luck, John	34		05/05/2024
Quality Control:			
Name	Authorization Date		
Coniglio, Thomas	07/01/2024		

 INCIDENT NARRATIVE

Dispatched for activated fire alarm upon arrival panel showed activated smoke detector on the first floor outside of the sales office. investigation showed no sign of smoke or fire and employees on duty in the area also reported not seeing any smoke. director of maint. jose silva was on scene he was advised to have the detector checked. the alarm was reset and all units cleared. the remote panel at the front door showed the alarm activation but we were unable to silence the alarm or reset it with the key in the on position. deputy fire inspector c taurack was advised of the situation

W Walker for J Luck

Created By: Walker, Bill

 Unit Reports

ENGINE 3

Use	Responding From	Priority
(1) - Suppression		
Response Delays		
Dispatch Time	Enroute Time	Arrival Time
16:44:00, 05/05/2024	16:56:00, 05/05/2024	17:00:00, 05/05/2024
At Patient Time	Clear Time	In District Time
	17:34:00, 05/05/2024	

ENGINE 3

Actions Taken:

Investigate

Person 1: Luck, George

Action Taken 1

(58) - Operate apparatus or vehicle

Person 2: Clark, Timothy

Person 3: Lee, Cheng-Yu

Person 4: Steinfeld, Tyler

CHIEF CAR

Use	Responding From	Priority
(0) - Other		

Response Delays

Dispatch Time	Enroute Time	Arrival Time
16:44:00, 05/05/2024	16:44:00, 05/05/2024	17:00:00, 05/05/2024
At Patient Time	Clear Time	In District Time
	17:34:00, 05/05/2024	

Actions Taken:

Incident command

Personnel

John Luck