

**Passaic Fire Department
(NJ)**Station: **WS**
Shifts Or Platoon: **Tour 2**Location:
**355 HARRISON ST
PASSAIC NJ 07055**Lat/Long:
**N 40° 52' 4.37"
W 74° 7' 51.95"**Zone:
Engine 3 - E3
Location Type: **1 - Street address**Incident Type:
131 - Passenger vehicle fireFDID: **16070**
Incident #: **2024-2796**
Exposure ID: **81193068**
Exposure #: **0**
Incident Date: **08/10/2024**
Dispatch Run #: **24-2796**

Report Completed by:	Martinez , Jorge	ID: 208	Date: 08/10/2024
Report Reviewed by:	Martinez , Jorge	ID: 208	Date: 08/10/2024
Report Printed by:	Failla, Toni	ID: ADMIN	Date: 10/2/2024 Time: 10:55

Structure Type:	Property Use: 900 - Outside or special property, other		
Automatic Extinguishment System Present: ☐	Detectors Present: ☐	Cause of Ignition: Cause undetermined after investigation	
Aid Given or Received: None	Primary action taken: 81 - Incident command		
Additional actions: 10 - Fire control or extinguishment, other , 12 - Salvage & overhaul			
Losses	Pre-Incident Values		
Property:	Property:	Civilian Injuries: 0	Fire Service Injuries: 0
Contents:	Contents:	Civilian Fatalities: 0	Fire Service Fatalities: 0
Total:	Total:	Total Casualties: 0	Total Fire Service Casualties: 0
Total # of apparatus on call: 2		Total # of personnel on call: 6	

NARRATIVE (1)**Narrative Title:** Lt. B.Bautista**Narrative Author:** Bautista, Beda**Narrative Date:** 08/10/2024 21:43:00**Narrative Apparatus ID:** E1**Narrative:**

At 1916 hours, Engine 1 responded to the area of 355 Harrison St. for an auto fire. Upon arrival, members investigated and found a passerby had broken the windows and extinguished the fire prior to Fire Department arrival. Members conducted overhaul and used the water extinguisher to extinguish the smoldering contents. Thermal Imaging Cameras were used and found no signs of extension. FF Wood acted as Arson Investigator and conducted his report on scene. Engine 1 was released by PD who remained on scene to await the arrival of City Tow. Command was terminated and Engine 1 available at 1937 hours. For more information, refer to PD CAD # 2451412. Lt. B.Bautista

NARRATIVE (2)**Narrative Title:** T/Capt. Martinez**Narrative Author:** Martinez, Jorge**Narrative Date:** 08/10/2024 22:07:21**Narrative Apparatus ID:** L1**Narrative:**

At 1916 responded to 355 Harrison St for a reported MVA with a light smoke condition. Upon arrival investigated and found a vehicle fire that was extinguished by a passerby using a fire extinguisher. The vehicle was parked. As the passerby drove past the vehicle he noticed the smoke condition and broke the windows to extinguish the fire. The Fire was in the front passengers seat. The area was overhauled and cooled down with a water can. The area was checked with a TIC for any hot spots. Arson investigator FF Wood on scene conducting investigation. PD remained on scene. Released by command at 1937hours.

T/Capt. Martinez 208

APPARATUS

Fire Controlled Date / Time:		8/10/2024 7:21:00 PM	
Unit	E1	Unit	L1
Type:	Engine	Type:	Truck or aerial
Use:	Suppression	Use:	Suppression
Response Mode:	Lights and Sirens	Response Mode:	()
# of People	3	# of People	3
Alarm	08 /10/2024 19:15:00	Alarm	08 /10/2024 19:15:00
Dispatched	08 /10/2024 19:16:00	Dispatched	08 /10/2024 19:16:00
Enroute	-- / -- / -- -- : -- : --	Enroute	-- / -- / -- -- : -- : --
Arrived	08 /10/2024 19:21:00	Arrived	08 /10/2024 19:21:00
Cancelled	-- / -- / -- -- : -- : --	Cancelled	-- / -- / -- -- : -- : --
Cleared Scene	08 /10/2024 19:37:00	Cleared Scene	08 /10/2024 19:37:00
In Quarters	-- / -- / -- -- : -- : --	In Quarters	-- / -- / -- -- : -- : --
In Service	-- / -- / -- -- : -- : --	In Service	-- / -- / -- -- : -- : --
Number Of People not on apparatus: 0			

FIRE

Acres Burned	None or Less Than One	Acres Burn From Wildland Form	False
Area Of Fire Origin	Operator/passenger area of transportation equipment	Heat Source	Undetermined
Item First Ignited	Undetermined	Fire Is Confined To Object Of Origin	
Type Of Material	Undetermined	Cause Of Ignition	Cause undetermined after investigation
Factor Contributing To Ignition	Undetermined		
Human Factors Contributing	None		
Mobile Property Involve And Type	Not involved in ignition, but burned	Mobile Property Type	Automobile, passenger car, ambulance, race car
Mobile Property Make	Jeep	Mobile Property Year	2007
Mobile Property Model	Commander	License Plate	R36RLC
State	NJ	VIN	1J8HG48P97C632889

ARSON

Agency Name	Agency Address	Agency Phone
	355 Harrison St.	
Case Status	Availability Of Material First Ignited	
	Unknown	
Entry Method	Extent Of Fire Involvement On Arrival	Container
Window – forced or broken	Smoke only showing	
Property Ownership	Initial Observations	Laboratory Used
Private	Entry forced prior to FD arrival	

CUSTOM FIELDS FORM

Is this response related to a Lithium-Ion battery fire / explosion / incident?	UNKNOWN
COVID-19 (Coronavirus) presumptive related incident/response?	NO
Is this CIVIL UNREST / PROTEST / RIOT Related?	NO, this is NOT attributed to a CIVIL UNREST / PROTEST / RIOT situation
Were FIRE HYDRANT(s) blocked at this fire/emergency scene? (If yes, notify police immediately).	No
If this was a restaurant, bar, night club or any other place of gathering, was HOOKAH (or any other tobacco product) being smoked?	NO
Were CO (Carbon Monoxide) levels present?	NO

Member Making Report (Lieutenant Jorge Martinez): _____

Incident Reviewer (Lieutenant Jorge Martinez): _____