



Passaic Fire Department (NJ)

Station: **WS**
Shifts Or Platoon: **Tour 1**

Location:
459 HARRISON ST
PASSAIC NJ 07055

Lat/Long:
N 40° 52' 0.77"
W 74° 8' 5.27"

Zone:
Engine 1 - E1
Location Type: **1 - Street address**

Incident Type:
111 - Building fire

FDID: **16070**
Incident #: **2024-2950**
Exposure ID: **81414555**
Exposure #: **0**
Incident Date: **08/25/2024**
Dispatch Run #: **24-2950**

Report Completed by:	Pilipski , Damien M	ID: 147	Date: 08/25/2024
Report Reviewed by:	Pilipski , Damien M	ID: 147	Date: 08/25/2024
Report Printed by:	Failla, Toni	ID: ADMIN	Date: 10/2/2024 Time: 10:59

Structure Type: Enclosed building		Property Use: 419 - 1 or 2 family dwelling	
Automatic Extinguishment System Present: ☐		Detectors Present: ☐	Cause of Ignition: Unintentional
Aid Given or Received: None		Primary action taken: 81 - Incident command	
Additional actions: 86 - Investigate , 11 - Extinguishment by fire service personnel			
Losses	Pre-Incident Values		
Property:	Property:	Civilian Injuries: 0	Fire Service Injuries: 0
Contents:	Contents:	Civilian Fatalities: 0	Fire Service Fatalities: 0
Total:	Total:	Total Casualties: 0	Total Fire Service Casualties: 0
Total # of apparatus on call: 7		Total # of personnel on call: 19	

NARRATIVE (1)**Narrative Title:** LT. Niessen**Narrative Author:** Niessen, Robert**Narrative Date:** 08/25/2024 13:34:59**Narrative Apparatus ID:** L2**Narrative:**

Ladder 2 responded to 459 Harrison Street on a working structure fire @ 1233. Upon arrival members brought a chainsaw to an overhang over the rear porch and cut holes to expose fire. Engine 1 members extinguished all visible fire in and around the rear porch. Ladder 2 members also stretched six lengths of 1 3/4" hose to the 'Charlie' side second floor window in preparation for fire extension into the house. The fire was placed under control and command released Ladder 2 @ 1305.

LT. Robert Niessen

NARRATIVE (2)**Narrative Title:** Capt. B Rutherford**Narrative Author:** Rutherford, Bart**Narrative Date:** 08/25/2024 14:54:26**Narrative Apparatus ID:** E1**Narrative:**

At 1232 hours responded to 459 Harrison Street on a reported fire, upon arrival E1 made the hydrant on Harrison and Myrtle and laid in. E1 members stretched a 1 3/4 inch line to division two to the short porch roof an extinguished the fire in the roof line. Members performed overhaul, fire placed under control. Released by command at 1349 hours.

NARRATIVE (3)**Narrative Title:** Lt LaPlaca**Narrative Author:** Temporary Lieutenant, Tour 1**Narrative Date:** 08/25/2024 15:03:45**Narrative Apparatus ID:** E4**Narrative:**

Engine 4 responded to 459 Harrison St @ 1232 for a reported structure fire. Upon arrival @ 1236 secured a hydrant at the Wilscot St and placed engine 4 at Myrtle Ave and Harrison St. Members then came in for man power and secured the utilities in the basement. The electric panel breakers were secured for both floors. All members reloaded hose beds for Engine 4 and engine 1. Released by command @ 1344 available.

Lt LaPlaca # 173

NARRATIVE (4)**Narrative Title:** LT. J.IVANICKI**Narrative Author:** Ivanicki, Joseph**Narrative Date:** 08/25/2024 15:54:38**Narrative Apparatus ID:** L1**Narrative:**

At 1232 hrs. L-1 responded to 459 Harrison st. for a reported structure fire. Upon arrival smoke was showing from the first floor rear roof area. L-1 did a search of the first and second floor apts. first before going out to the roof through the kitchen window. We cut and removed the roofing so E-1 could extinguish the fire. We overhauled the area and checked for any extension to the main part of the house but it never got into the house. All members went to rehab before packing up all of our equipment. Command terminated at 1349 hrs.

NARRATIVE (5)**Narrative Title:** Lt. P. O'Connor**Narrative Author:** OConnor, Peter**Narrative Date:** 08/25/2024 17:35:03**Narrative Apparatus ID:** E2**Narrative:**

At 1244 hours responded on 2nd alarm assignment to aforementioned address for a structure fire, Upon arrival E2 released by Command.

No action taken by this company. Available 1255.

Lt. Peter O'Connor #150

NARRATIVE (6)**Narrative Title:** LT J. Goller**Narrative Author:** Goller, Jesse**Narrative Date:** 08/25/2024 16:28:43**Narrative Apparatus ID:** E3**Narrative:**

At 1232 hours Engine 3 responded to 459 Harrison St. for a reported structure fire. Engine 3 responded as the Rapid Intervention Team. The command board was set up across from 459 Harrison St. and members of Engine 3 set up in front of 459 Harrison St as the rapid Intervention Team with tools and RIT bag. Members of Engine 3 set up a 16 foot straight ladder on the read Delta side of the building and assisted Ladder 1 and Engine 1 in opening up the roof and exposing any hot spots. The fire was extinguished and all hoses and tools were repacked for Engine 1 and Engine 4. No injuries reported for Engine 3 and available at 1348 hours.

NARRATIVE (7)**Narrative Title:** BC. Pilipski**Narrative Author:** Pilipski, Damien**Narrative Date:** 08/25/2024 20:43:09**Narrative Apparatus ID:** 93**Narrative:**

Responded to 459 Harrison St. for a reported fire. On arrival Battalion-1 established command and conducted an investigation. Found smoke showing from the C/D corner and confirmed a working fire. An assessment on the scene found that 2 contractors were working on the roof with a torch and accidentally ignited a fire inside the rear lower roof line. Ladder-1 used a chain saw to expose the burning area from the top side of the roof. & Engine-1 extinguished all fire with a 1 1/3 pre-connected exterior line. A 2nd line was advanced to the interior to check for any extension. The area was overhauled and checked with a T.I.C. Fire placed under control @1247. The owner was on the scene. The contractors were told the use of a torch for roofing requires a permit. On duty arson investigators Buck & Rutherford conducted the arson investigation. FF Rotte injured his hand during operations but did not require medical attention at this time. All apparatus were restored to order command terminated 1349.

APPARATUS**Fire Controlled Date / Time:** 8/25/2024 12:47:00 PM

Unit	L2	Unit	E2
Type:	Truck or aerial	Type:	Engine
Use:	Suppression	Use:	Suppression
Response Mode:	()	Response Mode:	Lights and Sirens
# of People	3	# of People	3
Alarm	08 /25/2024 12:32:00	Alarm	08 /25/2024 12:32:00
Dispatched	08 /25/2024 12:33:00	Dispatched	08 /25/2024 12:33:00
Enroute	-- / -- / -- -- : -- : --	Enroute	-- / -- / -- -- : -- : --
Arrived	08 /25/2024 12:36:00	Arrived	08 /25/2024 12:36:00
Cancelled	-- / -- / -- -- : -- : --	Cancelled	-- / -- / -- -- : -- : --
Cleared Scene	08 /25/2024 13:05:00	Cleared Scene	08 /25/2024 12:55:00
In Quarters	-- / -- / -- -- : -- : --	In Quarters	-- / -- / -- -- : -- : --
In Service	-- / -- / -- -- : -- : --	In Service	-- / -- / -- -- : -- : --
Unit	93	Unit	L1
Type:	Chief officer car	Type:	Truck or aerial
Use:	Suppression	Use:	Suppression
Response Mode:	Lights and Sirens	Response Mode:	()
# of People	1	# of People	3
Alarm	08 /25/2024 12:32:00	Alarm	08 /25/2024 12:32:00
Dispatched	08 /25/2024 12:33:00	Dispatched	08 /25/2024 12:33:00
Enroute	-- / -- / -- -- : -- : --	Enroute	-- / -- / -- -- : -- : --
Arrived	08 /25/2024 12:36:00	Arrived	08 /25/2024 12:36:00
Cancelled	-- / -- / -- -- : -- : --	Cancelled	-- / -- / -- -- : -- : --
Cleared Scene	08 /25/2024 13:49:00	Cleared Scene	08 /25/2024 13:49:00
In Quarters	-- / -- / -- -- : -- : --	In Quarters	-- / -- / -- -- : -- : --
In Service	-- / -- / -- -- : -- : --	In Service	-- / -- / -- -- : -- : --
Unit	E3	Unit	E1
Type:	Engine	Type:	Engine
Use:	Suppression	Use:	Suppression
Response Mode:	Lights and Sirens	Response Mode:	()
# of People	3	# of People	3
Alarm	08 /25/2024 12:32:00	Alarm	08 /25/2024 12:32:00
Dispatched	08 /25/2024 12:33:00	Dispatched	08 /25/2024 12:33:00
Enroute	-- / -- / -- -- : -- : --	Enroute	-- / -- / -- -- : -- : --
Arrived	08 /25/2024 12:36:00	Arrived	08 /25/2024 12:36:00
Cancelled	-- / -- / -- -- : -- : --	Cancelled	-- / -- / -- -- : -- : --
Cleared Scene	08 /25/2024 13:48:00	Cleared Scene	08 /25/2024 13:49:00
In Quarters	-- / -- / -- -- : -- : --	In Quarters	-- / -- / -- -- : -- : --
In Service	-- / -- / -- -- : -- : --	In Service	-- / -- / -- -- : -- : --
Unit	E4		
Type:	Engine		
Use:	Suppression		
Response Mode:	Lights and Sirens		
# of People	3		
Alarm	08 /25/2024 12:32:00		
Dispatched	08 /25/2024 12:33:00		
Enroute	-- / -- / -- -- : -- : --		
Arrived	08 /25/2024 12:36:00		
Cancelled	-- / -- / -- -- : -- : --		
Cleared Scene	08 /25/2024 13:44:00		
In Quarters	-- / -- / -- -- : -- : --		
In Service	-- / -- / -- -- : -- : --		

Number Of People not on apparatus: 0

FIRE			
Acres Burned	None or Less Than One	Acres Burn From Wildland Form	False
Area Of Fire Origin	Roof surface: exterior	Heat Source	Flame/torch used for lighting
Item First Ignited	Structural component or finish, other	Fire Is Confined To Object Of Origin	
Type Of Material	Sawn wood, including all finished lumber	Cause Of Ignition	Unintentional
Factor Contributing To Ignition	Heat source too close to combustibles.		
Human Factors Contributing	None		

STRUCTURE FIRE			
Structure Type	Enclosed building	Building Status	In normal use
# Of Stories At Above Grade	3	# Of Stories Below Grade	1
Square Feet		Length	50
Width	30	Floor Of Origin	2
Fire Spread	Confined to floor of origin		
Minor Damage	0	Significant Damage	0
Heavy Damage	0	Extreme Damage	0

PEOPLE -- PERSON 1			
Is Owner	True	Business Name	
Telephone Number	862-686-8099	Involvement	
Name	MR Luis Marquez	Date of Birth	
Address	459 HARRISON ST 1st flor PASSAIC, NJ 07055-		

PEOPLE -- PERSON 2			
Is Owner	False	Business Name	P & G Construction
Telephone Number	201-494-0932	Involvement	Contractor
Name	MR Johnathan Santos	Date of Birth	
Address	807 Van Houten AVE Clifton, NJ		

PEOPLE -- PERSON 3			
Is Owner	False	Business Name	
Telephone Number	973-851-8315	Involvement	Contractor that used the torch
Name	MR Joesph Robertson	Date of Birth	
Address	339 Boulevard Passaic, NJ 07055-		

CUSTOM FIELDS FORM

Is this response related to a Lithium-Ion battery fire / explosion / incident?	NO
COVID-19 (Coronavirus) presumptive related incident/response?	NO
Is this CIVIL UNREST / PROTEST / RIOT Related?	NO, this is NOT attributed to a CIVIL UNREST / PROTEST / RIOT situation
Were FIRE HYDRANT(s) blocked at this fire/emergency scene? (If yes, notify police immediately).	No
If this was a restaurant, bar, night club or any other place of gathering, was HOOKAH (or any other tobacco product) being smoked?	NO
Were CO (Carbon Monoxide) levels present?	NO

Member Making Report (Battalion Chief Damien M Pilipski): _____

Incident Reviewer (Battalion Chief Damien M Pilipski): _____