



Passaic Fire Department (NJ)

Station: **WS**
Shifts Or Platoon: **Tour 3**

Location:
42 FOURTH ST # A4
PASSAIC NJ 07055

Lat/Long:
N 40° 51' 46.07"
W 74° 6' 51.48"

Zone:
Engine 2 - E2
Location Type: **1 - Street address**

Incident Type:
111 - Building fire

FDID: **16070**
Incident #: **2024-2423**
Exposure ID: **80689905**
Exposure #: **0**
Incident Date: **07/10/2024**
Dispatch Run #: **24-2423**

Report Completed by:	Santiago , Louis	ID: 156	Date: 07/10/2024
Report Reviewed by:	Santiago , Louis	ID: 156	Date: 07/10/2024
Report Printed by:	Failla, Toni	ID: ADMIN	Date: 10/2/2024 Time: 10:42

Structure Type: **Enclosed building** Property Use: **429 - Multifamily dwelling**

Automatic Extinguishment System Present: ☐ Detectors Present: ☒ Cause of Ignition: **Cause under investigation**

Aid Given or Received: **None** Primary action taken: **81 - Incident command**

Additional actions: **86 - Investigate , 10 - Fire control or extinguishment, other**

Losses	Pre-Incident Values		
Property:	Property:	Civilian Injuries: 0	Fire Service Injuries: 0
Contents:	Contents:	Civilian Fatalities: 0	Fire Service Fatalities: 0
Total:	Total:	Total Casualties: 0	Total Fire Service Casualties: 0
Total # of apparatus on call: 7		Total # of personnel on call: 19	

Neighboring Agencies

Agency Name: CLIFTON
Agency ID: 1602
Agency Type: Fire

NARRATIVE (1)**Narrative Title:** LT. Niessen**Narrative Author:** Niessen, Robert**Narrative Date:** 07/10/2024 20:05:04**Narrative Apparatus ID:** E4**Narrative:**

Engine 4 responded to 42 Fourth Street on a report of an appliance fire @ 1755. Upon arrival a working structure fire was announced by command. Engine 4 members assisted in stretching hose lines to the seat of the fire. Members then checked the structure for victims by forcing doors and searching for residents. All residents were accounted for and the fire was placed under control. Members then assisted Engine 2 and Engine 3 in re-packing their hose onto their apparatus and command released Engine 4 @ 1931.

LT. Robert Niessen

NARRATIVE (2)**Narrative Title:** Capt. B.Giaconia**Narrative Author:** Giaconia, Bart**Narrative Date:** 07/10/2024 20:30:51**Narrative Apparatus ID:** L1**Narrative:**

Responded at 1805 hours to 42 Fourth Street on a second alarm structure fire. Upon arrival Ladder 1 preformed a primary search of the apartments above the fire. Members forced entry to apartments 3,6, and 9. Members removed 1 occupant from apartment 3. Members then assisted in ventilation and overhaul the fire apartment. Members secured the gas to the apartment. All members Rehabbed. Released by command. Ladder 1 available at 1931 hours.

Capt. B.Giaconia

NARRATIVE (3)**Narrative Title:** LT. R. Rivera**Narrative Author:** Rivera, Rene**Narrative Date:** 07/10/2024 20:30:39**Narrative Apparatus ID:** E1**Narrative:**

At 1755 hrs. Engine 1 responded to 42 Fourth St. when a second alarm was struck for an appliance fire which advanced to a kitchen fire. Upon arrival Engine 1 was ordered to come in for man power as per command. Engine 1 members gained access to the basement and secured power to the fire apartment in question. Engine 1 became available at 1933 hrs. when released as per command.

LT. R. Rivera

NARRATIVE (4)**Narrative Title:** B/C Santiago**Narrative Author:** Pilipski, Damien**Narrative Date:** 07/10/2024 21:30:25**Narrative Apparatus ID:** 93**Narrative:**

@1755hrs dispatched to 42 Fourth st on a report of an appliance fire. Upon arrival L-2a reported smoke showing then report of a kitchen fire apartment 4a. E2 and E3 secured hydrants and then 2 attack lines were stretched through A side door located, confined and extinguished all fire. Reports from tenants were occupants were still inside. L-1 conducted primary search and secured utilities. E4 and E-1 assisted with evacuation of the structure and overhaul. Tic was used by L-1 to check for extension found all clear Fire was under control at 1824hrs. 91, 92 and 98 on scene. Pseg gas requested to scene. Rehab and EMS on scene. Investigator Woods conducted the Investigation. Walter Porto on scene for 1 family needing relocation and Red Cross gathered information.

Owner on scene building turned over to owner Pd on scene B/C available 1944hrs.

NARRATIVE (5)**Narrative Title:** LT. J.IVANICKI**Narrative Author:** Ivanicki, Joseph**Narrative Date:** 07/10/2024 21:36:22**Narrative Apparatus ID:** E2**Narrative:**

At 1755 hrs. E-2 responded to 42 Fourth st. for a reported fire. Upon arrival we used the hydrant at the intersection of Fourth and Essex st. E-2 then pulled up to the building and we use 4 length of 1 1/3 hose line to the first floor apt. were the fire was in the kitchen area. The oven and the wall behind the oven was on fire extending up into the cabinets. After we extinguished the fire we overhauled the area behind and above the oven. We assisted with packing up all equipment and hose lines. After we went to rehab we were released by command at 1944 hrs.

NARRATIVE (6)**Narrative Title:** Lt. Gomez**Narrative Author:** Gomez, Lenin**Narrative Date:** 07/10/2024 21:51:23**Narrative Apparatus ID:** E3**Narrative:**

At 1755 Engine 3 responded to 42 Fourth St for a reported fire. Upon arrival Engine 3 established a water supply at the intersection of Passaic St and Fourth st using two lengths of LDH(4 inch supply line). Engine 3 members advanced four lengths of 1 3/4 attack line through the front door of apartment 4-a on Division 1 to locate ,confine and extinguish. Fire was extinguished. Members Re-packed the hoses. Recall at 1923.

Lt. Gomez

NARRATIVE (7)**Narrative Title:** Capt.Romero**Narrative Author:** Romero, Jorge**Narrative Date:** 07/10/2024 22:04:58**Narrative Apparatus ID:** L2**Narrative:**

At 1755 hrs. responded to 42 4th St. apt.4A for a report of an appliance fire. Upon arrival establish command and conducted investigation. Found moderate amount of smoke coming from division 1 A side entrance to the structure. Ladder 2 proceeded thru intensified smoking condition thru the common hallway to the apt located on division 1 and discovery the main body of fire in the kitchen area around the stove. Ladder 2 crew utilized the water can to confine the fire as well as controlling the door to the apt. until Engine crews arrived the hose lines. During the incident B/C #3 assumed command from Ladder 2A. Primary search utilizing the T.I.C. was completed during the initial operation and results were negative.

After the fire was extinguished by Engine crews; secondary searches and overhaul was conducted; results were negative of search and no extension. The utilities were secured to the apt. The completion of the all tasks order by command was completed and all equipment returned to the apparatus; Ladder 2 was released by command and available at 1944 hrs.

APPARATUS**Fire Controlled Date / Time:**

7/10/2024 6:24:00 PM

Unit E4
Type: Engine
Use: Suppression
Response Mode: ()
of People 3
Alarm 07 /10/2024 17:54:00
Dispatched 07 /10/2024 17:55:00
Enroute -- / -- / -- -- : -- : --
Arrived 07 /10/2024 17:59:00
Cancelled -- / -- / -- -- : -- : --
Cleared Scene 07 /10/2024 19:31:00
In Quarters -- / -- / -- -- : -- : --
In Service -- / -- / -- -- : -- : --

Unit L1
Type: Truck or aerial
Use: Suppression
Response Mode: Lights and Sirens
of People 3
Alarm 07 /10/2024 17:54:00
Dispatched 07 /10/2024 17:55:00
Enroute -- / -- / -- -- : -- : --
Arrived 07 /10/2024 18:05:00
Cancelled -- / -- / -- -- : -- : --
Cleared Scene 07 /10/2024 19:31:00
In Quarters -- / -- / -- -- : -- : --
In Service -- / -- / -- -- : -- : --

Unit E2
Type: Engine
Use: Suppression
Response Mode: Lights and Sirens
of People 3
Alarm 07 /10/2024 17:54:00
Dispatched 07 /10/2024 17:55:00
Enroute -- / -- / -- -- : -- : --
Arrived 07 /10/2024 17:59:00
Cancelled -- / -- / -- -- : -- : --
Cleared Scene 07 /10/2024 19:44:00
In Quarters -- / -- / -- -- : -- : --
In Service -- / -- / -- -- : -- : --

Unit E3
Type: Engine
Use: Suppression
Response Mode: Lights and Sirens
of People 3
Alarm 07 /10/2024 17:54:00
Dispatched 07 /10/2024 17:55:00
Enroute -- / -- / -- -- : -- : --
Arrived 07 /10/2024 17:59:00
Cancelled -- / -- / -- -- : -- : --
Cleared Scene 07 /10/2024 19:23:00
In Quarters -- / -- / -- -- : -- : --
In Service -- / -- / -- -- : -- : --

Unit L2
Type: Truck or aerial
Use: Suppression
Response Mode: Lights and Sirens
of People 3
Alarm 07 /10/2024 17:54:00
Dispatched 07 /10/2024 17:55:00
Enroute -- / -- / -- -- : -- : --
Arrived 07 /10/2024 17:59:00
Cancelled -- / -- / -- -- : -- : --
Cleared Scene 07 /10/2024 19:44:00
In Quarters -- / -- / -- -- : -- : --
In Service -- / -- / -- -- : -- : --

Unit E1
Type: Engine
Use: Suppression
Response Mode: Lights and Sirens
of People 3
Alarm 07 /10/2024 17:54:00
Dispatched 07 /10/2024 17:55:00
Enroute -- / -- / -- -- : -- : --
Arrived 07 /10/2024 17:59:00
Cancelled -- / -- / -- -- : -- : --
Cleared Scene 07 /10/2024 19:33:00
In Quarters -- / -- / -- -- : -- : --
In Service -- / -- / -- -- : -- : --

Unit 93
Type: Chief officer car
Use: Suppression
Response Mode: Lights and Sirens
of People 1
Alarm 07 /10/2024 17:54:00
Dispatched 07 /10/2024 17:55:00
Enroute -- / -- / -- -- : -- : --
Arrived 07 /10/2024 17:59:00
Cancelled -- / -- / -- -- : -- : --
Cleared Scene 07 /10/2024 19:44:00
In Quarters -- / -- / -- -- : -- : --
In Service -- / -- / -- -- : -- : --

Number Of People not on apparatus: 0

FIRE			
Acres Burned	None or Less Than One	Acres Burn From Wildland Form	False
Area Of Fire Origin	Cooking area, kitchen	Heat Source	Spark, ember, or flame from operating equipment
Item First Ignited	Undetermined	Fire Is Confined To Object Of Origin	
Type Of Material	Undetermined	Cause Of Ignition	Cause under investigation
Factor Contributing To Ignition	Undetermined		
Human Factors Contributing	None		
Equipment Involved In Ignition Flag	True	Equipment Involved	Oven, rotisserie
Equipment Power Source	Natural gas or other lighter-than-air gas	Equipment Portability	Stationary

STRUCTURE FIRE			
Structure Type	Enclosed building	Building Status	In normal use
# Of Stories At Above Grade	4	# Of Stories Below Grade	1
Square Feet		Length	120
Width	75	Floor Of Origin	1
Fire Spread	Confined to room of origin		
Minor Damage	0	Significant Damage	0
Heavy Damage	0	Extreme Damage	0
Presence Of Detectors	Present	Type Of Detection System	Smoke
Detector Power Supply	Multiple detectors and power supplies	Detector Operation	Detector operated
Detector Effectiveness	Detector alerted occupants, occupants responded	Detector Failure Reason	

ARSON		
Property Ownership	Initial Observations	Laboratory Used
	Doors unlocked	None

CUSTOM FIELDS FORM	
Is this response related to a Lithium-Ion battery fire / explosion / incident?	NO
COVID-19 (Coronavirus) presumptive related incident/response?	UNKNOWN
Is this CIVIL UNREST / PROTEST / RIOT Related?	NO, this is NOT attributed to a CIVIL UNREST / PROTEST / RIOT situation
Were FIRE HYDRANT(s) blocked at this fire/emergency scene? (If yes, notify police immediately).	No
If this was a restaurant, bar, night club or any other place of gathering, was HOOKAH (or any other tobacco product) being smoked?	NO
Were CO (Carbon Monoxide) levels present?	NO

Member Making Report (Battalion Chief Louis Santiago): _____

Incident Reviewer (Battalion Chief Louis Santiago): _____