

Incident Run Log

Bergenfield Fire Department

Date Range: From 01/01/2025 to 01/27/2025

Company: All Companies

Sorted by: Not selected

Date	FDID	Incident#	Alarm	###	Address	Suite	Zip	Type	Lgth
01/01/2025	02030	2025-000001	00:29		N. Washington Ave.		07621-	Good intent call, other	0.1
01/01/2025	02030	2025-000002	01:17	145	E. Clinton Ave		07621-	Dumpster or other outside trash receptacle fire	0.6
01/01/2025	02030	2025-000003	02:01	131	School St.		07621-	Dumpster or other outside trash receptacle fire	0.6
01/01/2025	02030	2025-000004	13:48	90	New Bridge Rd.		07621-	Smoke detector activation, no fire - unintentional	0.2
01/01/2025	02030	2025-000005	19:57		Twin Boro Lane		07621-	Dumpster or other outside trash receptacle fire	0.0
01/02/2025	02030	2025-000006	08:12	95	N. Queen St.		07621-	Chemical hazard (no spill or leak)	0.0
01/02/2025	02030	2025-000007	11:52	293	Murray Hill Terr.	221	07621-	Medical assist, assist EMS crew	0.0
01/02/2025	02030	2025-000008	15:17	51	E. Main St.		07621-	Smoke detector activation, no fire - unintentional	0.0
01/02/2025	02030	2025-000009	23:16	56	Norfolk St.		07621-	Smoke or odor removal	0.0
01/03/2025	02030	2025-000010	15:52	1	Glenwood Dr. East		07621-	Smoke detector activation, no fire - unintentional	0.0
01/03/2025	02030	2025-000011	16:23	31	Lee Pl.		07621-	Carbon monoxide detector activation, no CO	0.0
01/04/2025	02030	2025-000012	08:24	375	Larch Ave.		07603-	Cover assignment, standby, moveup	0.0
01/04/2025	02030	2025-000013	15:56	293	Murray Hill Terr.	517	07621-	Cooking fire, confined to container	0.0
01/07/2025	02030	2025-000014	11:02	375	Larch Ave		07603-	Cover assignment, standby, moveup	1.0
01/08/2025	02030	2025-000015	02:14	144	W. Central Ave.		07621-	Water or steam leak	0.4
01/08/2025	02030	2025-000016	04:28	49	Sussex Rd.		07621-	Carbon monoxide detector activation, no CO	0.3
01/08/2025	02030	2025-000017	19:56	72	Hallberg Ave.		07621-	Smoke detector activation, no fire - unintentional	0.4
01/10/2025	02030	2025-000018	10:48	108	S. Front St.		07621-	Detector activation, no fire - unintentional	0.1
01/10/2025	02030	2025-000019	13:06	88	N. Prospect Ave.		07621-	Citizen complaint	0.1
01/10/2025	02030	2025-000020	16:56	175	E. Church St.		07621-	Cooking fire, confined to container	0.2
01/10/2025	02030	2025-000021	19:20	75	Liberty Rd.	A	07621-	Gas leak (natural gas or LPG)	1.0
01/11/2025	02030	2025-000022	00:19		Ralph St.		07621-	Gas leak (natural gas or LPG)	1.9
01/12/2025	02030	2025-000024	07:21	169	Howard Dr.	A	07621-	Medical assist, assist EMS crew	0.4
01/12/2025	02030	2025-000025	11:30	226	New Bridge Rd.		07621-	Motor vehicle accident with injuries	0.6
01/12/2025	02030	2025-000026	21:31	124	Bradley Ave		07621-	Smoke or odor removal	0.0
01/13/2025	02030	2025-000027	13:03		Bedford Rd.		07621-	Gas leak (natural gas or LPG)	0.0
01/14/2025	02030	2025-000028	08:43	160	Frederick Pl.		07621-	Gas leak (natural gas or LPG)	0.0
01/15/2025	02030	2025-000029	15:26	34	Sylvamdur Ave.		07621-		0.0
01/15/2025	02030	2025-000030	16:41	37	Fairview Ave	C	07621-	Cooking fire, confined to container	0.3
01/15/2025	02030	2025-000031	16:42	57	Moos Ln.		07621-	Outside storage fire	0.9
01/15/2025	02030	2025-000032	18:22	74	New Jersey Ave.		07621-	Cooking fire, confined to container	0.4
01/16/2025	02030	2025-000033	12:57	80	S. Prospect Ave		07621-		0.0
01/16/2025	02030	2025-000034	18:09	294	S. Washington Ave	10	07621-	Smoke or odor removal	0.4
01/17/2025	02030	2025-000035	22:24	60	Glenwood Dr. South		07621-	Alarm system activation, no fire - unintentional	0.4
01/18/2025	02030	2025-000036	13:02	293	Murray Hill Terrace	519	07621-	Smoke or odor removal	0.0
01/18/2025	02030	2025-000037	14:14	42	Glenwood Dr. East		07621-	Carbon monoxide detector activation, no CO	0.3
01/18/2025	02030	2025-000038	15:03	78	Portland Ave.		07621-	Smoke detector activation, no fire - unintentional	0.4
01/18/2025	02030	2025-000039	20:34	55	Fairview Ave.	1	07621-	Cooking fire, confined to container	0.4
01/19/2025	02030	2025-000040	02:23	110	Maiden Ln.		07621-	Heat from short circuit (wiring), defective/worn	0.5
01/19/2025	02030	2025-000041	17:50	294	S. Washington Ave,	14	07621-	Smoke detector activation due to malfunction	0.3
01/20/2025	02030	2025-000042	09:51	141	Sussex Rd.		07621-	Smoke detector activation due to malfunction	0.7
01/20/2025	02030	2025-000043	11:34	7	Twin Boro Ln.		07621-	Carbon monoxide detector activation, no CO	0.3
01/21/2025	02030	2025-000044	10:17	32	W. Church St.		07621-	Alarm system activation, no fire - unintentional	0.0
01/21/2025	02030	2025-000045	13:58	135	Dudley Dr.		07621-	Smoke detector activation, no fire - unintentional	0.3
01/21/2025	02030	2025-000046	18:34	45	Momar Dr.		07621-	Alarm system sounded due to malfunction	0.2
01/21/2025	02030	2025-000047	18:48	78	Portland Ave.		07621-	Smoke or odor removal	0.3
01/22/2025	02030	2025-000048	09:09	139	Dudley Dr.		07621-	Carbon monoxide detector activation, no CO	0.2
01/22/2025	02030	2025-000049	15:28	203	Hillside Ave		07621-	Water or steam leak	0.2
01/22/2025	02030	2025-000050	18:40	25	Coyne Ct.		07621-	Passenger vehicle fire	1.1
01/23/2025	02030	2025-000051	17:56	17	Cleveland St.		07621-	Water or steam leak	0.3
01/24/2025	02030	2025-000052	02:58	282	N. Prospect Ave.		07621-	Hazardous condition, other	0.6
01/24/2025	02030	2025-000053	09:54	225	Harrington St.		07621-	Smoke detector activation due to malfunction	0.0
01/24/2025	02030	2025-000054	22:35	155	W. Church St.		07621-	Public service assistance, other	0.3
01/25/2025	02030	2025-000055	09:17	92	S. Front St.		07621-	Detector activation, no fire - unintentional	0.3

Date	FDID	Incident#	Alarm	###	Address	Suite	Zip	Type	Lgth
01/26/2025	02030	2025-000056	01:17	610	S. Prospect Ave.		07621-	Carbon monoxide detector activation, no CO	0.0
01/26/2025	02030	2025-000057	16:59	62	Levitt Ave.		07621-	Fire, other	0.5
01/26/2025	02030	2025-000058	18:27	162	Merritt Ave.		07621-	Smoke scare, odor of smoke	0.1
01/26/2025	02030	2025-000059	18:50	103	Highgate Terr.		07621-	CO detector activation due to malfunction	0.4
01/11/2025	02030	2025-000023	13:52	20	Merritt Ave.		07621-	Gas leak (natural gas or LPG)	0.0

Total Number of Incidents: 59

Total Length of Incidents: 17.8 Hours

Bergenfield Fire Department

Bergenfield, NJ

This report was generated on 1/27/2025 1:49:46 PM



Basic Incident Info for Incident Type

Incident Type(s): All Incident Types | Start Date: 10/28/2024 | End Date: 12/31/2024

Incident Date	Incident #	Dispatch Run Number	Address	Narrative	Station	Zone
10/29/2024	2024-558		74 Surrey LN	Fire department responded to 74 Surrey Ln for activated alarms that started about 24 hours in the past, but are no longer activated. On arrival, units checked the residence throughout and found a faulty detector in the kitchen area of the first floor. Homeowner advised to replace detector. No hazards found inside home. FD cleared scene.	HQ - Station HQ	Prospect
10/29/2024	2024-559		139 S Washington AVE	Fire department dispatched to 139 S Washington Ave for activated alarms. On arrival, business owner stated they called the alarm company to put system on test for a fire drill. FD units checked the building throughout and found no hazards. FD cleared scene.	HQ - Station HQ	Alert
10/29/2024	2024-560		66A S Washington AVE	Fire department dispatched to 66 S Washington Ave for activated alarms. On arrival, business owner from 66A S Wash stated a child pulled the pull station inside the business. Units checked the business throughout and found no hazards. Alarm reset. FD cleared scene.	HQ - Station HQ	Alert
10/29/2024	2024-561		30 Highview Ave	DISPATCHED FOR A FIRE ALARM ACTIVATION. ALARM WAS SET OFF DUE TO SMOKE FROM COOKING. THE ALARM WAS REST AND HELD.	03 - Station 03	Prospect
10/29/2024	2024-562		244 E Main ST	The fire department responded to an activated fire alarm at 244 E Main St. Upon investigation it was determined that the alarm was set off by a resident of the group home pulling the pull station. The pull station and then the fire alarm were reset.	02 - Station 02	Co2
10/30/2024	2024-563		140 Woodbine ST	Fire department dispatched to 140 Woodbine St for activated alarms from a water flow switch. On arrival, units found sprinkler company on scene testing system. No hazards found. FD cleared scene.	HQ - Station HQ	Prospect
10/30/2024	2024-564		110 Stillman AVE	PROSPECT FIRE COMPANY WAS DISPATCHED TO 110 STILLMAN AVE FOR AN ODOR OF GAS IN THE ROADWAY. PSE&G ARRIVED ON THE SCENE AND DETERMINED THAT THE ODOR WAS DUE TO A FAILED RECENT REPAIR IN THE ROADWAY. THE HOUSES IN THE AREA WERE CHECKED WITH NO FINDINGS. PSE&G RELEASED THE FD FROM THE SCENE.	03 - Station 03	Alert
11/01/2024	2024-565		15 Dudley DR	Fire department dispatched to 15 Dudley Dr for an inside odor of gas. On arrival, units found a gas leak in a hose going to the dryer in the basement. PSEG responded. FD released by PSEG	HQ - Station HQ	Prospect
11/01/2024	2024-566		87 Dudley DR	Fire department dispatched to 87 Dudley Dr for a problem with a gas stove. On arrival, homeowner stated flames on gas stove "were too orange" and they may have a CO issue. Units checked the residence throughout and found no hazards. Units checked residence using multi gas meters, negative readings. FD cleared scene.	HQ - Station HQ	Prospect

This report is limited to 500 pages. Incidents with more than one narrative will appear on multiple pages. Only REVIEWED incidents included.



emergencyreporting.com

Doc Id: 830

Page # 1 of 14

Incident Date	Incident #	Dispatch Run Number	Address	Narrative	Station	Zone
11/02/2024	2024-567		415 south washington ave	THE FIRE DEPARTMENT WAS DISPATCHED TO THE ABOVE ADDRESS FOR A REPORTED FIRE. DEPUTY 2 ARRIVED ON SCENE AND HAD NO SIGNS OF SMOKE, FIRE OR ALARMS SOUNDING. STAFF REPORTED THERE WAS A FLASH FIRE ON THE FRYER WITH NO EXTENSION. UNITS HELD IN QUARTERS.	03 - Station 03	Prospect
11/02/2024	2024-568		10 William ST	ALARMS WERE SOUNDING & OCCUPANTS WERE EVACUATED UPON FD ARRIVAL. THE BUILDING MAINTENANCE COORDINATOR MET FD UNITS OUT FRONT STATING A SMOKE MACHINE WAS THE CAUSE OF THE ALARM. FD UNITS VENTED THE STRUCTURE. ALARM WAS RESET.	02 - Station 02	Co2
11/03/2024	2024-569		369 Washington AVE	BFD WAS DISPATCHED TO 369 S WASHINGTON AVE FOR A SMOKE CONDITION FROM A WASHING MACHINE. THERE WAS NO SMOKE CONDITION INSIDE THE BUILDING WHEN 740 ARRIVED. THE WASHING MACHINE IN QUESTION WAS DISCONNECTED AND THE ALARM WAS REST.	01 - Station 01	Alert
11/04/2024	2024-570		52 Beverly PL	PROSPECT FIRE COMPANY WAS DISPATCHED TO 52 BEVERLY PL FOR A RUN AWAY BOILER. THE PD ARRIVED ON SCENE FIRST AND SHUT OFF THE THERMOSTAT TO THE FURNACE. THE CREW OF E1 INVESTIGATED WITH A MULTIGAS METER AND NO READINGS WERE FOUND. THE CREW THEN SHUT DOWN THE GAS AND ELECTRIC TO THE FURNACE. PSE&G ARRIVED ON THE SCENE AND RELEASED THE FD.	03 - Station 03	Alert
11/04/2024	2024-571		30 Highgate	THE FIRE DEPARTMENT WAS DISPATCHED TO THE ABOVE ADDRESS FOR AN ACTIVATED CO ALARM. UNITS ARRIVED ON SCENE TO FIND THE HOMEOWNER WAITING OUTSIDE SAYING THE ALARM WENT OFF. UNITS FOUND A DETECTOR CHIRPIING END OF LIFE. NO READINGS OF CO FOUND IN THE HOUSE. RESIDENT WAS ADVISED TO REPLACE THE DETECTOR.	03 - Station 03	Prospect
11/04/2024	2024-572		217 Phelps AVE	Dispatched for possible run away boiler. Upon arrival FD was met by resident that had no clue of any issues. FD checked entire house with negative results.	HQ - Station HQ	Co2
11/04/2024	2024-573		Washington	A smoke condition was reported in front of Boro Hall. Nothing was found. A passing bus was determined to be at the origin of the call	02 - Station 02	Co2
11/05/2024	2024-574		245 Johnson AVE	Smoke condition due to pre heating of oven. Alarm was reset w/o need for vent.	HQ - Station HQ	Co2
11/06/2024	2024-575		5 Washington AVE	BFD WAS DISPATCHED TO 5 S WASHINGTON AVE FOR A REPORT OF SMOKE COMING FROM THE BUILDING. DC2 AND 740 ARRIVED ON THE SCENE AND FOUND NO SMOKE. THE AREA WAS INVESTIGATED AND NOTHING WAS FOUND. ALL UNITS WERE CANCELLED.	01 - Station 01	Alert
11/08/2024	2024-576		90 New Bridge RD	THE FIRE DEPARTMENT WAS DISPATCHED TO THE ABOVE LOCATION FOR AN ACTIVATED FIRE ALARM. E1 ARRIVED ON SCENE AND FOUND ALARMS SOUNDING AND OCCUPANTS EVACUATED. AN ACTIVATED HEAD WAS FOUND IN THE BATHROOM DUE TO UNK CAUSES. ALARM WAS RESET. UNITS PICKED UP FROM THE SCENE.	03 - Station 03	Prospect
11/08/2024	2024-577		385 Ivy LN	Fire department dispatched to 385 Ivy Ln for activated alarms. On arrival, units found alarm set off due to smoke from cooking. No need for ventilation. Alarm reset and held. NTC issued for fault in alarm system. FD cleared scene.	HQ - Station HQ	Prospect

This report is limited to 500 pages. Incidents with more than one narrative will appear on multiple pages. Only REVIEWED incidents included.



Incident Date	Incident #	Dispatch Run Number	Address	Narrative	Station	Zone
11/08/2024	2024-578		101 Thames BLVD	THE FIRE DEPARTMENT WAS DISPATCHED TO THE AREA OF 101 THAMES FOR AN OUTSIDE ODOR OF SMOKE. UNITS ARRIVED ON SCENE TO FIND A SLIGHT ODOR OF RESIDUAL SMOKE COMING FROM A NEARBY WILDFIRE IN ENGLEWOOD CLIFFS. NO SIGNS OF FIRE WERE FOUND IN THE AREA.	03 - Station 03	Prospect
11/10/2024	2024-579		3 Lee PL	PROSPECT FIRE COMPANY WAS DISPATCHED TO 3 LEE PL FOR AN ACTIVATED CO ALARM. THE ALARM WAS ACTIVATED DUE TO THE RESIDENT CHANGING THE BATTERIES. THE HOUSE WAS CHECKED THROUGHOUT WITH 2 MULTIGAS METERS AND NOTHING WAS FOUND.	03 - Station 03	Prospect
11/11/2024	2024-580		89 Hallberg AVE	PROSPECT FIRE COMPANY WAS DISPATCHED TO 89 HALLBERG AVENUE FOR AN ODOR OF GAS INSIDE THE HOUSE. THE ODOR WAS TRACED BACK TO THE ATTIC AND ONE OF THE TWO HVAC UNITS IN THE HAD THE HIGHEST READINGS. GAS WAS SECURED TO BOTH HVAC UNITS AND VENTILATION OPERATIONS WERE STARTED. PSE&G ARRIVED ON THE SCENE AND FOUND THE SOURCE OF THE GAS TO BE AN ISSUE WITH THE HVAC UNIT IN THE ATTIC. THE HOUSE WAS VENTILATED DOWN TO ZERO %LEL. AND PSE&G RELEASED THE FD FROM THE SCENE.	03 - Station 03	Prospect
11/12/2024	2024-581		387 S Washington	Smoldering mulch. Extinguished with water can.	02 - Station 02	Alert
11/13/2024	2024-582		6 Malden CT	Fire department dispatched to 6 Malden Ct for an issue with a heating system. On arrival, homeowner met FD units outside and stated there is an issue with the fan motor on the heating system. Units checked the residence throughout and found no hazards. Home checked using multi gas meters, negative readings. PSEG requested to respond in. FD cleared scene.	HQ - Station HQ	Prospect
11/13/2024	2024-583		N Washington AVE	Fire department dispatched to the intersection of N Washington Ave and Main St for an odor of natural gas in the area. On arrival, units checked the area as well as several businesses on Washington Ave, no readings found. Odor was unfounded, FD cleared scene.	HQ - Station HQ	Alert
11/13/2024	2024-584		150 Church ST	Fire department dispatched in front of 150 W Church for possible broken gas line. On arrival, units found a slight leak underneath the sidewalk in front of 150 W Church St. PSEG arrived. FD released by PSEG	HQ - Station HQ	Alert
11/13/2024	2024-585		107 N Prospect AVE	Fire department dispatched to the rear of 107 N. Prospect Ave. for a fire pit in the backyard. On arrival, unit found resident burning leaves in a fire pit. Fire pit extinguished, resident advised of the current burn ban. FD cleared scene.	HQ - Station HQ	Alert
11/14/2024	2024-586		81 Maiden LN	PROSPECT FIRE COMPANY WAS DISPATCHED TO 81 MAIDEN LN FOR AN ACTIVATED FIRE ALARM. THE CREW FROM ENGINE 1 WAS DENIED ENTRY INTO THE HOME BY THE HOMEOWNER. THE HOMEOWNER ADVISED US THAT THE ALARM WAS ACTIATED DUE TO STEAM FROM THE SHOWER AND THAT THE ALARM WAS ALREADY RESET. FIRE DEPARTMENT COMMAND WAS TERMINATED.	03 - Station 03	Prospect
11/15/2024	2024-587		289 S Washington AVE	Fire department dispatched to 289 S Washington Ave. on arrival, units found alarm set off due to smoke from cooking in apartment 7B. No need for ventilation. Alarms reset. FD cleared scene.	HQ - Station HQ	Alert

This report is limited to 500 pages. Incidents with more than one narrative will appear on multiple pages. Only REVIEWED incidents included.



Incident Date	Incident #	Dispatch Run Number	Address	Narrative	Station	Zone
11/16/2024	2024-588		268 Washington AVE 3-28	Smoke from cooking was determined to be the culprit. the tenant of Apt. 28A was informed NOT to vent into common areas in the future. Superintendent reported to the complex and assisted in finding the Alarm panel for Bldg 3. Alarm was reset and command was terminated.	02 - Station 02	Alert
11/17/2024	2024-589		110 Tulip ST	Upon arrival it was determined that residual drifting smoke from NY's wildfires were the source of the condition. E3 investigated along Highland Ave. further and found nothing.	02 - Station 02	Alert
11/17/2024	2024-590		78 Lee PL	PROSPECT FIRE COMPANY WAS DISPATCHED TO 78 LEE PL FOR AN ACTIVATED FIRE ALARM. THE HOUSE WAS CHECKED THROUGHOUT WITH A TIC AND A MULTIGAS METER AND NO READINGS OR CAUSES OF THE AFA WERE FOUND. THE ALARM WAS RESET AND HELD.	03 - Station 03	Prospect
11/17/2024	2024-591		19 Merritt AVE	THE BFD WAS DISPATCHED TO A REPORT OF A FIRE BEHIND CHASE BANK ON WASHINGTON AVE. PD UNITS ENROUTE LOCATED A FIRE IN THE REAR OF 19 MERRITT AVE. UPON ARRIVAL, THE HOMEOWNER WAS IN THE DRIVEWAY STARTING TO TRY & STRETCH THE GARDEN HOSE TO EXTINGUISH. HE WAS REMOVED BY PD UNITS TO SAFETY. FIRE HAD CROSSED THROUGH THE FENCE & STARTED TO TAKE OFF TO THE BRUSH BEHIND. CREW FROM ENGINE3 SECURED A WATER SUPPLY & STRETCHED THE ATTACK LINE TO EXTINGUISH THE FIRE. CREW FROM ENGINE 1 ASSISTED WITH OVERHAULING THE AREA OF ORIGIN. CREW FROM RESCUE 1 PROVIDED LIGHTING FOR THE AREA. THE FIRE OFFICIAL WAS NOTIFIED BUT DID NOT ANSWER NOR DID HE RESPOND. THE AREA OF ORIGIN WAS EXTENSIVELY OVERHAULED TO ENSURE ALL HOT SPOTS WERE FULLY EXTINGUISHED.	02 - Station 02	Co2
11/18/2024	2024-592		41 Washington AVE	41 S Washington Avenue was a boiler technician starting the boiler creating a light smoke condition which activated the fire alarms. No need to vent. Alarms were silenced until the technician completed the work.	HQ - Station HQ	Alert
11/18/2024	2024-593		28 Momar DR	HOMEOWNER MET FD UNITS OUT FRONT STATING A HAIR DRYER SET THE ALARM OFF. THE ALARM WAS RESET PRIOR TO FD ARRIVAL. UNITS CHECKED THE STRUCTURE. ALL GOOD.	02 - Station 02	Co2
11/18/2024	2024-594		57 Carnation ST	HOMEOWNER MET FD UNITS OUT FRONT STATING THEY SMELLED NATURAL GAS IN THE KITCHEN. UPON INVESTIGATING, A BURNER ON THE STOVE WAS FOUND TO BE MALFUNCTIONING. THE HOMEOWNER WAS ADVISED TO CALL A REPAIRMAN & THE GAS TO THE STOVE WAS SECURED.	02 - Station 02	Alert
11/19/2024	2024-595		241 Main ST	Activated alarm due to smoke from cooking. FD vented using fan. Alarm was reset.	HQ - Station HQ	Alert
11/20/2024	2024-596		29 N Washington AVE	Fire department dispatched to 29 N Washington Ave, St John's Church, for activated alarms.	HQ - Station HQ	Alert
11/20/2024	2024-597		29 N Washington AVE	Fire department dispatched to 29 N Washington Ave, St John's Church, for activated alarms. On arrival, units found alarm set off due to workers on scene. Workers advised to properly cover alarm heads before continuing work. Alarm reset. FD cleared scene.	HQ - Station HQ	Alert
11/20/2024	2024-598		80 S Prospect AVE	Fire department dispatched to 80 S Prospect Ave, Bergenfield High School, for activated alarms. On arrival, units found alarm set off due to the use of a smoke machine in the auditorium. Units ventilated the building using a blowhard and a smoke ejector. Alarm reset. FD cleared scene.	HQ - Station HQ	Prospect

This report is limited to 500 pages. Incidents with more than one narrative will appear on multiple pages. Only REVIEWED incidents included.



Incident Date	Incident #	Dispatch Run Number	Address	Narrative	Station	Zone
11/21/2024	2024-599		289 S Washington AVE	ALARMS WERE SOUNDING UPON FD ARRIVAL. THE BUSINESS OWNER STATED ONE OF THE TENANTS IN THE APARTMENTS UPSTAIRS BURNT FOOD. FD UNITS VENTED THE APARTMENT & RESET THE ALARM.	02 - Station 02	Alert
11/22/2024	2024-600		155 Washington AVE	ALARMS WERE SOUNDING UPON FD ARRIVAL. THE ALARM ANNUNCIATOR READ AN ACTIVATION IN ZONE 3. THE BUILDING WAS SEARCHED WITH NO ACTIVATED HEADS FOUND. A WATER LEAK IN THE CEILING IN SUITE 315 WAS FOUND BUT THERE WERE NO HEADS NEAR IT. ALARM WAS UNABLE TO BE SILENCED OR RESET. A BUILDING REPRESENTATIVE WAS NOTIFIED & A NOTICE TO CORRECT WAS LEFT IN SUITE 315.	02 - Station 02	Co2
11/22/2024	2024-601		110 Vreeland AVE	Fire department dispatched to 110 Vreeland Ave for an arcing electrical wire. On arrival, units found a wire from a rooftop de-icing system arcing near the garage. PSEG electric responded in. Units traced and isolated power to the wire. Homeowner advised to contact an electrician for necessary repairs. FD released by PSEG	HQ - Station HQ	Prospect
11/22/2024	2024-602		40 W Church ST	Fire alarm set off by burnt food. No need to vent. Alarm reset.	02 - Station 02	Alert
11/23/2024	2024-603		1 N Washington AVE	Fire alarm set off by hair care products. Alarm was reset and holding.	01 - Station 01	Co2
11/23/2024	2024-604		66 S Washington	Alarm sounding on arrival. Smoke from cooking caused the activation. Owner vented, alarm reset.	02 - Station 02	Alert
11/24/2024	2024-605		406 S Washington AVE	ALARM WAS SOUNDING UPON FD ARRIVAL. THE ALARM PANEL STATED "ZONE 1 ACTIVATION" WHICH WAS A PULL STATION IN THE REAR. THE PULL STATION WAS RESET & THE ALARM WAS RESET.	02 - Station 02	Alert
11/25/2024	2024-606		235 Woodbine ST	Fire department dispatched to 235 Woodbine St, in the Bank of America Parking Lot, for a vehicle fire. On arrival, units found a vehicle with light smoke and fire showing from the front end toward the passenger side. Units used a 2.5 Gal water can to extinguish the fire. Units pulled the booster line to continue cooling engine compartment. Light overhaul completed to check for any hot spots. Vehicle owner contacted tow company to remove vehicle.	HQ - Station HQ	Prospect
11/25/2024	2024-607		195 E Clinton AVE	Fire department dispatched to 195 E Clinton Ave for a possible oven fire. On arrival, units found a slight smoke condition caused by burnt popcorn in the microwave. Units removed the microwave from the residence and ventilated using a blowhard fan. Homeowner advised to replace microwave. FD cleared scene.	HQ - Station HQ	Alert
11/25/2024	2024-608		S Washington AVE	The Bergenfield Fire Department responded to a personal injury auto accident at the intersection of South Washington Avenue and East Clinton Avenue. Upon arrival 3 vehicles were observed to have been in a collision. One vehicle was on the sidewalk but did not strike the structure. Fluid was observed to be on the ground from two vehicles and a small amount, estimated to be less than 1 gallon, had made it to a catch basin on the corner. The NJ DEP was notified for a case number: 24-11-25-1714-46. Speedy dry was applied to the affected area as well as two absorbent pigs around the catch basin. Once the tows removed the vehicles, the fire department cleared the scene.	HQ - Station HQ	Alert
11/26/2024	2024-609		160 New Jersey AVE	Interior smell of gas. Resident called PSE&G for odor of gas. PS notified FD to respond. Occupant called in smell and then left the house. FD forced entry through an elevated side window and checked the house throughout with negative results. PSE&G responded and released the FD.	HQ - Station HQ	Co2

This report is limited to 500 pages. Incidents with more than one narrative will appear on multiple pages. Only REVIEWED incidents included.



Incident Date	Incident #	Dispatch Run Number	Address	Narrative	Station	Zone
11/27/2024	2024-610		57 Luke ST 2L	Fire department dispatched to 57 Luke St for activated alarms. On arrival, units found alarm set off due to smoke from cooking in apartment 2L. Apartment vented using natural ventilation. FD cleared scene	HQ - Station HQ	Prospect
11/27/2024	2024-611		107 Greenwich DR	BFD WAS DISPATCHED TO 107 GREENWHICH DR FOR A REPORTED OVEN FIRE. THE FIRE WAS EXTINGUISHED BY THE HOMEOWNER PRIOR TO FD ARRIVAL. THE HOUSE WAS VENTILATED BY THE CREW FROM E1 AND THE HOMEOWNER WAS ADVISED NOT TO USE THE OVEN.	01 - Station 01	Prospect
11/27/2024	2024-612		11 Sylvamdur AVE	PROSPECT FIRE COMPANY WAS DISPATCHED TO 11 SYLVAMDUR AVE FOR AN ACTIVATED FIRE ALARM. THE CREW FROM ENGINE 1 INVESTIGATED AND FOUND THAT THE ALARM WAS ACTIVATED DUE TO SMOKE FROM COOKING. THE HOMEOWNER RESET THE ALARM PRIOR TO FD ARRIVAL. NATURAL VENTILATION WAS ALSO PERFORMED PRIOR TO FD ARRIVAL.	03 - Station 03	Prospect
11/28/2024	2024-613		60 Ralph ST	Reported power line down on fire in the area of Ralph St and Carlisle St. Investigation found a primary power line down between Carlisle and Cooper St. on fire in front of 60 Ralph St. PSE&G cut power to the power line upon their arrival. FD extinguished the shrubs and bushes that caught fire as a result of the downed line IFO 60 Ralph St. C.Naylis 07:15 Hrs 11/28/24	03 - Station 03	Alert
11/28/2024	2024-614		50 Williamson RD	THE FIRE DEPARTMENT WAS DISPATCHED TO THE ABOVE LOCATION FOR A SMOKE CONDITION IN THE HOUSE. UNITS ARRIVED ON SCENE TO FIND A LIGHT SMOKE CONDITION FROM COOKING. NO FIRE WAS FOUND. COOKING AREA WAS CHECKED FOR EXTENSION AND NO VENTILATION WAS NEEDED. FD UNITS RESET THE ALARM AND CLEARED THE SCENE.	01 - Station 01	Alert
11/28/2024	2024-615		32 Church ST	Upon arrival, smoke from cooking was identified as the trigger. Apartment was vented, smoke cleared, alarm reset. 740 terminated command.	02 - Station 02	Alert
11/28/2024	2024-616		1 Murray Hill TER	Upon arrival, smoke from cooking was identified as the trigger to the alarm. Dwelling was vented, alarm reset, 740 terminated command.	02 - Station 02	Alert
11/28/2024	2024-617		326 New Bridge RD	THE FIRE DEPARTMENT WAS DISPATCHED TO THE ABOVE LOCATION FOR AN ACTIVATED FIRE ALARM. UNITS ARRIVED ON SCENE TO FIND THE ALARM WAS SET OFF FROM COOKING SMOKE. NO VENTILATION WAS NEEDED. ALARM WAS RESET AND FIRE DEPARTMENT UNITS LEFT THE SCENE.	03 - Station 03	Prospect
11/28/2024	2024-618		1 Highgate TER	Cancelled enroute on a call already allocated to E1.	02 - Station 02	Prospect
11/29/2024	2024-619		249 Center ST	BERGENFIELD FIRE DEPARTMENT REQUESTED TO RESPOND MUTUAL AID TO NEW MILFORD WITH AN ENGINE TO COVER AT THEIR FIREHOUSE WHILE THEY OPERATED AT A HOUSE FIRE. E1 RESPONDED AND WAS RELEASED BY COMMAND AND RETURNED TO TOWN.	01 - Station 01	MutualAid
11/29/2024	2024-620		4 N Christie ST	THE FIRE DEPARTMENT WAS DISPATCHED TO THE ABOVE LOCATION FOR AN ACTIVATED FIRE ALARM. UNITS ARRIVED ON SCENE TO FIND THE RESIDENTS EVACUATED REPORTING THEY SET THE FIRE ALARMS FROM COOKING. FD RESET THE ALARM AND CHECKED FOR EXTENSION. UNITS PICKED UP FROM THE SCENE.	02 - Station 02	Co2

This report is limited to 500 pages. Incidents with more than one narrative will appear on multiple pages. Only REVIEWED incidents included.



Incident Date	Incident #	Dispatch Run Number	Address	Narrative	Station	Zone
11/30/2024	2024-621		155 N Washington	Upon arrival, it was determined that this was malfunction as the property is a repeat offender with a record of malfunctions, system was reset, command terminated.	02 - Station 02	Co2
11/30/2024	2024-622		65 Haven AVE	Upon arrival, the emergency was a sewage back up in the basement of the property. Help was provided to secure an elderly occupant outside for warmth and comfort, while P4 tried to determine the origin of the back up. Once Eng1 concluded the Boro sewer service was not to blame, the owner was informed of the need to contact a private plumbing service. Eng3 remained on scene until family members arrived to relieve the occupant and take over the situation. Assignment was reduced then command terminated.	02 - Station 02	Co2
12/01/2024	2024-623		266 Huber PL	it was determined that the CO unit had reached its shelf life and expired, producing the endo-o-life chirp. Homeowner was informed to replace his unit ASAP.	02 - Station 02	Co2
12/02/2024	2024-624		Lincoln AVE	Fire department dispatched to the intersection of Lincoln Ave and Galvan PI for a possible garbage truck fire. On arrival, units found a light smoke condition in the rear of a garbage truck from smoldering garbage. Fire department units used the booster line to cool and quench the garbage in the back of the truck. Crews performed overhaul to check for any residual heat or fire, checks negative. FD cleared scene.	HQ - Station HQ	Alert
12/02/2024	2024-625		244 Hickory AVE	Fire department dispatched to 244 Hickory Ave for activated CO alarms. On arrival, units found 50-100ppm CO in the basement near the boiler. Residents refused BVAC services. FD units secured the boiler using the emergency cutoff. PSEG responded in. FD released by PSEG.	HQ - Station HQ	Co2
12/03/2024	2024-626		205 State ST	Mutual Aid request from Mid Bergen Mutual Aid for an Engine to respond to Hackensack Fire HQ to stand by. However the request was canceled	01 - Station 01	MutualAid
12/04/2024	2024-627		198 N Washington AVE	The fire department was dispatched for an outside odor of burning coming from the cell tower equipment located at the North East corner of the municipal complex. Members investigated with TIC and did not observe any obvious hazards. There was no odor present, nor any signs of smokes or fire. The companies who have cellular and electrical equipment were notified by BPD to respond. After observing no status change for a reasonable about of time the FD concluded operations as there was no ETA for the responders for the companies with equipment on site. BPD was advised.	01 - Station 01	Co2
12/04/2024	2024-628		23 Ford CT	Resident burning leaves in yard.	HQ - Station HQ	Alert
12/06/2024	2024-629		20 Pelham PL	PROSPECT FIRE COMPANY WAS DISPATCHED TO 20 PELHAM PL FOR AN ACTIVATED CO ALARM. THE CREW FROM E1 INVESTIGATED AND FOUND APPROX 50 PPM OF CARBON MONOXIDE IN THE BASEMANET, PSE&G WAS REQUESTEDTHE CAUSE OF THE CO WAS TRACED BACK TO AN ISSUE WITH THE FURNACE. THE HOUSE WAS VENTILATED DOWN TO ZERO PPM AND THE FURNACE WAS TURNED OFF. THE HOMEOWNER WAS ADVISED TO AWAIT THE ARRIVAL OF PSE&G. COMMAND WAS TERMINATED.	03 - Station 03	Alert
12/07/2024	2024-630		73 Spring AVE	THE HOMEOWNER MET FD UNITS OUT FRONT STATING THE BOILER WAS UNABLE TO BE SHUT OFF. THE GAS & WATER TO THE UNIT WERE SECURED. A THOROUGH INVESTIGATION DETERMINED THERE WERE NO READINGS WITHIN THE STRUCTURE. FD UNITS WERE RELEASED BY PSE&G.	03 - Station 03	Prospect

This report is limited to 500 pages. Incidents with more than one narrative will appear on multiple pages. Only REVIEWED incidents included.



Incident Date	Incident #	Dispatch Run Number	Address	Narrative	Station	Zone
12/07/2024	2024-631		123 Sussex	PROSPECT FIRE COMPANY WAS DISPATCHED TO 123 SUSSEX RD FOR AN ACTIVATED FIRE ALARM. DC2 ARRIVED ON SCENE AND FOUND THAT THE SMOKE DETECTOR WAS SET OFF DUE TO AN UNKNOWN CAUSE AND THE ALARM WAS RESET PRIOR TO FD ARRIVAL. DC1 CANCELLED E1 WHILE ENROUTE AND TERMINATED COMMAND. -PAPER REPORT AS PER CS 305 M POLANDICK: CANCELLED ENROUTE BY CMD. ALARM RESET BEFORE ARRIVAL OF E1.	03 - Station 03	Prospect
12/08/2024	2024-632		21 Highgate	THE FIRE DEPARTMENT WAS DISPATCHED TO THE ABOVE LOCATION FOR AN ACTIVATED CO ALARM. UNITS ARRIVED ON SCENE TO FIND THE RESIDENTS OUTSIDE SAYING THE ALARM WAS GOING OFF IN THE BASEMENT. THE HOUSE WAS CHECKED WITH MULTI GAS METER WITH NO RESULTS FOUND. NO ACTIVATED HEADS WERE FOUND. RESIDENT WAS ADVISED TO CONTACT THEIR ALARM COMPANY TO HAVE THE DETECTORS AND SYSTEM CHECKED OR REPLACED.	03 - Station 03	Prospect
12/09/2024	2024-633		238 E Main ST	The fire department was dispatched to 238 E Main Street for an activated fire alarm. Upon arrival of Capt Schade, it was determined the alarm was set off by cooking smoke. There was no need to vent any smoke. Engine 3 was kept in quarters, and the alarm was reset and he cleared the scene.	01 - Station 01	Co2
12/09/2024	2024-634		128 Harrington ST	Fire department dispatched to 128 Harrington St for activated alarms. On arrival, units found an out-of-date detector on the second floor. Homeowner advised to replace detector. FD cleared scene.	HQ - Station HQ	Alert
12/10/2024	2024-635		54 Glenwood DR E	Fire department dispatched to 54 Glenwood Dr E for a smoke condition. On arrival, units found a light haze pushing from the roofline/siding on the B (south) side of the residence. Units used forcible entry to gain access to the residence through a door in the garage. E4 secured water and stretched a dry inch and three quarter line to the front door. After investigation, units determined the cause of the haze was due to an improperly venting dryer on the second floor. Homeowner advised to have the dryer inspected for any damage or ruptures, as well as have the vent from the dryer thoroughly cleaned. FD cleared scene.	HQ - Station HQ	Prospect
12/11/2024	2024-636		445 Greenwich ST	Fire department dispatched to 445 Greenwich St for activated alarms. On arrival, resident advised FD that alarms were set off due to smoke from cooking. FD units confirmed cause of alarm. No need for vent. FD cleared scene.	HQ - Station HQ	Prospect
12/12/2024	2024-637		165 Bradley AVE	Fire department dispatched to 165 Bradley Ave for activated alarms. On arrival, homeowner met FD units outside and stated alarms were set off due to construction on the second floor. No hazards found. FD cleared scene.	HQ - Station HQ	Alert
12/15/2024	2024-638		33 Lunn AVE	THE HOMEOWNER MET FD UNITS OUT FRONT STATING THE GAS FOR THE DRYER WAS SHUT OFF & WHEN TURNED BACK ON, AN ODOR OF GAS WAS FOUND. IT DISSIPATED QUICKLY. FD UNITS CHECKED THE LINES WITH THE GAS METER WITH 0 READINGS. IT WAS DETERMINED THAT THE ODOR WAS THE PILOT LIGHT NOT BEING LIT & DISSIPATED AFTER IT REIGNITED.	02 - Station 02	Co2

This report is limited to 500 pages. Incidents with more than one narrative will appear on multiple pages. Only REVIEWED incidents included.



Incident Date	Incident #	Dispatch Run Number	Address	Narrative	Station	Zone
12/15/2024	2024-639		66 Magnolia ST	THE HOMEOWNER MET FD UNITS OUT FRONT STATING HIS ALARM WENT ON & OFF SEVERAL TIMES. FURTHER INVESTIGATION FOUND THAT THE DETECTOR WAS OUT OF DATE. THE HOMEOWNER WAS ADVISED TO REPLACE THE DETECTOR.	02 - Station 02	Alert
12/15/2024	2024-640		30 Elm ST	Upon arrival. level of COs were checked and were found to be normal. Tenant was informed to replace the CO detector. DC2 terminated command.	02 - Station 02	Alert
12/16/2024	2024-641		66 S Washington AVE	ALARMS WERE SOUNDING UPON FD ARRIVAL. THE BUSINESS OWNER MET FD UNITS AT THE FRONT DOOR STATING A CANDLE WAS DUMPED OVER & SMOKED. THE BUSINESS WAS NATURALLY VENTED PRIOR TO FD ARRIVAL. THE ALARM WAS RESET.	02 - Station 02	Alert
12/16/2024	2024-642		105 Maple ST	Reported odor of something burning within the home and a possible run away boiler reported by PSE&G. FD investigation found an overheated heating blower motor caused the odor. PSE&G secured the utilities to the unit and released the FD. C.Naylis 12/17/24 13:12 Hrs.	02 - Station 02	Co2
12/18/2024	2024-643		189-191 N Washington AVE	Co.2 assisted by PSEG on scene worked to determine the source of the CO readings at 187 N Washington. Notice to correct was left, cause undetermined, possible heater malfunction.	02 - Station 02	Co2
12/18/2024	2024-644		294 S Washington AVE	Call from PD after they observe an sizeable water leak spraying from a the boiler room vent of Bldg 15 (west wall). Super arrived on scene with keys, access was gained to determine that a hot water tank pipe had disconnected from its fitting allowing pressurized water to spray uncontrollably and flood the room. Water and gas were shut off. Command was terminated.	02 - Station 02	Alert
12/18/2024	2024-645		187 N Washington AVE	THE FIRE DEPARTMENT WAS DISPATCHED TO THE ABOVE LOCATION FOR AN ACTIVATED CO ALARM. FD UNITS ARRIVED ON SCENE AND USED THE KNOX BOX TO OBTAIN KEYS TO ENTER THE STORES. UPON ENTRY TO 187 N WASH THE MULTI GAS METER BEGAN TO PICK UP READINGS OF CO AND HAD ELEVATED READINGS OF 50 IN THE REAR OF THE STORE NEAR A HEATING UNIT. FD SECURED THE GAS TO THE HEATER AND USED A BLOW HARD FAN TO VENTILATE THE STORE DOWN TO 0. FD RESECURED THE STORE AND CHECKED THE ADJOINING STORES WITH NO READINGS. KEYS RESECURED IN THE KNOX BOX. FD TERMINATED COMMAND. THE FD WAS AT THE SAME LOCATION HOURS EARLIER FOR AN AFA AND CO.	03 - Station 03	Co2
12/18/2024	2024-646		387 S Washington AVE	The fire department was requested to 387 S Washington Ave for an activated fire alarm. Upon arrival I discovered the alarm was set off due to normal cooking. There was no need to vent, and the alarm was reset. Engine 1 was returned while responding.	03 - Station 03	Alert
12/20/2024	2024-647		21 Brook ST	BFD WAS DISPATCHED TO 21 BROOK ST FOR A POSSIBLE RUNAWAY BOILER. DC2 ARRIVED AND DETERMINED THAT THE ISSUE WAS A BROKEN PIPE AND NOT A RUNAWAY BOILER. THE WATER WAS SECURED TO THE HOME AND THE SYSTEM WAS DRAINED DOWN UNTIL THE LEAK WAS STOPPED. THE HOMEOWNER WAS ADVISED TO CONTACT A PLUMBER.	01 - Station 01	Alert

This report is limited to 500 pages. Incidents with more than one narrative will appear on multiple pages. Only REVIEWED incidents included.



Incident Date	Incident #	Dispatch Run Number	Address	Narrative	Station	Zone
12/20/2024	2024-648		72 Reid AVE	PROSPECT FIRE COMPANY WAS DISPATCHED 72 REID AVE FOR AN ODOR OF GAS IN THE BASEMENT. THE CREW FROM E1 INVESTIGATED AND FOUND THAT THE ODOR OF GAS WAS CAUSED BY A LEAK NEAR THE GAS METER. THE HOUSE WAS VENTILATED NATURALLY AND WE AWAITED THE ARRIVAL OF PSE&G. PSE&G ARRIVED ON THE SCENE AND AFTER AN INVESTIGATION THE PSE&G TECH RELEASED THE FD FROM THE SCENE AND COMMAND WAS TERMINATED.	03 - Station 03	Prospect
12/21/2024	2024-649		56 Hallberg AVE	HOMEOWNER HAD WORK DONE TO THE HOME EARLIER IN THE WEEK. DEBRIS IN THE SMOKE DETECTOR LIKELY CAUSED THE ALARM ACTIVATION. REPORT AS PER CS NANCY NAYLIS.	03 - Station 03	Prospect
12/22/2024	2024-650		100 School ST	THE BUSINESS OWNER MET FD UNITS OUTSIDE STATING BURNT TOAST CAUSED THE ACTIVATION. FD UNITS SILENCED THE ALARM & VENTED THE STRUCTURE. ALARM WAS RESET & HOLDING.	02 - Station 02	Alert
12/22/2024	2024-651		511 S Prospect AVE	AFA DUE TO STEAM FROM THE SHOWER. ALARM WAS RESET PRIOR TO FD ARRIVAL.	03 - Station 03	Prospect
12/22/2024	2024-652		115-125 E Clinton AVE	UPON FD ARRIVAL, THE BUILDING SUPER EXPLAINED THAT AN OVERLOADED WASHER CAUSED THE MACHINE TO OVERHEAT & SMOKE. THE UNIT WAS SECURED, SMOKE VENTED & ALARM RESET.	02 - Station 02	Co2
12/22/2024	2024-653		123 Williamson RD	HOMEOWNER MET FD UNITS OUT FRONT STATING A SEWAGE BACKUP WAS CAUSING WATER TO OVERFLOW OUT OF THE SHOWER DRAIN & RUNNING INTO AN OUTLET. FD UNITS SECURED THE POWER TO THE HOUSE & ADVISED THE HOMEOWNER TO CALL A PLUMBER.	02 - Station 02	Alert
12/23/2024	2024-654		147 N FIRST ST	Call came in as AFA. Upon arrival, E3 proceeded to check on all floor for CO readings. All were negative. Heads were then individually checked for expiration date, batteries, dust and malfunctions. 2 heads were found to be malfunctioning (1 low battery - 2nd fl landing top of stairs and 1 malfunction, possible early end of life on sealed unit - 2nd floor bedroom Delta side). Homeowner was informed of the issues and of the necessary corrective actions to be taken.	02 - Station 02	Co2
12/23/2024	2024-655		22 Columbia AVE	Fire department dispatched to 22 Columbia Ave for activated alarms. On arrival, units found a water leak in the ceiling of the kitchen area. Units shut down water to stop leak. NTC issued for alarm system in trouble. Business owner advised to contact plumber. Building department notified. FD cleared scene.	HQ - Station HQ	Co2
12/24/2024	2024-656		24 W Church ST	ALARMS WERE SOUNDING UPON FD ARRIVAL. THE SUPER MET FD UNITS OUT FRONT STATING THE TENANT IN APARTMENT 2B BURNT FOOD. NO FIRE. CREWS FROM E3 VENTED THE APARTMENT. ALARM RESET.	02 - Station 02	Alert
12/25/2024	2024-657		48 Haring ST	PROSPECT FIRE COMPANY WAS DISPATCHED TO 48 HARING ST FOR A POSSIBLE RUNAWAY BOILER. E1 ARRIVED ON THE SCENE AFTER PSE&G AND DETERMINED THAT THIS WAS NOT A RUNAWAY BOILER BUT IT WAS A STUCK ZONE. PSE&G RELEASED E1 FROM THE SCENE.	03 - Station 03	Alert

This report is limited to 500 pages. Incidents with more than one narrative will appear on multiple pages. Only REVIEWED incidents included.



Incident Date	Incident #	Dispatch Run Number	Address	Narrative	Station	Zone
12/25/2024	2024-658		63 Mt Vernon ST	BFD WAS REQUESTED BY MID BERGEN MUTUAL AID TO THE VILLAGE OF RIDGEFIELD PARK FOR A COVER ASSIGNMENT WHILE THEY OPERATED AT A 3-ALARM FIRE ON EMERSON ST. IN THEIR TOWN. E1 STOOD BY ON MT VERNON ST AND TOOK IN NO CALLS WHILE WE STOOD BY. WE WERE RELEASED BY COMMAND.	03 - Station 03	MutualAid
12/25/2024	2024-659		29 E Central AVE	PD UNITS MET FD UNITS OUT FRONT STATING THERE WAS 2' OF WATER IN THE BASEMENT. WITH PROPER WATER GEAR DONNED, FD UNITS WENT INTO THE BASEMENT TO SECURE THE WATER, GAS & ELECTRICITY. THE HOMEOWNER WAS ADVISED TO CONTACT A PLUMBER.	02 - Station 02	Co2
12/26/2024	2024-660		31 Veterans PLZ	Fire department dispatched to 31 Veterans Plaza for activated alarms on the second floor. On arrival, units found alarm set off due to workers on scene. Workers advised to cover alarm heads until work is complete. Alarms reset. FD cleared scene.	HQ - Station HQ	Alert
12/26/2024	2024-661		20 N Washington AVE	The Bergenfield Fire Department responded to 20 N Washington Ave for an activated fire alarm. Upon arrival, alarms were sounding, but not smoke or fire was observed on a 360. Knox box 201 was used to access keys to make entry. Entry was made through a rear door and a water leak was observed with fallen ceiling tiles in the office of the carpet store. Members were able to raise the resident of the second floor. Upon entry, water was observed coming through the light fixture and smoke detector. The resident advised us his aunt lived on the third floor and wasn't sure if she was home. He granted permission to force the door to the apartment as the door was locked and Knox keys did not work for that door. Entry was gained with some damage to the door, but negative for occupants. Access made to the bathroom where hot water was turned on and running. The drain was blocked with gloves and a container of food was in the sink in what appeared to be an attempt to heat food. The water was turned off. The fire alarm was silenced but unable to reset. It was also in trouble. Water was also coming through the light fixture on the second floor landing. The light cover was taken down to let the water drain. The resident was advised of what to do. A notice to correct was left for the fire alarm system to be checked, and noted the water through the electrical fixture. The note was left in the office of Allied Carpet.	01 - Station 01	Alert
12/27/2024	2024-662		387 S Washington AVE	The Bergenfield Fire Department responded to 387 S Washington Avenue for an activated fire alarm. Upon arrival, there were no alarms sounding. Members made contact with the employee of the bakery who reported that the alarm went off because of normal cooking. A check of the building proved negative for smoke or fire. The activated smoke detector was located in the area near the cooking. With no need to ventilate the smoke, the fire alarm system was reset. The owner did report the employee silenced the fire alarm prior to the arrival of the fire department. He was advised no to do that and could be subject to monetary fines in the future.	01 - Station 01	Alert
12/27/2024	2024-663		213 Highland AVE	Fire department dispatched in front of 213 Highland Ave for an odor of natural gas. On arrival, units observed readings of 1-2% LEL of natural gas along with several strong odors. PSEG responded to scene. FD released by PSEG	HQ - Station HQ	Alert
12/27/2024	2024-664		133 N Queen ST	Fire department dispatched in front of 133 N Queen St for a gas leak. On arrival, units found a road crew from Veolia struck and broke a gas line while digging. PSEG responded in. FD released by PSEG	HQ - Station HQ	Alert

This report is limited to 500 pages. Incidents with more than one narrative will appear on multiple pages. Only REVIEWED incidents included.



Incident Date	Incident #	Dispatch Run Number	Address	Narrative	Station	Zone
12/27/2024	2024-665		29 Harriet AVE	BFD WAS REQUESTED FOR A FIRE IN THE HOUSE AT 29 HARRIET. DC2 ARRIVED ON THE SCENE AND DETERMINED THAT THE FIRE WAS EXTINGUISHED USING A DRY CHEM EXTINGUISHER PRIOR TO BFD ARRIVAL. THE CREWS FROM E1 AND E4 VENTILATED THE HOUSE AND CHECKED FOR EXTENSION. NO FIRE EXTENSION WAS FOUND. AFTER VENTILATION WAS COMPLETED THE HOUSE WAS TURNED BACK OVER TO THE HOMEOWNER.	03 - Station 03	Prospect
12/29/2024	2024-666		12 Smith AVE	Upon arrival, a candle setting fire to a shelf was the culprit. Dwelling was cleared of any smoke, said shelf removed and placed outside. Command was terminated.	02 - Station 02	Alert
12/29/2024	2024-667		50 Williamson RD	THE FIRE DEPARTMENT WAS DISPATCHED TO A REPORTED ODOR OF SOMETHING BURNING. THE FIRE DEPARTMENT ARRIVED ON SCENE AND FOUND A SLIGHT ODOR IN THE BASEMENT IN THE AREA OF THE HVAC FURNACE. NO GAS OR CO READINGS IN THE HOUSE. EMS WAS ONSCENE TO EVALUATE THE RESIDENTS WHO WERE COMPLAINING OF HEADACHES. PART OF THE HVAC FILTER HAD FALLEN APART AND WAS BURNING INSIDE THE FURNACE. THE FURNACE WAS SHUT OFF AND FILTER REMOVED. HOMEOWNER WAS ADVISED TO HAVE THE HVAC CHECKED. FD UNITS PICKED UP FROM THE SCENE AND COMMAND WAS TERMINATED.	03 - Station 03	Alert
12/29/2024	2024-668		81 S Van Brunt St	Mid-Bergen Mutual Aid requested a ladder to respond to cover the City of Englewood while they operated at a fire on Orchard St in their city. Ladder 2 and DC 2 responded and covered Englewood Fire HQ. C.Naylis 12/30/24 11:57 Hrs.	03 - Station 03	MutualAid
12/31/2024	2024-669		75 N Vivyen ST	The fire department was requested to 75 N Vivyen St for an inside odor of gas. Upon arrival, the resident reported that she had accidentally left a burner on the stove while she was gone for approximately 12 hours. Members checked the house and found no odors or readings. PSE&G arrived on scene and confirmed no readings before releasing the fire department. The scene was then turned over to PSE&G and the resident.	01 - Station 01	Alert
12/31/2024	2024-670		S Washington AVE	The fire department was dispatched to an outside odor of smoke. Upon arrival, there was no visible signs of smoke, and no odor detected. Engine 3 checked the area businesses including all of the Foster Village Shopping Center front and back, the top section of Howard Dr, and Sylvan Ave with negative results. Engine 3 then returned to quarters with nothing found.	01 - Station 01	Alert
12/31/2024	2024-671		22 Greenwich ST	Dispatched for struck gas line. No gas line struck, no hazard.	HQ - Station HQ	Prospect
12/31/2024	2024-672		43 Sugden ST	Dispatched for activated smoke detector. Upon arrival FD was denied entry by the female occupant	HQ - Station HQ	Prospect
12/31/2024	2024-673		41 Ivy LN	Dispatched for outdoor odor of natural gas. FD units checked parking lot as well as 41 Ivy Ln. with negative results.	HQ - Station HQ	Prospect
12/31/2024	2024-674		135 Hickory AVE	Dispatched for vehicle vs house. FD checked all utilities and stood by while vehicle was removed from the side of the house. The vehicle left a 3x3 hole in the home. Building dept. was notified	HQ - Station HQ	Co2

This report is limited to 500 pages. Incidents with more than one narrative will appear on multiple pages. Only REVIEWED incidents included.



Incident Date	Incident #	Dispatch Run Number	Address	Narrative	Station	Zone
12/31/2024	2024-675		223 S Washington AVE	BFD WAS REQUESTED TO 223 S WASHINGTON AVE FOR AN ACTIVATED CO ALARM. ALARM ACTIVATED AFTER THE DETECTOR WAS REMOVED. THE DETECTOR WAS SOUNDING A SINGLE CHIRP EVERY 3 MINUTES. THE BUILDING WAS CHECKED THROUGHOUT WITH 2 MULTIGAS METERS AND NO READINGS WERE FOUND. THE BUILDING REP WAS ADVISED TO CONTACT THEIR ALARM COMPANY.	01 - Station 01	Alert
12/31/2024	2024-676		81 S Van Brunt ST	The Bergenfield Fire Department was requested by Mid Bergen mutual aid to send a ladder truck to the City of Englewood to cover their fire house during a 2nd Alarm structure fire. While enroute the ladder was redirected to the scene, and the rescue was then also requested to respond to the scene at 64 Tracey Place. Upon arrival of ladder 2, the crew was directed to be the FAST Team. Members conducted a 360 survey of the scene, and then identified places where ground ladders were needed and deployed them from Englewood and Hackensack ladder companies. The rescue crew stood by on scene until released by command.	03 - Station 03	MutualAid
12/31/2024	2024-677		144 Sussex RD	BFD WAS REQUESTED FOR AN ODOR OF BURNING. THE CREW FROM RESCUE 1 INVESTIGATED AND FOUND THAT THERE WAS A SLIGHT ODOR OF BURING IN THE BASEMENT THAT QUICKLY DISSIPATED. THE ISSUE WAS LIKELY CAUSED BY A LIGHTING STRIKE IN THE AREA. THE HOMEOWNER STATED THAT THE LIGHTS GOT VERY BRIGHT THEN BLEW OUT. THE HOMEOWNER THEN REPLACED THE LIGHT BULBS AND EVERYTHING WORKED FINE. THE HOMEOWNER WAS ADVISED TO FOLLOW UP WITH AN ELECTRICIAN.	03 - Station 03	Prospect
12/31/2024	2024-678		21 Briarcliffe RD	BFD WAS REQUESTED TO 144 SUSSEX FOR AN ODOR OF BURNING. WHEN DC2 ARRIVED ON SCENE THE NEIGHBOR FROM 21 BRIARCLIFFE RD STATED THAT HE HAD SMOKE IN THE HOUSE AND AN ODOR OF BURNING. THE CREW FROM E1 INVESTIGATED AND FOUND THAT THERE WAS A BURNED UP CABLE LINE THAT RAN NEAR THE ELECTRICAL PANEL. IT IS BELIEVED THAT THERE WAS A LIGHTING STRIKE TO THE UTILITY POLE OUTSIDE THAT CAUSED THE CABLE LINE TO SHORT OUT AND BURN AND ALSO CAUSED A VOLTAGE SPIKE IN THE HOME. THE VOLTAGE SPIKE CAUSED THE LIGHTS IN THE HOME TO GET BRIGHT AND THEN THE LIGHTS BLEW OUT ACCORDING TO THE HOMEOWNER. THE WHOLE HOUSE WAS CHECKED THROUHOUT AND NO ISSUES WERE FOUND. THE MAIN BREAKER IN THE ELECTRICAL PANEL WAS SHUT OFF AND THEN PSE&G REMOVED THE METER PAN ON THE HOME. THE SMOKE WAS VENTILATED FROM THE HOME AND THEN THE HOUSE WAS RECHEKED AND NOTHING WAS FOUND. THE HOMEOWNER WAS ADVISED TO CONTACT AN ELECTRICIAN. ENGINE 1 WAS THEN RELEASED FROM THE SCENE.	03 - Station 03	Prospect

Incident Date	Incident #	Dispatch Run Number	Address	Narrative	Station	Zone
12/31/2024	2024-679		29 Briarcliffe	BFD WAS DISPATCHED TO 29 BRIARCLIFF RD FOR A REPORTED FIRE. DC2 ARRIVED ON THE SCENE AND DETERMINED THAT THERE WAS A FIRE ON THE EXTERIOR CORNER OF THE HOUSE. ENGINE1 LAID SUPPLY HOSE FROM THE 1ST DUE HYDRANT TO THE FIRE SCENE AND STRETCHED ONE 1 3/4 HANDLINE TO THE REAR OF THE STRUCTURE FOR EXTINGUISHMENT. ONCE THE FIRE WAS KNOCKED DOWN, THE CREW FROM RESCUE 1 ASSISTED IN OPENING UP THE SIDE AND REAR CORNER OF THE HOUSE TO CHECK FOR FURTHER FIRE SPREAD. SOME FIRE SPREAD WAS FOUND AND EXTINGUISHED. THE OTHER CREW FROM RESCUE 1 PERFORMED SEARCHES OF THE ENTIRE STRUCTURE WHILE ALL CHECKED NEGATIVE. ONCE SEARCHES WERE COMPLETED, THE CREW FROM RESCUE 1 OPENED UP THE C-D CORNER ON ALL FLOORS IN THE INTERIOR TO CHECK FOR EXTENSION. NO INTERIOR EXTENSION WAS FOUND. AFTER THE FIRE WAS FULLY EXTINGUISHED AND OVERHAULED THE SMOKE FROM THE HOUSE WAS VENTILATED AND THE HOSE LINES WERE PICKED UP. ENGINE 1 AND RESCUE 1 WERE THEN RELEASED FROM THE SCENE.	03 - Station 03	Prospect

This report is limited to 500 pages. Incidents with more than one narrative will appear on multiple pages. Only REVIEWED incidents included.



emergencyreporting.com

Doc Id: 830

Page # 14 of 14