



# Invoice

Please Send Payment to:  
217 Halls Mill Road  
Lebanon, NJ 08833

Branch Office:  
Washington Crossing, PA

Date 5/7/2019 Invoice # 2019-0653

Phone # (908)-823-4367 Fax # (866) 844-3086

## Bill To

SCPC - Sellars  
301 Old York Road  
Bridgewater, NJ 08807

## Ship To

SCPC - Sellars  
301 Old York Road  
Bridgewater, NJ 08807

| P.O. Number | Terms     | Ship     | SME Number | Proposal # | Service Report # | Due Date | Project |
|-------------|-----------|----------|------------|------------|------------------|----------|---------|
| 154569      | Net 30 SD | 5/7/2019 | 19-0058    |            |                  | 7/6/2019 |         |

| Quantity | Item Code               | Description                                                          | Price Each | Amount |
|----------|-------------------------|----------------------------------------------------------------------|------------|--------|
|          |                         | Colonial Park. Tech put all on one ticket                            |            |        |
| 45       | TAG                     | Yearly tagging and inspection of fire extinguisher - All Types       | 2.35       | 105.75 |
| 4        | Refill                  | Refilling of a Fire Extinguisher                                     | 7.50       | 30.00  |
| 4        | Regular/Service Re...   | Service charge for refilling, recharging or replacing a broken gauge | 5.00       | 20.00  |
| 2        | Recharge 2.5 ABC        | Recharge of a 2.5 ABC fire extinguishers                             | 5.00       | 10.00  |
| 0        | Recharge 5# ABC         | Recharge of a 5# ABC fire Extinguisher                               | 15.00      | 0.00   |
| 2        | Recharge 10/20AB...     | Recharge of a 10/20 ABC or Water                                     | 20.00      | 40.00  |
| 0        | Recharge K Class        | Recharge of a K Class Fire Extinguisher                              | 50.00      | 0.00   |
| 0        | Recharge CO2,BC ...     | Recharge of any CO2 5 and 10#, any size BC and PKP 5 and 10#.        | 5.00       | 0.00   |
| 2        | 6 - Year Inspection ... | 6 - Year Inspection 2.5 ABC                                          | 8.00       | 16.00  |
| 2        | 6 - Year Inspection ... | 6 Year Inspection of a 5/10/20 ABC                                   | 10.00      | 20.00  |
| 0        | 6 YR - Hal/Water/...    | Hal/Water/Co2/BC/PKP                                                 | 8.00       | 0.00   |
| 0        | 2.5 ABC                 | Hydrostatic testing of 2.5# ABC Fire Extinguisher                    | 5.00       | 0.00   |
| 0        | 5,10,20 ABC             | Hydrostatic testing of 5,10 or 20# ABC Fire Extinguisher             | 20.00      | 0.00   |

Billing Questions?? Email - Sales@fireandsecuritytech.com

**Sales Tax (6.625%)** \$0.00

**Total** \$241.75

\*\*\* To avoid an annual 18% service charge, please pay before invoice due date. \*\*\*



# Invoice

Please Send Payment to:  
217 Halls Mill Road  
Lebanon, NJ 08833

Branch Office:  
Washington Crossing, PA

Date 5/7/2019 Invoice # 2019-0632

Phone # (908)-823-4367 Fax # (866) 844-3086

## Bill To

SCPC - Envirmental Education Center  
190 Lord Stirling Rd  
Basking Ridge, NJ 07920

## Ship To

SCPC - Envirmental Education Center  
190 Lord Stirling Rd  
Basking Ridge, NJ 07920

| P.O. Number | Terms                   | Ship                                                                 | SME Number | Proposal # | Service Report # | Due Date | Project |
|-------------|-------------------------|----------------------------------------------------------------------|------------|------------|------------------|----------|---------|
| 154569      | Net 30 SD               | 5/7/2019                                                             | 19-0058    |            |                  | 7/6/2019 |         |
| Quantity    | Item Code               | Description                                                          | Price Each | Amount     |                  |          |         |
| 32          | TAG                     | Yearly tagging and inspection of fire extinguisher - All Types       | 2.35       | 75.20      |                  |          |         |
| 9           | Refill                  | Refilling of a Fire Extinguisher                                     | 7.50       | 67.50      |                  |          |         |
| 9           | Regular/Service Re...   | Service charge for refilling, recharging or replacing a broken gauge | 5.00       | 45.00      |                  |          |         |
| 0           | Recharge 2.5 ABC        | Recharge of a 2.5 ABC fire extinguishers                             | 5.00       | 0.00       |                  |          |         |
| 0           | Recharge 5# ABC         | Recharge of a 5# ABC fire Extinguisher                               | 15.00      | 0.00       |                  |          |         |
| 9           | Recharge 10/20AB...     | Recharge of a 10/20 ABC or Water                                     | 20.00      | 180.00     |                  |          |         |
| 0           | Recharge K Class        | Recharge of a K Class Fire Extinguisher                              | 50.00      | 0.00       |                  |          |         |
| 0           | Recharge CO2,BC ...     | Recharge of any CO2 5 and 10#, any size BC and PKP 5 and 10#.        | 5.00       | 0.00       |                  |          |         |
| 0           | 6 - Year Inspection ... | 6 - Year Inspection 2.5 ABC                                          | 8.00       | 0.00       |                  |          |         |
| 9           | 6 - Year Inspection ... | 6 Year Inspection of a 5/10/20 ABC                                   | 10.00      | 90.00      |                  |          |         |
| 0           | 6 YR - Hal/Water/...    | Hal/Water/Co2/BC/PKP                                                 | 8.00       | 0.00       |                  |          |         |
| 0           | 2.5 ABC                 | Hydrostatic testing of 2.5# ABC Fire Extinguisher                    | 5.00       | 0.00       |                  |          |         |
| 9           | 5,10,20 ABC             | Hydrostatic testing of 5,10 or 20# ABC Fire Extinguisher             | 20.00      | 180.00     |                  |          |         |

Billing Questions?? Email - Sales@fireandsecuritytech.com

**Sales Tax (6.625%)** \$0.00

\*\*\* To avoid an annual 18% service charge, please pay before invoice due date. \*\*\*

**Total** \$637.70



# Invoice

Please Send Payment to:  
217 Halls Mill Road  
Lebanon, NJ 08833

Branch Office:  
Washington Crossing, PA

Date 5/7/2019 Invoice # 2019-0630

Phone # (908)-823-4367 Fax # (866) 844-3086

## Bill To

SCPC - Leisure Services  
PO Box 5327  
North Branch, NJ 08876

## Ship To

Ross Mansion  
Maple Ave  
Basking Ridge, NJ 07920

| P.O. Number | Terms     | Ship     | SME Number | Proposal # | Service Report # | Due Date | Project |
|-------------|-----------|----------|------------|------------|------------------|----------|---------|
| 154569      | Net 30 SD | 5/7/2019 | 19-0058    |            |                  | 7/6/2019 |         |

| Quantity | Item Code               | Description                                                          | Price Each | Amount |
|----------|-------------------------|----------------------------------------------------------------------|------------|--------|
| 10       | TAG                     | Yearly tagging and inspection of fire extinguisher - All Types       | 2.35       | 23.50  |
| 6        | Refill                  | Refilling of a Fire Extinguisher                                     | 7.50       | 45.00  |
| 6        | Regular/Service Re...   | Service charge for refilling, recharging or replacing a broken gauge | 5.00       | 30.00  |
| 0        | Recharge 2.5 ABC        | Recharge of a 2.5 ABC fire extinguishers                             | 5.00       | 0.00   |
| 0        | Recharge 5# ABC         | Recharge of a 5# ABC fire Extinguisher                               | 15.00      | 0.00   |
| 6        | Recharge 10/20AB...     | Recharge of a 10/20 ABC or Water                                     | 20.00      | 120.00 |
| 0        | Recharge K Class        | Recharge of a K Class Fire Extinguisher                              | 50.00      | 0.00   |
| 0        | Recharge CO2,BC ...     | Recharge of any CO2 5 and 10#, any size BC and PKP 5 and 10#.        | 5.00       | 0.00   |
| 0        | 6 - Year Inspection ... | 6 - Year Inspection 2.5 ABC                                          | 8.00       | 0.00   |
| 6        | 6 - Year Inspection ... | 6 Year Inspection of a 5/10/20 ABC                                   | 10.00      | 60.00  |
| 0        | 6 YR - Hal/Water/...    | Hal/Water/Co2/BC/PKP                                                 | 8.00       | 0.00   |
| 0        | 2.5 ABC                 | Hydrostatic testing of 2.5# ABC Fire Extinguisher                    | 5.00       | 0.00   |
| 6        | 5,10,20 ABC             | Hydrostatic testing of 5,10 or 20# ABC Fire Extinguisher             | 20.00      | 120.00 |

Billing Questions?? Email - Sales@fireandsecuritytech.com

Sales Tax (6.625%) \$0.00

\*\*\* To avoid an annual 18% service charge, please pay before invoice due date. \*\*\*

**Total** \$398.50



# Invoice

Please Send Payment to:  
217 Halls Mill Road  
Lebanon, NJ 08833

Branch Office:  
Washington Crossing, PA

Date 5/7/2019 Invoice # 2019-0622

Phone # (908)-823-4367 Fax # (866) 844-3086

## Bill To

SCPC - Sellars  
301 Old York Road  
Bridgewater, NJ 08807

## Ship To

North Branch Park - Headquarters  
355 Milltown Road  
Bridgewater, NJ 08807

| P.O. Number | Terms     | Ship     | SME Number | Proposal # | Service Report # | Due Date | Project |
|-------------|-----------|----------|------------|------------|------------------|----------|---------|
| 154569      | Net 30 SD | 5/7/2019 | 19-0058    |            |                  | 7/6/2019 |         |

| Quantity | Item Code               | Description                                                          | Price Each | Amount |
|----------|-------------------------|----------------------------------------------------------------------|------------|--------|
| 33       | TAG                     | Yearly tagging and inspection of fire extinguisher - All Types       | 2.35       | 77.55  |
| 7        | Refill                  | Refilling of a Fire Extinguisher                                     | 7.50       | 52.50  |
| 7        | Regular/Service Re...   | Service charge for refilling, recharging or replacing a broken gauge | 5.00       | 35.00  |
| 0        | Recharge 2.5 ABC        | Recharge of a 2.5 ABC fire extinguishers                             | 5.00       | 0.00   |
| 0        | Recharge 5# ABC         | Recharge of a 5# ABC fire Extinguisher                               | 15.00      | 0.00   |
| 7        | Recharge 10/20AB...     | Recharge of a 10/20 ABC or Water                                     | 20.00      | 140.00 |
| 0        | Recharge K Class        | Recharge of a K Class Fire Extinguisher                              | 50.00      | 0.00   |
| 0        | Recharge CO2,BC ...     | Recharge of any CO2 5 and 10#, any size BC and PKP 5 and 10#.        | 5.00       | 0.00   |
| 0        | 6 - Year Inspection ... | 6 - Year Inspection 2.5 ABC                                          | 8.00       | 0.00   |
| 7        | 6 - Year Inspection ... | 6 Year Inspection of a 5/10/20 ABC                                   | 10.00      | 70.00  |
| 0        | 6 YR - Hal/Water/...    | Hal/Water/Co2/BC/PKP                                                 | 8.00       | 0.00   |
| 0        | 2.5 ABC                 | Hydrostatic testing of 2.5# ABC Fire Extinguisher                    | 5.00       | 0.00   |
| 3        | 5,10,20 ABC             | Hydrostatic testing of 5,10 or 20# ABC Fire Extinguisher             | 20.00      | 60.00  |

Billing Questions?? Email - Sales@fireandsecuritytech.com

**Sales Tax (6.625%)** \$0.00

\*\*\* To avoid an annual 18% service charge, please pay before invoice due date. \*\*\*

**Total** \$435.05



# Invoice

Please Send Payment to:  
217 Halls Mill Road  
Lebanon, NJ 08833

Branch Office:  
Washington Crossing, PA

Date 5/7/2019 Invoice # 2019-0621

Phone # (908)-823-4367 Fax # (866) 844-3086

## Bill To

SCPC - Sellars  
301 Old York Road  
Bridgewater, NJ 08807

## Ship To

North Branch Park - Maintenance  
355 Milltown Road  
Bridgewater, NJ 08807

| P.O. Number | Terms                   | Ship                                                                 | SME Number | Proposal # | Service Report # | Due Date | Project |
|-------------|-------------------------|----------------------------------------------------------------------|------------|------------|------------------|----------|---------|
| 154569      | Net 30 SD               | 5/7/2019                                                             | 19-0058    |            |                  | 7/6/2019 |         |
| Quantity    | Item Code               | Description                                                          | Price Each | Amount     |                  |          |         |
| 19          | TAG                     | Yearly tagging and inspection of fire extinguisher - All Types       | 2.35       | 44.65      |                  |          |         |
| 5           | Refill                  | Refilling of a Fire Extinguisher                                     | 7.50       | 37.50      |                  |          |         |
| 5           | Regular/Service Re...   | Service charge for refilling, recharging or replacing a broken gauge | 5.00       | 25.00      |                  |          |         |
| 0           | Recharge 2.5 ABC        | Recharge of a 2.5 ABC fire extinguishers                             | 5.00       | 0.00       |                  |          |         |
| 0           | Recharge 5# ABC         | Recharge of a 5# ABC fire Extinguisher                               | 15.00      | 0.00       |                  |          |         |
| 5           | Recharge 10/20AB...     | Recharge of a 10/20 ABC or Water                                     | 20.00      | 100.00     |                  |          |         |
| 0           | Recharge K Class        | Recharge of a K Class Fire Extinguisher                              | 50.00      | 0.00       |                  |          |         |
| 0           | Recharge CO2,BC ...     | Recharge of any CO2 5 and 10#, any size BC and PKP 5 and 10#.        | 5.00       | 0.00       |                  |          |         |
| 0           | 6 - Year Inspection ... | 6 - Year Inspection 2.5 ABC                                          | 8.00       | 0.00       |                  |          |         |
| 5           | 6 - Year Inspection ... | 6 Year Inspection of a 5/10/20 ABC                                   | 10.00      | 50.00      |                  |          |         |
| 0           | 6 YR - Hal/Water/...    | Hal/Water/Co2/BC/PKP                                                 | 8.00       | 0.00       |                  |          |         |
| 0           | 2.5 ABC                 | Hydrostatic testing of 2.5# ABC Fire Extinguisher                    | 5.00       | 0.00       |                  |          |         |
| 3           | 5,10,20 ABC             | Hydrostatic testing of 5,10 or 20# ABC Fire Extinguisher             | 20.00      | 60.00      |                  |          |         |

Billing Questions?? Email - Sales@fireandsecuritytech.com

**Sales Tax (6.625%)** \$0.00

\*\*\* To avoid an annual 18% service charge, please pay before invoice due date. \*\*\*

**Total** \$317.15



# Invoice

Please Send Payment to:  
217 Halls Mill Road  
Lebanon, NJ 08833

Branch Office:  
Washington Crossing, PA

Date 5/7/2019 Invoice # 2019-0641

Phone # (908)-823-4367 Fax # (866) 844-3086

**Bill To**

SCPC - Sellars  
301 Old York Road  
Bridgewater, NJ 08807

**Ship To**

SCPC - Sellars  
301 Old York Road  
Bridgewater, NJ 08807

| P.O. Number | Terms                   | Ship                                                                 | SME Number | Proposal # | Service Report # | Due Date | Project |
|-------------|-------------------------|----------------------------------------------------------------------|------------|------------|------------------|----------|---------|
| 154569      | Net 30 SD               | 5/7/2019                                                             | 19-0058    |            |                  | 7/6/2019 |         |
| Quantity    | Item Code               | Description                                                          | Price Each | Amount     |                  |          |         |
|             |                         | Bucks Gardens                                                        |            |            |                  |          |         |
| 13          | TAG                     | Yearly tagging and inspection of fire extinguisher - All Types       | 2.35       | 30.55      |                  |          |         |
| 3           | Refill                  | Refilling of a Fire Extinguisher                                     | 7.50       | 22.50      |                  |          |         |
| 3           | Regular/Service Re...   | Service charge for refilling, recharging or replacing a broken gauge | 5.00       | 15.00      |                  |          |         |
| 0           | Recharge 2.5 ABC        | Recharge of a 2.5 ABC fire extinguishers                             | 5.00       | 0.00       |                  |          |         |
| 1           | Recharge 5# ABC         | Recharge of a 5# ABC fire Extinguisher                               | 15.00      | 15.00      |                  |          |         |
| 2           | Recharge 10/20AB...     | Recharge of a 10/20 ABC or Water                                     | 20.00      | 40.00      |                  |          |         |
| 0           | Recharge K Class        | Recharge of a K Class Fire Extinguisher                              | 50.00      | 0.00       |                  |          |         |
| 0           | Recharge CO2,BC ...     | Recharge of any CO2 5 and 10#, any size BC and PKP 5 and 10#.        | 5.00       | 0.00       |                  |          |         |
| 0           | 6 - Year Inspection ... | 6 - Year Inspection 2.5 ABC                                          | 8.00       | 0.00       |                  |          |         |
| 3           | 6 - Year Inspection ... | 6 Year Inspection of a 5/10/20 ABC                                   | 10.00      | 30.00      |                  |          |         |
| 0           | 6 YR - Hal/Water/...    | Hal/Water/Co2/BC/PKP                                                 | 8.00       | 0.00       |                  |          |         |
| 0           | 2.5 ABC                 | Hydrostatic testing of 2.5# ABC Fire Extinguisher                    | 5.00       | 0.00       |                  |          |         |
| 3           | 5,10,20 ABC             | Hydrostatic testing of 5,10 or 20# ABC Fire Extinguisher             | 20.00      | 60.00      |                  |          |         |

Billing Questions?? Email - Sales@fireandsecuritytech.com

**Sales Tax (6.625%)** \$0.00

\*\*\* To avoid an annual 18% service charge, please pay before invoice due date. \*\*\*

**Total** \$213.05



# Invoice

Please Send Payment to:  
217 Halls Mill Road  
Lebanon, NJ 08833

Branch Office:  
Washington Crossing, PA

Date 5/7/2019 Invoice # 2019-0628

Phone # (908)-823-4367 Fax # (866) 844-3086

## Bill To

SCPC - Sellars  
301 Old York Road  
Bridgewater, NJ 08807

## Ship To

SCPC - Sellars  
301 Old York Road  
Bridgewater, NJ 08807

| P.O. Number | Terms     | Ship     | SME Number | Proposal # | Service Report # | Due Date | Project |
|-------------|-----------|----------|------------|------------|------------------|----------|---------|
| 154569      | Net 30 SD | 5/7/2019 | 19-0058    |            |                  | 7/6/2019 |         |

| Quantity | Item Code               | Description                                                          | Price Each | Amount |
|----------|-------------------------|----------------------------------------------------------------------|------------|--------|
|          |                         | Merril House                                                         |            |        |
| 7        | TAG                     | Yearly tagging and inspection of fire extinguisher - All Types       | 2.35       | 16.45  |
| 4        | Refill                  | Refilling of a Fire Extinguisher                                     | 7.50       | 30.00  |
| 4        | Regular/Service Re...   | Service charge for refilling, recharging or replacing a broken gauge | 5.00       | 20.00  |
| 0        | Recharge 2.5 ABC        | Recharge of a 2.5 ABC fire extinguishers                             | 5.00       | 0.00   |
| 0        | Recharge 5# ABC         | Recharge of a 5# ABC fire Extinguisher                               | 15.00      | 0.00   |
| 4        | Recharge 10/20AB...     | Recharge of a 10/20 ABC or Water                                     | 20.00      | 80.00  |
| 0        | Recharge K Class        | Recharge of a K Class Fire Extinguisher                              | 50.00      | 0.00   |
| 0        | Recharge CO2,BC ...     | Recharge of any CO2 5 and 10#, any size BC and PKP 5 and 10#.        | 5.00       | 0.00   |
| 0        | 6 - Year Inspection ... | 6 - Year Inspection 2.5 ABC                                          | 8.00       | 0.00   |
| 4        | 6 - Year Inspection ... | 6 Year Inspection of a 5/10/20 ABC                                   | 10.00      | 40.00  |
| 0        | 6 YR - Hal/Water/...    | Hal/Water/Co2/BC/PKP                                                 | 8.00       | 0.00   |
| 0        | 2.5 ABC                 | Hydrostatic testing of 2.5# ABC Fire Extinguisher                    | 5.00       | 0.00   |
| 4        | 5,10,20 ABC             | Hydrostatic testing of 5,10 or 20# ABC Fire Extinguisher             | 20.00      | 80.00  |

Billing Questions?? Email - Sales@fireandsecuritytech.com

Sales Tax (6.625%) \$0.00

\*\*\* To avoid an annual 18% service charge, please pay before invoice due date. \*\*\*

**Total** \$266.45



# Invoice

Please Send Payment to:  
217 Halls Mill Road  
Lebanon, NJ 08833

Branch Office:  
Washington Crossing, PA

Date 5/7/2019 Invoice # 2019-0623

Phone # (908)-823-4367 Fax # (866) 844-3086

## Bill To

SCPC - Sellars  
301 Old York Road  
Bridgewater, NJ 08807

## Ship To

North Branch Park - Stocker  
355 Milltown Road  
Bridgewater, NJ 08807

| P.O. Number | Terms                   | Ship                                                                 | SME Number | Proposal # | Service Report # | Due Date | Project |
|-------------|-------------------------|----------------------------------------------------------------------|------------|------------|------------------|----------|---------|
| 154569      | Net 30 SD               | 5/7/2019                                                             | 19-0058    |            |                  | 7/6/2019 |         |
| Quantity    | Item Code               | Description                                                          | Price Each | Amount     |                  |          |         |
| 19          | TAG                     | Yearly tagging and inspection of fire extinguisher - All Types       | 2.35       | 44.65      |                  |          |         |
| 3           | Refill                  | Refilling of a Fire Extinguisher                                     | 7.50       | 22.50      |                  |          |         |
| 3           | Regular/Service Re...   | Service charge for refilling, recharging or replacing a broken gauge | 5.00       | 15.00      |                  |          |         |
| 0           | Recharge 2.5 ABC        | Recharge of a 2.5 ABC fire extinguishers                             | 5.00       | 0.00       |                  |          |         |
| 0           | Recharge 5# ABC         | Recharge of a 5# ABC fire Extinguisher                               | 15.00      | 0.00       |                  |          |         |
| 3           | Recharge 10/20AB...     | Recharge of a 10/20 ABC or Water                                     | 20.00      | 60.00      |                  |          |         |
| 0           | Recharge K Class        | Recharge of a K Class Fire Extinguisher                              | 50.00      | 0.00       |                  |          |         |
| 0           | Recharge CO2,BC ...     | Recharge of any CO2 5 and 10#, any size BC and PKP 5 and 10#.        | 5.00       | 0.00       |                  |          |         |
| 0           | 6 - Year Inspection ... | 6 - Year Inspection 2.5 ABC                                          | 8.00       | 0.00       |                  |          |         |
| 3           | 6 - Year Inspection ... | 6 Year Inspection of a 5/10/20 ABC                                   | 10.00      | 30.00      |                  |          |         |
| 0           | 6 YR - Hal/Water/...    | Hal/Water/Co2/BC/PKP                                                 | 8.00       | 0.00       |                  |          |         |
| 0           | 2.5 ABC                 | Hydrostatic testing of 2.5# ABC Fire Extinguisher                    | 5.00       | 0.00       |                  |          |         |
| 2           | 5,10,20 ABC             | Hydrostatic testing of 5,10 or 20# ABC Fire Extinguisher             | 20.00      | 40.00      |                  |          |         |

Billing Questions?? Email - Sales@fireandsecuritytech.com

**Sales Tax (6.625%)** \$0.00

\*\*\* To avoid an annual 18% service charge, please pay before invoice due date. \*\*\*

**Total** \$212.15



# Invoice

Please Send Payment to:  
217 Halls Mill Road  
Lebanon, NJ 08833

Branch Office:  
Washington Crossing, PA

Date 5/7/2019  
Invoice # 2019-0624

Phone # (908)-823-4367 Fax # (866) 844-3086

## Bill To

SCPC - Sellars  
301 Old York Road  
Bridgewater, NJ 08807

## Ship To

Reeves Art Center  
Stanton Road  
Branchburg, NJ 08876

| P.O. Number | Terms     | Ship     | SME Number | Proposal # | Service Report # | Due Date | Project |
|-------------|-----------|----------|------------|------------|------------------|----------|---------|
| 154569      | Net 30 SD | 5/7/2019 | 19-0058    |            |                  | 7/6/2019 |         |

| Quantity | Item Code               | Description                                                          | Price Each | Amount |
|----------|-------------------------|----------------------------------------------------------------------|------------|--------|
| 5        | TAG                     | Yearly tagging and inspection of fire extinguisher - All Types       | 2.35       | 11.75  |
| 4        | Refill                  | Refilling of a Fire Extinguisher                                     | 7.50       | 30.00  |
| 4        | Regular/Service Re...   | Service charge for refilling, recharging or replacing a broken gauge | 5.00       | 20.00  |
| 0        | Recharge 2.5 ABC        | Recharge of a 2.5 ABC fire extinguishers                             | 5.00       | 0.00   |
| 0        | Recharge 5# ABC         | Recharge of a 5# ABC fire Extinguisher                               | 15.00      | 0.00   |
| 4        | Recharge 10/20AB...     | Recharge of a 10/20 ABC or Water                                     | 20.00      | 80.00  |
| 0        | Recharge K Class        | Recharge of a K Class Fire Extinguisher                              | 50.00      | 0.00   |
| 0        | Recharge CO2,BC ...     | Recharge of any CO2 5 and 10#, any size BC and PKP 5 and 10#.        | 5.00       | 0.00   |
| 0        | 6 - Year Inspection ... | 6 - Year Inspection 2.5 ABC                                          | 8.00       | 0.00   |
| 4        | 6 - Year Inspection ... | 6 Year Inspection of a 5/10/20 ABC                                   | 10.00      | 40.00  |
| 0        | 6 YR - Hal/Water/...    | Hal/Water/Co2/BC/PKP                                                 | 8.00       | 0.00   |
| 0        | 2.5 ABC                 | Hydrostatic testing of 2.5# ABC Fire Extinguisher                    | 5.00       | 0.00   |
| 2        | 5,10,20 ABC             | Hydrostatic testing of 5,10 or 20# ABC Fire Extinguisher             | 20.00      | 40.00  |

Billing Questions?? Email - Sales@fireandsecuritytech.com

Sales Tax (6.625%) \$0.00

\*\*\* To avoid an annual 18% service charge, please pay before invoice due date. \*\*\*

**Total** \$221.75



# Invoice

Please Send Payment to:  
217 Halls Mill Road  
Lebanon, NJ 08833

Branch Office:  
Washington Crossing, PA

Date 5/7/2019 Invoice # 2019-0629

Phone # (908)-823-4367 Fax # (866) 844-3086

## Bill To

SCPC - Sellars  
301 Old York Road  
Bridgewater, NJ 08807

## Ship To

SCPC - Sellars  
301 Old York Road  
Bridgewater, NJ 08807

| P.O. Number | Terms     | Ship     | SME Number | Proposal # | Service Report # | Due Date | Project |
|-------------|-----------|----------|------------|------------|------------------|----------|---------|
| 154569      | Net 30 SD | 5/7/2019 | 19-0058    |            |                  | 7/6/2019 |         |

| Quantity | Item Code               | Description                                                          | Price Each | Amount |
|----------|-------------------------|----------------------------------------------------------------------|------------|--------|
|          |                         | Sellers/Duke Island                                                  |            |        |
| 68       | TAG                     | Yearly tagging and inspection of fire extinguisher - All Types       | 2.35       | 159.80 |
| 18       | Refill                  | Refilling of a Fire Extinguisher                                     | 7.50       | 135.00 |
| 18       | Regular/Service Re...   | Service charge for refilling, recharging or replacing a broken gauge | 5.00       | 90.00  |
| 6        | Recharge 2.5 ABC        | Recharge of a 2.5 ABC fire extinguishers                             | 5.00       | 30.00  |
| 3        | Recharge 5# ABC         | Recharge of a 5# ABC fire Extinguisher                               | 15.00      | 45.00  |
| 9        | Recharge 10/20AB...     | Recharge of a 10/20 ABC or Water                                     | 20.00      | 180.00 |
| 0        | Recharge K Class        | Recharge of a K Class Fire Extinguisher                              | 50.00      | 0.00   |
| 0        | Recharge CO2,BC ...     | Recharge of any CO2 5 and 10#, any size BC and PKP 5 and 10#.        | 5.00       | 0.00   |
| 6        | 6 - Year Inspection ... | 6 - Year Inspection 2.5 ABC                                          | 8.00       | 48.00  |
| 12       | 6 - Year Inspection ... | 6 Year Inspection of a 5/10/20 ABC                                   | 10.00      | 120.00 |
| 0        | 6 YR - Hal/Water/...    | Hal/Water/Co2/BC/PKP                                                 | 8.00       | 0.00   |
| 6        | 2.5 ABC                 | Hydrostatic testing of 2.5# ABC Fire Extinguisher                    | 5.00       | 30.00  |
| 12       | 5,10,20 ABC             | Hydrostatic testing of 5,10 or 20# ABC Fire Extinguisher             | 20.00      | 240.00 |

Billing Questions?? Email - Sales@fireandsecuritytech.com

**Sales Tax (6.625%)** \$0.00

\*\*\* To avoid an annual 18% service charge, please pay before invoice due date. \*\*\*

**Total** \$1,077.80