



Learn how
to get more out
of your system

See reverse side
for details.

Save a stamp!
Pay by phone:
1-800-606-3535

Electronic Funds Transfer
or Credit Card:
Please complete information
on back of Remit section.

Questions?
Call Toll-Free:
1-800-642-2874
Hearing Impaired:
1-800-395-6137
Email:

Invoice 140918369

adt.com/commercial

Account Number	Invoice Date	Payment Due Date	PO Number	Amount Due
949236004	07/12/2021	08/11/2021		\$600.00

Description	Qty	Unit Price	Amount
OAKLAND BOE - VALLEY SCHOOL 71 OAK STREET			
Job# 280856242			
Trip Charge	1	\$150.00	\$150.00
Labor Charge	3	\$150.00	\$450.00
Sub Total			\$600.00
INVOICE AMOUNT DUE			\$600.00

RECEIVED

7-26-21



Service Work Order

Job # 280856242

Customer OAKLAND PUBLIC SCHOOLS
Site OAKLAND BOE - VALLEY SCHOOL
CS# INSP67780-
Address 71 OAK STREET

Customer# 949236004
Site# 949043394

OAKLAND, NJ 07436-

Site Phone
Requested By JOE
Service Plan DP635F-D635 Pref Fire/Gen Bank
Warranty Status Labor Only
System Type SUN2-FIRE_SYSTEM
Panel Location
Job Request FIRE4-Commercial Service Call
Commitment 07/09/2021 12:00-16:00

Phone 973 390-7433

TROUBLE SIGNAL - HAVING A PROBLEM WITH A HEAT DETECTOR

Comment

{1 of 3} 7/9/21 MK I arrived on site and found a trouble on the panel for the tech heat detector above the ceiling in the tech area at address 86 and at address 84 in the tech office. I reviewed the central station information and saw that the original {3 of 3} located it in the hallway above the ceiling by the stairs. It was loose in its base. I reinstalled it and it began communicating again. Left system normal upon departure.

{2 of 3} trouble was for the device at address 86 above the ceiling. I searched throughout the tech are for the 86 device and finally