

ALL INVOICES AND
CORRESPONDENCE MUST BE SENT
TO ABOVE ADDRESS REGARDLESS
OF SHIPPING POINT

**WOODBINE BOARD OF EDUCATION
BUSINESS OFFICE**
1076 Almond Road
Pittsgrove, NJ 08318
856-358-3094 ext. 4023

PURCHASE ORDER NO. **100015**

PO# AND ORDERED BY
NAME MUST APPEAR ON
ALL LABELS, CARTONS &
INVOICES

Page 1 of 1

Copy 3

Ship to

WOODBINE ELEMENTARY
801 Webster Street
Woodbine, NJ 08270

To

FRANKLIN ALARM COMPANY INC
P.O. BOX 84
FRANKLINVILLE, NJ 08322

1264

Account Code

11-190-100-500-050-0

Amount

276.00

Date: 07/01/20

Dept:

Notice: The purchaser is exempt by statute from paying all Federal, State
and Municipal Excise Sales & other taxes.

Qty	Unit	Description	Unit Price	Amount
1.		FIRE ALARM SYSTEM MONITORING - JULY 2020-JUNE 2021	276.000	276.00
CR 011433 8/17				

Total for Lines **\$276.00**

NOTICE TO VENDOR OR CONTRACTOR

1. Order invalid unless signed by the Secretary of the Board of Education
2. Shipping statement must accompany delivery of materials
3. Voucher provided by the Board of Education must be forwarded to the secretary to process payment
4. Please submit invoice as soon as order is completed
5. Must have NJ Reg. on file with us in order to receive payment

SCHOOL OFFICE USE ONLY

I certify that the goods or services itemized have been received

Signature

Title

Date

NO ORDER VALID UNLESS SIGNED BY THE SECRETARY

SECRETARY, BOARD OF EDUCATION



P.O. BOX 84, FRANKLINVILLE, NJ 08322

856-728-6424 Fax 728-3763

www.FranklinAlarm.com

NJ State Burg/Fire Alarm Lic#34BF00006500

100015

11-190-100-500

INVOICE

Date
6/4/2020

Invoice #
75250

Bill To

WOODBINE ELEMENTARY SCHOOL
C/O WOODBINE BOE
1076 ALMOND RD.
PITTSBORO, NJ 08318

Reference

P.O. #	TERMS	REP
	NET 10	

Description	Quantity	Cost	Amount
Fire Alarm System Monitoring July 2020 through June 2021 **Our monitoring rates have increased slightly. We appreciate your business!		276.00	276.00

Subtotal	\$276.00
Sales Tax (0.0%)	\$0.00
TOTAL	\$276.00
Payments/Credits	\$0.00
BALANCE DUE	\$276.00

THANK YOU FOR YOUR BUSINESS!

Contact us with changes needed on your monitoring account. TESTING YOUR ALARM MONTHLY WILL LET YOU KNOW IF YOUR SYSTEM IS WORKING PROPERLY. For your convenience we accept all major credit cards. Please call our office for details. Finance chgs of 1.5% per mo is added on accts 30 days or more past due.

ALL INVOICES AND
CORRESPONDENCE MUST BE SENT
TO ABOVE ADDRESS REGARDLESS
OF SHIPPING POINT

WOODBINE BOARD OF EDUCATION
BUSINESS OFFICE
1076 Almond Road
Pittsgrove, NJ 08318
856-358-3094 ext. 4023

PURCHASE ORDER NO.

100015

PO# AND ORDERED BY
NAME MUST APPEAR ON
ALL LABELS, CARTONS &
INVOICES

Page 1 of 1

Copy 4

Ship to

WOODBINE ELEMENTARY
801 Webster Street
Woodbine, NJ 08270

To

FRANKLIN ALARM COMPANY INC
P.O. BOX 84
FRANKLINVILLE, NJ 08322

1264

Account Code

11-190-100-500-050-0

Amount

276.00

Date: 07/01/20

Dept:

Notice: The purchaser is exempt by statute from paying all Federal, State
and Municipal Excise Sales & other taxes.

Qty	Unit	Description	Unit Price	Amount
1.		FIRE ALARM SYSTEM MONITORING - JULY 2020-JUNE 2021	276.000	276.00

Total for Lines \$276.00

NOTICE TO VENDOR OR CONTRACTOR

1. Order invalid unless signed by the Secretary of the Board of Education
2. Shipping statement must accompany delivery of materials
3. Voucher provided by the Board of Education must be forwarded to the secretary to process payment
4. Please submit invoice as soon as order is completed
5. Must have NJ Reg. on file with us in order to receive payment

SCHOOL OFFICE USE ONLY

I certify that the goods or services itemized have been received

Signature

Title

Date

NO ORDER VALID UNLESS SIGNED BY THE SECRETARY

SECRETARY, BOARD OF EDUCATION

RECEIVING COPY

ALL INVOICES AND
CORRESPONDENCE MUST BE SENT
TO ABOVE ADDRESS REGARDLESS
OF SHIPPING POINT

WOODBINE BOARD OF EDUCATION
BUSINESS OFFICE
1076 Almond Road
Pittsgrove, NJ 08318
856-358-3094 ext. 4023

PURCHASE ORDER NO.

100212

PO# AND ORDERED BY
NAME MUST APPEAR ON
ALL LABELS, CARTONS &
INVOICES

Page 1 of 1

Copy 3

Ship to

WOODBINE ELEMENTARY
801 Webster Street
Woodbine, NJ 08270

To

FRANKLIN ALARM COMPANY INC
P.O. BOX 84
FRANKLINVILLE, NJ 08322

1264

Account Code

11-190-100-500-050-0

Amount

762.00

Date: 03/10/21

Dept:

Notice: The purchaser is exempt by statute from paying all Federal, State
and Municipal Excise Sales & other taxes

Qty	Unit	Description	Unit Price	Amount
		Invoice 77142		
1.		Fire Alarm Inspection 3/4/21	675.000	675.00
1.		Replaced SG-42 pull station rear class by exit in library	87.000	87.00
# 11797 4/27/21				

Total for Lines **\$762.00**

NOTICE TO VENDOR OR CONTRACTOR

1. Order invalid unless signed by the Secretary of the Board of Education
2. Shipping statement must accompany delivery of materials
3. Voucher provided by the Board of Education must be forwarded to the secretary to process payment
4. Please submit invoice as soon as order is completed
5. Must have NJ Reg. on file with us in order to receive payment

SCHOOL OFFICE USE ONLY

I certify that the goods or services itemized have been received

Signature

Title

Date

NO ORDER VALID UNLESS SIGNED BY THE SECRETARY

SECRETARY, BOARD OF EDUCATION



P.O. BOX 84, FRANKLINVILLE, NJ 08322

856-728-6424 Fax 728-3763

www.FranklinAlarm.com

NJ State Burg/Fire Alarm

11-190-100-500-DSO

INVOICE

Date
3/10/2021

Invoice #
77142

Bill To

Reference

WOODBINE ELEMENTARY SCHOOL
C/O WOODBINE BOE
1076 ALMOND RD.
PITTSBORO, NJ 08318

P.O. #	TERMS	REP
	NET 10	

Description	Quantity	Cost	Amount
Fire Alarm Inspection 3/4/21		675.00	675.00
Replaced SG-42 pull station rear class by exit by library.	1	87.00	87.00

THANK YOU FOR YOUR BUSINESS!

Contact us with changes needed on your monitoring account. TESTING YOUR ALARM MONTHLY WILL LET YOU KNOW IF YOUR SYSTEM IS WORKING PROPERLY. For your convenience we accept all major credit cards. Please call our office for details. Finance cges of 1.5% per mo is added on accts 30 days or more past due.

Subtotal	\$762.00
Sales Tax (6.625%)	\$0.00
TOTAL	\$762.00
Payments/Credits	\$0.00
BALANCE DUE	\$762.00

FACI 
FRANKLIN
ALARM COMPANY, INC.

SERVICE REPORT

TROUBLE REPORTED OR
WORK REQUESTED

replaced 1 power
Station rear class
by exit by library

I HEREBY REQUEST THE ABOVE WORK TO BE DONE AND
AGREE TO PAY FOR SAME WHEN BILLED.

SUBSCRIBER . . .

Inspection Report

Cycle: Annually
[Ref #201016]



NJ License # P00348

Building

Woodbine Elementary
801 Webster St.
Woodbine, NJ

Customer


Woodbine Elementary
801 Webster St.
Woodbine, NJ

Contact Us

P.O. Box 84
Franklinville, NJ 08322
Call: (856) 728-6424
Fax: (856) 728-3763
JPetsch@FranklinAlarm.com

Signature

I state that the information on this form is correct at the time and place of my inspection, and that all equipment tested at this time was left in operational condition upon completion of this inspection except as noted.

Inspected by	Approved by	Signature	Date
Tom Macneir	Joseph C. Petsch SET		03/04/2021

Except as noted, the building is occupied with the same occupancy classification and hazard of contents as last inspection. Also, the system has remained in service without modification and is free of actuation of devices and alarms.

Equipment Summary

Name	Total	N/A	Failed
Alarm Panel			
Addressable	1	0	0
Battery			
Sealed Lead Acid: AH Meter 2 Batteries	1	0	0
Initiating Device			
Duct Detector	3	0	0
Heat Detector	47	0	0
Manual Pull Station	18	0	0
Smoke Detector - PE: No Sensitivity	60	0	0
Remote Power Supply #1			
	1	0	0
Remote Power Supply #2			
	1	0	0

Equipment Tests

Alarm Panel Information		
Panel Manufacturer EST / GE	Model ETS - 3	Serial #
Location Main Office	Over-current Protect Type Breaker	Over-current Size (Amps) 20
Battery Tests		

Inspection Report

Cycle: Annually

[Ref #201016]



NJ License # P00348

Battery Tests													
Location	Quantity	Type	Manufacture Model	Replacement Date	Condition	Connections	Leaks or Corrosion	Voltage with Charger	#1 Voltage - No Load	#1 Measured Capacity (A/hr)	#2 Voltage - No Load	#2 Measured Capacity (A/hr)	Rated Capacity
	2				Ok	Ok	Ok						Ok

System Function Summary	
Description	Test Result
Alarm Functions	
Evacuation Alarm functions including Bells/Horns/Strobes actuate properly	Pass
Description	Test Result
Alarm Panel Supervisory Functions	
Ground faults in alarm circuits are detected	Pass
Integrity of single or multiple circuits providing interface between two or more control panels verified.	Pass
Electrical opens in initiating and indicating circuits are detected.	Pass
Electrical shorts in initiating and indicating circuits are detected.	Pass
Loss of AC power to the alarm panel is detected by the alarm system.	Pass
Loss of Secondary power to the alarm panel is detected by the alarm system.	Pass

Central Station Test			
Operator spoke to		Type Transmission	Digital
Alarm, Trouble and Supervisory indication tested and verified with the central station?	Yes		
Panel Inspection			
Are zones labeled and identified?	Yes	Are drawings and wiring diagrams available at the panel?	Yes
Have all fuses been checked for rating and supervision?	Yes	System was in operation upon arrival?	Yes
Are operating instructions posted or available at the panel?	Yes	Panel and surrounding equipment, conduit and wiring well secured and in good condition	Yes
Surge/Transient suppressors visually inspected?	Yes	Are all lamps and displays operating correctly?	Yes
Primary power supply operates properly under full load?	Yes		

Inspection Report

Cycle: Annually

[Ref #201016]



FRANKLIN
ALARM COMPANY INC.

NJ License # P00348

Alarm Device Summary

Device Type	Location	Status
1st Floor		
	Above Ceiling by Gym Doors	Passed
	Above Ceiling by Gym Doors	Passed
Duct Detector	Library A105	Passed
Duct Detector	Computer Room	Passed
Duct Detector	Gym Entryway	Passed
Heat Detector	Nurse	Passed
Heat Detector	Gym	Passed
Heat Detector	Mechanical in Gym	Passed
Heat Detector	Gym	Passed
Heat Detector	Library Storage	Passed
Heat Detector	Gym	Passed
Heat Detector	Library by A101 Entry	Passed
Heat Detector	Boys Locker Room	Passed
Heat Detector	Kitchen	Passed
Heat Detector	Gym by Girls Locker Room	Passed
Heat Detector	Disiplinary Room	Passed
Heat Detector	Library Office	Passed
Heat Detector	Gym Office	Passed
Heat Detector	Boys Locker Room	Passed
Heat Detector	Library A105	Passed
Heat Detector	Stage	Passed
Heat Detector	A111	Passed
Heat Detector	Boiler Room	Passed
Heat Detector	Speech Room	Passed
Heat Detector	Computer Room	Passed
Heat Detector	Gym	Passed
Heat Detector	Gym	Passed
Heat Detector	Teachers Room	Passed
Heat Detector	Gym	Passed
Heat Detector	Girls Locker Room	Passed
Heat Detector	Kitchen Prep	Passed
Heat Detector	Library A101	Passed

Inspection Report

Cycle: Annually

[Ref #201016]



NJ License # P00348

Device Type	Location	Status
1st Floor		
Heat Detector	A101 Bath-Handicap	Passed
Heat Detector	Gym	Passed
Heat Detector	A110	Passed
Heat Detector	Girls Lav by Room 111	Passed
Heat Detector	Main Office Womens Bath	Passed
Heat Detector	Gym	Passed
Heat Detector	Gym	Passed
Heat Detector	Library A105	Passed
Heat Detector	Gym	Passed
Heat Detector	Janitor by Room 111	Passed
Heat Detector	Computer Room	Passed
Heat Detector	Disiplinary Room	Passed
Heat Detector	Gym	Passed
Heat Detector	A101 Unisex Bath	Passed
Heat Detector	Gym	Passed
Heat Detector	Library A101	Passed
Heat Detector	Boys Lav by Room 112	Passed
Heat Detector	Girls Locker Room	Passed
Heat Detector	Library A101	Passed
Heat Detector	Nurse	Passed
Manual Pull Station	Gym Side Exit #1	Passed
Manual Pull Station	Exit by Room 105	Passed
Manual Pull Station	Gym Side Exit #2	Passed
Manual Pull Station	Gym\Cafeteria	Passed
Manual Pull Station	Hall by Room 122	Passed
Manual Pull Station	Library A105	Passed
Manual Pull Station	Exit by Room 102	Passed
Manual Pull Station	Main Lobby	Passed
Manual Pull Station	Hall by Room 105	Passed
Manual Pull Station	Gym Rear Exit	Passed
Manual Pull Station	Boiler Room	Passed
Manual Pull Station	Foyer by A111	Passed
Manual Pull Station	Computer Room	Passed
Manual Pull Station	A101 Library Exit	Passed

Inspection Report

Cycle: Annually

[Ref #201016]



NJ License # P00348

Device Type	Location	Status
1st Floor		
Manual Pull Station	Gym\Cafeteria	Passed
Manual Pull Station	A101 Library Exit	Passed
Manual Pull Station	Hall by Room 103	Passed
Manual Pull Station	A101 Library Exit	Passed
Smoke Detector - PE: No Sensitivity	Room 106	Passed
Smoke Detector - PE: No Sensitivity	Superintendent	Passed
Smoke Detector - PE: No Sensitivity	Library A101	Passed
Smoke Detector - PE: No Sensitivity	Room 109	Passed
Smoke Detector - PE: No Sensitivity	Room 104	Passed
Smoke Detector - PE: No Sensitivity	Exit by Room 105	Passed
Smoke Detector - PE: No Sensitivity	Room 117	Passed
Smoke Detector - PE: No Sensitivity	Foyer by A111	Passed
Smoke Detector - PE: No Sensitivity	Hall by Gym\Main Office	Passed
Smoke Detector - PE: No Sensitivity	Room 115	Passed
Smoke Detector - PE: No Sensitivity	Hall by Speech Room	Passed
Smoke Detector - PE: No Sensitivity	Room 114	Passed
Smoke Detector - PE: No Sensitivity	Gym\Cafeteria	Passed
Smoke Detector - PE: No Sensitivity	Tech Room	Passed
Smoke Detector - PE: No Sensitivity	School Business Admin	Passed
Smoke Detector - PE: No Sensitivity	Room 107	Passed
Smoke Detector - PE: No Sensitivity	Library A105	Passed
Smoke Detector - PE: No Sensitivity	Room 103 Bath	Passed
Smoke Detector - PE: No Sensitivity	Disiplinary Room	Passed
Smoke Detector - PE: No Sensitivity	Room 105	Passed
Smoke Detector - PE: No Sensitivity	Teachers Room	Passed
Smoke Detector - PE: No Sensitivity	Room 116	Passed
Smoke Detector - PE: No Sensitivity	Room 102 Bath	Passed
Smoke Detector - PE: No Sensitivity	Room 118	Passed
Smoke Detector - PE: No Sensitivity	Main Lobby	Passed
Smoke Detector - PE: No Sensitivity	Hall by Room 102	Passed
Smoke Detector - PE: No Sensitivity	Teachers Room	Passed
Smoke Detector - PE: No Sensitivity	Room 108	Passed
Smoke Detector - PE: No Sensitivity	Library A101	Passed
Smoke Detector - PE: No Sensitivity	Room 101	Passed

Inspection Report

Cycle: Annually

[Ref #201016]



NJ License # P00348

Device Type	Location	Status
1st Floor		
Smoke Detector - PE: No Sensitivity	Room 121	Passed
Smoke Detector - PE: No Sensitivity	Hall by Boiler Room	Passed
Smoke Detector - PE: No Sensitivity	Nurse	Passed
Smoke Detector - PE: No Sensitivity	Gym\Cafeteria	Passed
Smoke Detector - PE: No Sensitivity	Hall by Room 110	Passed
Smoke Detector - PE: No Sensitivity	Library A105	Passed
Smoke Detector - PE: No Sensitivity	Room 101 Bath	Passed
Smoke Detector - PE: No Sensitivity	Room 120	Passed
Smoke Detector - PE: No Sensitivity	Library\Nurse Hallway	Passed
Smoke Detector - PE: No Sensitivity	Gym\Cafeteria	Passed
Smoke Detector - PE: No Sensitivity	Room 102	Passed
Smoke Detector - PE: No Sensitivity	Room 122	Passed
Smoke Detector - PE: No Sensitivity	Room 113	Passed
Smoke Detector - PE: No Sensitivity	Room 103	Passed
Smoke Detector - PE: No Sensitivity	Room 106 Bath	Passed
Smoke Detector - PE: No Sensitivity	Gym\Cafeteria	Passed
Smoke Detector - PE: No Sensitivity	Room 121	Passed
Smoke Detector - PE: No Sensitivity	Hall by Room 105	Passed
Smoke Detector - PE: No Sensitivity	Hall by Room 114	Passed
Smoke Detector - PE: No Sensitivity	Room 112	Passed
Smoke Detector - PE: No Sensitivity	Hall by Room 119	Passed
Smoke Detector - PE: No Sensitivity	Hall by Room 103	Passed
Smoke Detector - PE: No Sensitivity	Hall by A110	Passed
Smoke Detector - PE: No Sensitivity	Room 108 Bath	Passed
Smoke Detector - PE: No Sensitivity	Hall by Gym\Library	Passed
Smoke Detector - PE: No Sensitivity	Library A105	Passed
Smoke Detector - PE: No Sensitivity	Room 111	Passed
Smoke Detector - PE: No Sensitivity	Main Office	Passed
Smoke Detector - PE: No Sensitivity	Room 119	Passed
Smoke Detector - PE: No Sensitivity	Room 110	Passed

ALL INVOICES AND
CORRESPONDENCE MUST BE SENT
TO ABOVE ADDRESS REGARDLESS
OF SHIPPING POINT

**WOODBINE BOARD OF EDUCATION
BUSINESS OFFICE**
1076 Almond Road
Pittsgrove, NJ 08318
856-358-3094 ext. 4023

PURCHASE ORDER NO. **100212**

PO# AND ORDERED BY
NAME MUST APPEAR ON
ALL LABELS, CARTONS &
INVOICES

Page 1 of 1

Copy 4

Ship to

WOODBINE ELEMENTARY
801 Webster Street
Woodbine, NJ 08270

To

FRANKLIN ALARM COMPANY INC 1264
P.O. BOX 84
FRANKLINVILLE, NJ 08322

Account Code	Amount
11-190-100-500-050-0	762.00

Date: 03/10/21

Dept:

Notice: The purchaser is exempt by statute from paying all Federal, State
and Municipal Excise Sales & other taxes

Qty	Unit	Description	Unit Price	Amount
1.		Invoice 77142		
1.		Fire Alarm Inspection 3/4/21	675.000	675.00
1.		Replaced SG-42 pull station rear class by exit in library	87.000	87.00

Total for Lines **\$762.00**

NOTICE TO VENDOR OR CONTRACTOR

1. Order invalid unless signed by the Secretary of the Board of Education
2. Shipping statement must accompany delivery of materials
3. Voucher provided by the Board of Education must be forwarded to the secretary to process payment
4. Please submit invoice as soon as order is completed
5. Must have NJ Reg. on file with us in order to receive payment

SCHOOL OFFICE USE ONLY

I certify that the goods or services itemized have been received

Signature

CSA
Title

3/25/21
Date

NO ORDER VALID UNLESS SIGNED BY THE SECRETARY

SECRETARY, BOARD OF EDUCATION

RECEIVING COPY

ALL INVOICES AND
CORRESPONDENCE MUST BE SENT
TO ABOVE ADDRESS REGARDLESS
OF SHIPPING POINT

WOODBINE BOARD OF EDUCATION
BUSINESS OFFICE
1076 Almond Road
Pittsgrove, NJ 08318
856-358-3094 ext. 4023

PURCHASE ORDER NO. **100052**

PO# AND ORDERED BY
NAME MUST APPEAR ON
ALL LABELS, CARTONS &
INVOICES

Page 1 of 1

Copy 3

Ship to

WOODBINE ELEMENTARY
801 Webster Street
Woodbine, NJ 08270

To

GENRON FIRE PROTECTION
P.O. BOX 556
SOUTH SEAVILLE, NJ 08246

1278

Account Code

11-000-261-420-050-0

Amount

299.40

Date: 08/10/20

Dept:

Notice: The purchaser is exempt by statute from paying all Federal, State
and Municipal Excise Sales & other taxes

Qty	Unit	Description	Unit Price	Amount
		Estimate 2019282		
10.		CS10ABC - Certification of 10lb ABC fire extinguishers per NJPA 10.6.1	5.900	59.00
5.		CS5ABC - Certification of 5lb ABC fire extinguishers per NFPA 10.6.1	5.900	29.50
1.		CS5FE36 - Certification of 5lb FE-36 fire extinguisher per NFPA 10.6.1	5.900	5.90
1.		FIELD - Field Extinguisher Service	72.000	72.00
1.		FIRE - Inspection, Certification, and Service Fire Suppression System Pursuant to NFPA 17A Para 7.3.2	116.000	116.00
2.		360FS - 360 Degree Heat Link for Fire System	8.500	17.00

CANCELLED / Re-Entered

Over 10% difference

Refer to PO 100127

Total for Lines **\$299.40**

NOTICE TO VENDOR OR CONTRACTOR

- Order invalid unless signed by the Secretary of the Board of Education
- Shipping statement must accompany delivery of materials
- Voucher provided by the Board of Education must be forwarded to the secretary to process payment
- Please submit invoice as soon as order is completed
- Must have NJ Reg. on file with us in order to receive payment

SCHOOL OFFICE USE ONLY

I certify that the goods or services itemized have been received

Signature

Title

Date

NO ORDER VALID UNLESS SIGNED BY THE SECRETARY

SECRETARY, BOARD OF EDUCATION

ALL INVOICES AND
CORRESPONDENCE MUST BE SENT
TO ABOVE ADDRESS REGARDLESS
OF SHIPPING POINT

WOODBINE BOARD OF EDUCATION
BUSINESS OFFICE
1076 Almond Road
Pittsgrove, NJ 08318
856-358-3094 ext. 4023

PURCHASE ORDER NO.

100052

PO# AND ORDERED BY
NAME MUST APPEAR ON
ALL LABELS, CARTONS &
INVOICES

Page 1 of 1

Copy 4

Ship to

WOODBINE ELEMENTARY
801 Webster Street
Woodbine, NJ 08270

To

GENRON FIRE PROTECTION 1278
P.O. BOX 556
SOUTH SEAVILLE, NJ 08246

Account Code

11-000-261-420-050-0

Amount

299.40

Date: 08/10/20

Dept:

Notice: The purchaser is exempt by statute from paying all Federal, State
and Municipal Excise Sales & other taxes

Qty	Unit	Description	Unit Price	Amount
		Estimate 2019282		
10.		CS10ABC - Certification of 10lb ABC Fire Extinguishers per NJPA 10.6.1	5.900	59.00
5.		CS5ABC - Certification of 5lb ABC fire extinguishers per NFPA 10.6.1	5.900	29.50
1.		CS5FE36 - Certification of 5lb FE-36 fire extinguisher per NFPA 10.6.1	5.900	5.90
1.		FIELD - Field Extinguisher Service	72.000	72.00
1.		FIRESYS - Inspection, Certification, and Service Fire Suppression System Pursuant to NFPA 17A Para 7.3.2	116.000	116.00
2.		360FS - 360 Degree Heat Link for Fire System	8.500	17.00

Total for Lines **\$299.40**

NOTICE TO VENDOR OR CONTRACTOR

1. Order invalid unless signed by the Secretary of the Board of Education
2. Shipping statement must accompany delivery of materials
3. Voucher provided by the Board of Education must be forwarded to the secretary to process payment
4. Please submit invoice as soon as order is completed
5. Must have NJ Reg. on file with us in order to receive payment

SCHOOL OFFICE USE ONLY

I certify that the goods or services itemized have been received

Monica Hurley

Signature

9/28/2020

Title

Date

NO ORDER VALID UNLESS SIGNED BY THE SECRETARY

[Signature]

SECRETARY, BOARD OF EDUCATION

RECEIVING COPY

ALL INVOICES AND
CORRESPONDENCE MUST BE SENT
TO ABOVE ADDRESS REGARDLESS
OF SHIPPING POINT

**WOODBINE BOARD OF EDUCATION
BUSINESS OFFICE**
1076 Almond Road
Pittsgrove, NJ 08318
856-358-3094 ext. 4023

PURCHASE ORDER NO.

100127

PO# AND ORDERED BY
NAME MUST APPEAR ON
ALL LABELS, CARTONS &
INVOICES

Page 1 of 1

Copy 3

Ship to

WOODBINE ELEMENTARY
801 Webster Street
Woodbine, NJ 08270

To

GENRON FIRE PROTECTION
P.O. BOX 556
SOUTH SEAVILLE, NJ 08246

1278

Account Code

11-000-261-420-050-0

Amount

351.95

Date: 08/10/20

Dept:

Notice: The purchaser is exempt by statute from paying all Federal, State
and Municipal Excise Sales & other taxes

Qty	Unit	Description	Unit Price	Amount
		Invoice 42429		
5.		CS5ABC - Certification of 5lb ABC fire extinguishers	5.900	29.50
8.		CS10ABC - Certification of 10lb ABC fire extinguishers	5.900	47.20
1.		CS20ABC- Check and Service 20lb ABC fire extinguisher	5.900	5.90
1.		CS5FE36 - Certification of 5lb FE-36 fire extinguisher	5.900	5.90
1.		CS6LITER - Certification of 6 Liter Wet Chemical	5.900	5.90
1.		FE436500 - AA10S-1 NEW ANSUL 10lb ABC fire extinguisher	84.000	84.00
1.		ABC10 - 10lb ABC Recharge and certification	28.900	28.90
1.		HT10 - Hydro test 10lb	16.650	16.65
4.		ABC5 - 5lb ABC Recharge and Certification	26.000	104.00
2.		STEM - New Valve Stem	12.000	24.00
1.0		Report - System Report		

CR 011572
11/11

Total for Lines

\$351.95

NOTICE TO VENDOR OR CONTRACTOR

1. Order invalid unless signed by the Secretary of the Board of Education
2. Shipping statement must accompany delivery of materials
3. Voucher provided by the Board of Education must be forwarded to the secretary to process payment
4. Please submit invoice as soon as order is completed
5. Must have NJ Reg. on file with us in order to receive payment

SCHOOL OFFICE USE ONLY

I certify that the goods or services itemized have been received

Signature

Title

Date

NO ORDER VALID UNLESS SIGNED BY THE SECRETARY

SECRETARY, BOARD OF EDUCATION

GENRON Fire Protection
PO Box 556
South Seaville, NJ 08246
609-624-3000
609-624-2999

11-000-261-420

Estimate

DATE	ESTIMATE NO.
8/10/2020	2019282

NAME / ADDRESS
Woodbine Board of Education 801 Webster Street Woodbine, NJ 08270

P.O. NO.	REP
	5

ITEM	DESCRIPTION	QTY	COST	TOTAL
CS10ABC	Certification of 10lb ABC Fire Extinguishers per NFPA 10.6.1	10	5.90	59.00
CS5ABC	Certification of 5lb ABC fire extinguishers per NFPA 10.6.1	5	5.90	29.50
CS5FE36	Certification of 5lb. FE-36 fire extinguisher per NFPA 10.6.1	1	5.90	5.90
FIELD	Field Extinguisher Service	1	72.00	72.00
FIRESYS	Inspection, Certification and Service Fire Suppression System Pursuant to NFPA 17A Para 7.3.2	1	116.00	116.00
360FS	360 Degree Heat Link for Fire System	2	8.50	17.00
			TOTAL	\$299.40

SIGNATURE _____

ORDER FORM

COMPANY NAME	Glendon Fire Protection
FULL ADDRESS	PO Box 556
	So. Seaside, NJ 08246
PHONE #	609 624-3000
FAX #	609 624-2999

BOARD OFFICE USE ONLY

609-861-5174 EXT 126

WOODBINE BOARD OF EDUCATION

PURCHASE ORDER NO. _____

801 WEBSTER STREET

WOODBINE, NJ 08270

VENDOR NUMBER

DATE	REQUISITIONED BY	AUTHORIZED SIGNATURE
8/11/2020	(Monica) Morales	

MUST GET A QUOTE FROM VENDOR & SHIPPING CHARGES INCLUDED BEFORE SUBMISSION

QUANTITY	CODE	DESCRIPTION	UNIT PRICE	TOTAL
30		Certification of Fire Extinguishers See attached detail		
		SUBTOTAL		
		SHIPPING(10% OR VENDOR QUOTE)		
		TOTAL		

Date Received _____

Signature _____

GENRON Fire Protection
PO Box 556
South Seaville, NJ 08246
609-624-3000
609-624-2999

Estimate

DATE	ESTIMATE NO.
8/10/2020	2019282

NAME / ADDRESS
Woodbine Board of Education 801 Webster Street Woodbine, NJ 08270

P.O. NO.	REP
	5

ITEM	DESCRIPTION	QTY	COST	TOTAL
CS10ABC	Certification of 10lb ABC Fire Extinguishers per NFPA 10.6.1	10	5.90	59.00
CS5ABC	Certification of 5lb ABC fire extinguishers per NFPA 10.6.1	5	5.90	29.50
CS5FE36	Certification of 5lb. FE-36 fire extinguisher per NFPA 10.6.1	1	5.90	5.90
FIELD	Field Extinguisher Service	1	72.00	72.00
FIRESYS	Inspection, Certification and Service Fire Suppression System Pursuant to NFPA 17A Para 7.3.2	1	116.00	116.00
360FS	360 Degree Heat Link for Fire System	2	8.50	17.00
			TOTAL	\$299.40

SIGNATURE _____

**GENRON Fire**

PO Box 556
 South Seaville, NJ 08246
 609-624-3000
 609-624-2999

PLEASE REMIT TO:
GENRON INC.
P.O. Box 556
South Seaville NJ
08246

Invoice

DATE	INVOICE
9/24/2020	42429

BILL TO:

Woodbine Board of Education
 801 Webster Street
 Woodbine, NJ 08270

WORK LOCATION:

Woodbine Board of Education
 801 Webster Street
 Woodbine, NJ 08270



P.O.	TERMS	DUE	TECH	PHONE	SER DATE	TYPE	SYSTEM	S/N	H/T DATE
	Due on...	9/24/2020	FC	609-861-5174	8-31-2020	S/A			
ITEM	QTY	DESCRIPTION					RATE	AMOUNT	
CS5ABC	5	Certification of 5lb ABC fire extinguishers per NFPA 10.6.1					5.90	29.50	
CS10ABC	8	Certification of 10lb ABC Fire Extinguishers per NFPA 10.6.1					5.90	47.20	
CS20ABC	1	Check and Service 20lb ABC Fire Extinguisher per NFPA 10.6.1					5.90	5.90	
CS5FE36	1	Certification of 5lb. FE-36 fire extinguisher per NFPA 10.6.1					5.90	5.90	
CS6LITER	1	Certification of 6 Liter Wet Chemical per NFPA 10.6.1					5.90	5.90	
FE436500	1	AA10S-1 NEW ANSUL 10lb. ABC SENTRY Fire Extinguisher					84.00	84.00	
ABC10	1	10lb ABC Recharge and Certification					28.90	28.90	
HT10	1	Hydro-Test 10lb					16.65	16.65	
ABC5	4	5lb ABC Recharge and Certification					26.00	104.00	
STEM	2	New Valve Stem					12.00	24.00	
REPORT	1	System report provided with invoice. (NO CHARGE)					0.00	0.00	

Total \$351.95


WOULD YOU LIKE TO PAY YOUR INVOICE
 BY CREDIT CARD? PLEASE CALL THE
 OFFICE AND WE WILL TAKE CARE OF
 THAT FOR YOU

E-mail

ggburnell@genronfire.net

PLEASE NOTE OUR
 NEW REMITTANCE
 ADDRESS

☒ System is Compliant with NJAC-5:70-3				☐ System is Non-Compliant									
Genron Fire Protection 1066 Route 83, Clermont, NJ 08210 Phone: 609-624-3000 Fax: 609-624-2999 NJ Contractor Permit # P00254 US DOT Requalifier Facility RIN G821				WORK ORDER NO 739		DATE 08/31/2020		HAZARD AREA PROTECTED Hood duct appliance					
				SYSTEM MFG Ansul		SYS CAPACITY 3 Gal		SYS TYPE R-102		# OF CYLS 1			
CUSTOMER Woodbine Elem School				CONTACT		PHONE 609-861-5174		FAX					
ADDRESS 801 Webster				CITY Woodbine		STATE AND ZIP CODE NJ							
AHJ/PROTECTION DISTRICT				INSPECTION TYPE ☐ INITIAL ☐ ANNUAL ☐ SEMI-ANNUAL									
INITIAL ACTIONS/OBSERVATIONS				Y	N	N/A	HAZARD INSPECTION			Y	N	N/A	
1	Last serviced by: Genron						18	Hazard configuration appeared to remain unchanged?			☒	☐	☐
2	Were building personnel notified of the inspection?			☒	☐	☐	19	Are all observable penetrations to the hood and duct sealed?			☒	☐	☐
3	Was the monitoring company notified?			☐	☒	☐	20	No readily observable obstructions or interference that could impact effectiveness of the suppression system?			☒	☐	☐
4	System found charged and functioning at the time of tech's arrival?			☒	☐	☐	SYSTEM FUNCTIONAL TEST			Y	N	N/A	
5	System un-tampered since last visit?			☒	☐	☐	21	System disarmed per manufacturer's recommendations?			☒	☐	☐
6	System found to be at proper pressure upon arrival?			☐	☐	☒	22	Mechanical detection line tested and found to operate properly?			☒	☐	☐
VISUALLY CHECK SYSTEM				Y	N	N/A	23	Proper number and placement of detectors/links?			☒	☐	☐
7	Baffle-type filters installed in hood?			☒	☐	☐	24	Did the system operate properly from activation of a manual pull station?			☒	☐	☐
8	System [and appliance] appear unchanged since last service?			☒	☐	☐	25	Gas shut-off valve installed and working properly? (Note location)			☒	☐	☐
9	Were the nozzle caps in place at time of arrival?			☒	☐	☐	Across from hood						
10	Visible piping and nozzles properly connected, braced and free of damage?			☒	☐	☐	26	Replaced links with proper temperature rating? (List the number of links and degrees below)					
							Links	2	Deg	360	Links	Deg	
							Links	Deg		Links	Deg		
11	Piping/conduit/cabling free from observable obstructions?			☒	☐	☐	27	Is the manual reset for electric gas valves operational?			☒	☐	☐
12	Nozzle(s) inspected and found to be clear of obstructions?			☒	☐	☐	28	Did all electrical appliances shut off upon system operation?			☒	☐	☐
13	Correct Nozzle type(s) for protected equipment, plenum and ducts?			☒	☐	☐	29	Did all gas appliances shut off upon system operation?			☒	☐	☐
14	Nozzle(s) properly positioned over appliances?			☒	☐	☐	30	Did the make-up air shut down?			☐	☐	☒
15	Nozzles properly positioned in duct(s) and plenum(s)?			☒	☐	☐	31	Did the alarm system activate when the system tripped?			☒	☐	☐
16	Is there a fan warning sign on hood?			☐	☒	☐	32	Did control head(s)/cylinder releasing device(s) operate properly?			☒	☐	☐
17	Flow points/extinguishing agent with mfg's allowed maximums?			☒	☐	☐							
NOTIFICATION OF DEFICIENCIES				CUSTOMER INITIALS _____									
☐ A mark made in the adjacent box indicates that deficiencies exist with the current condition of the Fire Suppression System. If this is the case, the customer's authorized representative, by his or her signature and initials acknowledges these deficiencies represent an IMMEDIATE AND SERIOUS SAFETY CONCERN that the customer must correct. Service Company shall not be responsible if the Fire Suppression malfunctions or fails to function. It is the owner's responsibility to ensure that all deficiencies are removed or repaired.													

CUSTOMER Woodbine Elem School		CONTACT	PHONE 609-861-5174	FAX
ADDRESS 801 Webster		CITY Woodbine	STATE AND ZIP CODE NJ	
HOOD SIZE 13'		DUCT QUANTITY & SIZE 30' x 9'		
				
LABEL ALL APPLIANCES				
				
SIZE				
NOTES/COMMENTS				
INCLUDE ALL APPLIANCES. LABEL SIZE AND TYPE				
SYSTEM CONNECTED TO ALARM ☒ YES ☐ NO		GAS VALVE ☒ YES ☐ NO SIZE 3'		
NOZZLE QUANTITY		GAS VALVE STYLE:		
DUCT 1 PLENUM 2 APPLIANCE 3		☒ ELECTRICAL ☐ MECHANICAL		
REMOTE PULL ☒ YES ☐ NO		TYPE: ☒ RELEASE ☐ PULL		
② Egress				
ALL CONDITIONS ARE LIMITED TO ONLY THOSE THAT COULD BE OBSERVED AT THE TIME OF INSPECTION				

Hood duct appliances

KITCHEN SYSTEM REPORT – PAGE 2

CUSTOMER Woodbine Elem School			CONTACT			PHONE 609-861-5174		FAX		
ADDRESS 801 Webster			CITY Woodbine			STATE AND ZIP CODE NJ				
CYLINDERS AND AGENTS			Y	N	N/A	SYSTEM ACTIVATION		Y	N	N/A
33	Cylinder Pressure	psi	☐	☐	☒	45	Were all filters reinstalled?	☒	☐	☐
34	Hydrostatic test dates(s) of cylinder:		☐	☐	☐	46	Were all cartridges reinstalled? (if applicable)	☒	☐	☐
35	Were all cylinders free of signs of external corrosion and/or damage?		☐	☐	☐	47	Tandem/slave releasing device(s) reset properly?	☐	☐	☒
36	Are all cylinders securely mounted?		☐	☐	☐			☐	☐	☒
37	Cartridge inspected or replaced within mfg's recommended interval? Weight <i>visual</i>		☐	☐	☐	FINAL		Y	N	N/A
SYSTEM REACTIVATION			Y	N	N/A	48	Operator's manual on site?	☒	☐	☐
38	Test adapters, keeper pins, etc. removed from system?		☐	☐	☐	49	Class K portable extinguisher available and properly serviced?	☒	☐	☐
39	Detection [link] line has proper tension?		☐	☐	☐	50	Remote manual release free from obstruction & operable?	☒	☐	☐
40	Was the control head reset?		☐	☐	☐	51	Has the system been placed back in service?	☒	☐	☐
41	Were all fuel sources supplied by the gas valve relit?		☐	☐	☐	52	Monitoring company notified that the system is back in full service?	☐	☒	☐
42	Were all pilot lights supplied by the gas valve relit?		☐	☐	☐	53	Were building personnel notified of the system condition?	☒	☐	☐
43	Microswitch/relay(s)-electric appliances "on"?		☐	☐	☐	54	Have you received a signature from the building personnel?	☒	☒	☒
44	Are all nozzle caps in place?		☐	☐	☐	55	Inspection tag affixed to system?	☒	☐	☐
DESCRIPTION OF DEFICIENCIES										
COMMENTS AND RECOMMENDATIONS										
NOTIFICATION OF EXHAUST SYSTEM GREASE BUILD UP							CUSTOMER INITIALS _____			
☐ A mark made in the adjacent box indicates that we recommend that the entire exhaust and ventilation control system as well as appliances be inspected by a properly trained, qualified, and certified company or person(s) acceptable to the authority having jurisdiction to determine if cleaning is required. Any visual observations or comments noted by our Service Technician regarding grease build up are for informational purposes only and are based readily observable conditions at the time of service.										
AUTHORIZED CUSTOMER REPRESENTATIVE						AUTHORIZED COMPANY REPRESENTATIVE				
Signature <i>Monica Morales</i>						Signature <i>Francis Carlini</i>				
Print Name <i>MONICA MORALES</i>						Print Name & Certification Number <i>FRANCIS CARLINI</i> <i>POO 254</i>				

Customer Print:

ALL INVOICES AND
CORRESPONDENCE MUST BE SENT
TO ABOVE ADDRESS REGARDLESS
OF SHIPPING POINT

WOODBINE BOARD OF EDUCATION
BUSINESS OFFICE
1076 Almond Road
Pittsgrove, NJ 08318
856-358-3094 ext. 4023

PURCHASE ORDER NO. **100127**

PO# AND ORDERED BY
NAME MUST APPEAR ON
ALL LABELS, CARTONS &
INVOICES

Page 1 of 1

Copy 4

Ship to

WOODBINE ELEMENTARY
801 Webster Street
Woodbine, NJ 08270

To

GENRON FIRE PROTECTION
P.O. BOX 556
SOUTH SEAVILLE, NJ 08246

1278

Account Code	Amount
11-000-261-420-050-0	351.95

Date: **08/10/20**

Dept:

Notice: The purchaser is exempt by statute from paying all Federal, State
and Municipal Excise Sales & other taxes.

Qty	Unit	Description	Unit Price	Amount
		Invoice 42429		
5.		CS5ABC - Certrification of 5lb ABC fire extinguishers	5.900	29.50
8.		CS10ABC - Certification of 10lb ABC fire extinguishers	5.900	47.20
1.		CS20ABC- Check and Service 20lb ABC fire extinguisher	5.900	5.90
1.		CS5FE36 - Certification of 5lb FE-36 fire extinguisher	5.900	5.90
1.		CS6LITER - Certification of 6 Liter Wet Chemical	5.900	5.90
1.		FE436500 - AA10S-1 NEW ANSUL 10lb ABC fire extinguisher	84.000	84.00
1.		ABC10 - 10lb ABC Recharge and certification	28.900	28.90
1.		HT10 - Hydro test 10lb	16.650	16.65
4.		ABC5 - 5lb ABC Recharge and Certification	26.000	104.00
2.		STEM - New Valve Stem	12.000	24.00
1.0		Report - System Report		

Total for Lines **\$351.95**

NOTICE TO VENDOR OR CONTRACTOR

1. Order invalid unless signed by the Secretary of the Board of Education
2. Shipping statement must accompany delivery of materials
3. Voucher provided by the Board of Education must be forwarded to the secretary to process payment
4. Please submit invoice as soon as order is completed
5. Must have NJ Reg. on file with us in order to receive payment

SCHOOL OFFICE USE ONLY

I certify that the goods or services itemized have been received

Signature

Title

Date

NO ORDER VALID UNLESS SIGNED BY THE SECRETARY

SECRETARY, BOARD OF EDUCATION

RECEIVING COPY