

New Jersey Police Crash Investigation Report NJTR-1 (Rev. 01/22)

E	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death	

144. Crash Diagram

145. Crash Description/Narrative

D1 statement: Upon speaking to D1, she explained she was driving south on route 27 and began to feel sleepy. While following V2 she fell asleep at the wheel, and she crashed into the rear of V2. This crash caused moderate damage to the rear of V2, but the vehicle was operable and was driven off scene by the owner.

D2 statement: D2 explained she was driving south on route 27 when she noticed V1 was speeding up behind her and closing the distance. She then continued to speed up to avoid the collision but eventually was forced to slow down by traffic congestion. At this time, V1 crashed into the rear of V2. This caused minimal damage to the front bumper of V1. D2 explained she is physically handicapped and has to operate her accelerator and brake pedals with two poles due to her lower extremity handicap.

No parties reported injured at this time.

Conclusion: Due to D1 statement's, it was concluded that D1 caused the crash by falling asleep at the wheel and crashing into the rear of V2. (Driver Inattention).

Other Descriptions

01 - falling asleep - Field 118a

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Parra, Julio	270	Ellington, Ryan	174	☒ Pending ☐ Complete

**New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram**

Police Dept: Franklin Township Police Department/Somerset Co. Code: 01

Station: 5 Case No: 23051114

144. Crash Diagram (NOT TO SCALE)

