


New Jersey Police Crash Investigation Report NJTR-1 (Rev. 01/22)

E	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death

144. Crash Diagram



145. Crash Description/Narrative

Vehicle 1 - Black Toyota Highlander, Going Straight
Vehicle 2- Black Nissan Altima, Changing Lanes

D1 stated he was traveling down Easton Avenue when he put his right turn signal to merge and hit V2.

D2 stated she was traveling down Easton Avenue when she put her right turn signal to merge into the next lane. She further advised while she was in the right lane V1 merged quickly causing V1 to hit V2.

Investigation revealed that D1/V1 was attempting to change lanes, when traffic was not clear to do so, resulting in the crash.

Other Descriptions

01 - Driver not paying attention - Field 118b

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Salas, Zairy	283	Raics, James	177	☐ Pending ☒ Complete

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Franklin Township Police Department/Somerset Co. Code: 01

Station: _____ Case No: 23052771

144. Crash Diagram (NOT TO SCALE)

