


New Jersey Police Crash Investigation Report NJTR-1 (Rev. 01/22)

E	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death

144. Crash Diagram



145. Crash Description/Narrative

DRIVER OF V1 CLAIMED TO BE TRYING TO PARK WHEN HE ENDED UP GOING OVER THE CONCRETE PLANTER. HE APPLIED HIS BRAKES IN AN ATTEMPT TO STOP, BUT REPORTEDLY THEY WERE NOT FUNCTIONING CORRECTLY. AS A RESULT, HE COLLIDED WITH PARKED V2.

THE OWNER OF V2 STATED THAT HE WAS INSIDE THE STORE SHOPPING AT THE TIME WHEN HE HEARD A LOUD BLAST. HE PROMPTLY LEFT THE STORE AND NOTICED THAT HIS VEHICLE HAD BEEN STRUCK BY V1.

INVESTIGATION REVEALED DRIVER OF V1 CAUSED THE CRASH DUE TO DRIVER INATTENTION.

Other Descriptions

01 - FAILURE TO OBSERVE THE CONCRETE PLANTER - Field 118a

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Gonzalez, Emily	274	Ellington, Ryan	174	☒ Pending ☐ Complete

**New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram**


Police Dept: Franklin Township Police Department/Somerset Co. Code: 01

Station: FTPD Case No: 23054561

144. Crash Diagram (NOT TO SCALE)

3151 RT 27 (BOTTLE
REPUBLIC)

CONCRETE
PLANTER



Not To Scale



PARKING LOT