


New Jersey Police Crash Investigation Report NJTR-1 (Rev. 01/22)

E	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death

144. Crash Diagram



145. Crash Description/Narrative

V1 was traveling on Amwell Rd.

V2 was also traveling on Amwell Rd.

D1 stated that while trying to merge into the left lane to make a left onto South Middlebush Rd. D2 sped up and rear ended her.

D2 stated that when cars began to travel straight D1 merged into her lane, crossing the solid white lane marking causing V2 to strike V1.

The On-scene crash investigation resulted in D2 being responsible for the crash. This result was due to D2 initiating an improper lane change by crossing over the solid white lane marking.

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Scott, Justin	277	Ellington, Ryan	174	☒ Pending ☐ Complete

**New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram**

Police Dept: Franklin Township Police Department/Somerset Co. Code: 01

Station: FTPD Case No: 23054726

144. Crash Diagram (NOT TO SCALE)

