


New Jersey Police Crash Investigation Report NJTR-1 (Rev. 01/22)

E	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death

144. Crash Diagram



145. Crash Description/Narrative

V1 crossed centerline and struck oncoming V2.

D1 advised he was traveling North bound on S Middlebush Rd. when his vehicle began abruptly pulling to the left. D1 advised he could not maintain his lane and struck V2.

D2 advised he was traveling South bound on S Middlebush Rd. when V1 crossed the centerline and struck his vehicle.

Investigation revealed the crash was due to a V1 tire blowout.

Other Descriptions

01 - D1 advised front left tire suffered a blowout. - Field 118a

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Meyer, Robert	236	Raics, James	177	☐ Pending ☒ Complete

**New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram**

Police Dept: Franklin Township Police Department/Somerset Co. Code: 01

Station: FTPD Case No: 23055268

144. Crash Diagram (NOT TO SCALE)

